

Periodic Review Report

110 Luther Avenue BCP Site(BCP Site #C734118)March 17, 2019 to March 17, 2020Reporting Period

Syracuse Label Company Inc.





Executive Summary

The 110 Luther Avenue Brownfield Cleanup Program (BCP) Site (BCP Site #C734118) consists of approximately 1.40 acres of land located at 110 Luther Avenue, Town of Salina, Onondaga County, NY. The Site owner is Box Capital, LLC (Box Capital) and the Site Remedial Party is Syracuse Label Company, Inc. (Syracuse Label). The Site groundwater was historically found to be contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE) and its degradation byproducts, trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC). The Site was remediated to commercial use cleanup standards and received a Certificate of Completion (COC) from the New York State Department of Environmental Conservation (NYSDEC) on December 22, 2011. The COC was transferred to Box Capital on April 8, 2019.

The Site is currently in the site management stage in accordance with the Site Management Plan (SMP, S&W Redevelopment of NA, LLC, August 2011, Revised November 2011; Revised February 2017 and May 2019 by GHD Consulting Services Inc.). The SMP requires the maintenance and monitoring of Site institutional controls (ICs) and engineering controls (ECs).

The ICs and ECs for the Site remain in place and effective for protecting human health and the environment. Groundwater monitoring has been completed in accordance with the SMP on a semiannual basis. Based on the groundwater monitoring data, concentrations of target compounds in groundwater have shown a notable decrease over time as a result of the remedial actions and corrective measures performed at the Site. The groundwater analytical data indicates that groundwater standards for the contaminants of concern have been achieved for a majority of the monitoring locations.

The soil cover EC remains in place and continues to effectively mitigate potential exposure to remaining contamination via direct contact with subsurface soils. During this PRR certification period, there were no reported activities at the Site that penetrated the soil cover. The sub-slab depressurization system (SSDS) EC is inspected monthly by Syracuse Label. The system was operating as intended during this PRR's certification period, with the exception of a cracked fitting and dislodged ball valve at suction riser S-14 identified during the March 2020 inspection, which is scheduled to be repaired outside of this PRR's certification period.

The identified ICs include: (1) the designated use of the property for commercial/industrial uses; (2) confirmation that the ownership of the adjacent property located at 116 Luther Avenue remains unchanged from previous uses and ownership; and (3) the prohibition of groundwater use at the Site. Syracuse Label recently sold the Site to Box Capital, who continue to use the Site for commercial purposes and are also leasing a portion of the building to UniFirst for their commercial operations. The ownership of the adjacent property located at 116 Luther Avenue remains unchanged as evidenced by information obtained from the Onondaga County Real Property Tax Services website records. The groundwater use prohibition remains in place and groundwater is not used for any purpose at the Site.



Groundwater monitoring frequency has been reduced to semi-annually (MW-1, MW-7, MW-8, MW-10, and MW-18) with field conditions (i.e., depth to groundwater and field parameters only) recorded at MW-19 on the same semi-annual frequency. Groundwater samples are analyzed for chlorinated VOCs only, in accordance with the NYSDEC-approved revised SMP (GHD Consulting Services Inc., May 2019). The requirements necessary to discontinue Site maintenance and/or monitoring have not been met at this time. There is no need to propose a change to the frequency of PRR submittals at this time.



Table of Contents

| 1. | Introd | luction | | . 1 |
|----|---------|---|---|-------------------|
| | 1.1 | Purpose | | . 1 |
| 2. | Site C | Overview | | . 2 |
| 3. | Institu | itional and | Engineering Controls | . 5 |
| | 3.1 | Institution | al Controls | . 5 |
| | | 3.1.1 3.1.2 3.1.3 3.1.4 3.1.5 | Environmental Easement Groundwater Excavations Site Use Ownership of Adjacent Property. | . 5 . 5 . 5 |
| | 3.2 | Engineeri | ng Controls | . 6 |
| | | 3.2.1 3.2.2 | Sub-Slab Depressurization System Soil Cover Engineering Control | |
| 4. | Opera | ations and | Monitoring | . 8 |
| | 4.1 | Groundwa | ter Monitoring Results | . 8 |
| | 4.2 | Monitoring | Well Decommissioning | 10 |
| 5. | Reco | mmendatio | ns | 11 |

Figure Index

| Figure 1 | Site Location Map |
|----------|---|
| Figure 2 | Site Layout |
| Figure 3 | Groundwater Monitoring Results and Flow Direction |
| Figure 4 | Sub-Slab Depressurization System Layout |
| Figure 5 | Soil Cover Engineering Controls |

Table Index

| Table 1 | Groundwater Elevation Data |
|---------|--|
| Table 2 | Summary of Groundwater Sample Analytical Results |

Appendix Index

| Appendix A | Institutional and Engineering Controls Certification Form |
|------------|--|
| Appendix B | Property Ownership Information for Adjoining Property |
| Appendix C | Sub-Slab Depressurization System Inspection Checklists / Annual Inspection Form and Representative Photographs |
| Appendix D | Groundwater Sampling Waste Disposal Documentation |
| Appendix E | Approval Notifications for EQuIS Database Submittals |
| Appendix F | Time Series Plots |
| Appendix G | Change of Use and/or Ownership Documentation |
| | |



1. Introduction

1.1 Purpose

This Periodic Review Report (PRR) is being submitted on behalf of Syracuse Label Company, Inc. (Syracuse Label), the Remedial Party, for the 110 Luther Avenue Brownfield Cleanup Program (BCP) Site (BCP Site No. C734118) located at 110 Luther Avenue, Town of Salina, Onondaga County, NY (Figure 1). The purpose of the PRR and attached documentation is to document that institutional controls (ICs) and engineering controls (ECs), as described in the New York State Department of Environmental Conservation (NYSDEC)-approved Site Management Plan (SMP) and subsequent revisions, and the Environmental Easement, are in place and functioning as intended in accordance with 6NYCRR Part 375-3. The following elements are included in this report:

- 1. A complete description of all ICs and ECs employed at the Site.
- 2. An evaluation of the plans developed for implementation of the ECs and ICs regarding the continued effectiveness of any ICs and/or ECs required by the decision document for the Site.
- 3. A certification prepared by a professional engineer or qualified environmental professional that the ICs and/or ECs employed at the Site during the period are:
 - Unchanged from the previous certification, unless approved by the Department, consistent with the SMP.
 - In place and effective.
 - Performing as designed, and that there has been no occurrence that would: (1) impair the ability of the controls to protect public health and environment, or (2) constitute a violation or failure to comply with any operation and maintenance plan for such controls.
- 4. The Institutional and Engineering Controls Certification Form as issued by the Department has been completed and included as Appendix A.
- 5. Data tables and figures depicting results of semi-annual groundwater monitoring activities conducted on the Site.



2. Site Overview

The Site is located in the Town of Salina, Onondaga County, NY and is identified as Block 12 and Lots 04.1, 05.0, 06.1, 08.0, and 09.0 on the Onondaga County Tax Map (Tax Map No. 85-12). The Site consists of approximately 1.40 acres of land bound by Albion Avenue to the northwest; Knapp Street to the northeast; Luther Avenue and a parcel operated by Brannock Devices Company, Inc. to the southeast; and an unpaved parking area operated by Bush Electronics to the southwest (see Figure 2).

The Site is currently developed with a two-story building that was historically used for Syracuse Label's office space, light manufacturing, and warehouse operations. The property was transferred from Syracuse Label to Box Capital; and the COC was subsequently transferred on April 8, 2019 (Appendix G). Currently, the property and building is owned by Box Capital, LLC who utilizes a portion of the building for a commercial lighting showroom and warehouse operations and leases a portion of the building to UniFirst for their commercial operations. The portion of the Site not occupied by the building consists of paved parking and delivery areas, with minor grass-covered landscaping areas.

The Remedial Investigation (RI) conducted under Brownfield Cleanup Agreement (BCA) Index #B7-0811-09-08 between December 2009 and November 2010 characterized the nature and extent of contamination at the Site. The results of the RI, as reported in the RI Report (S&W Redevelopment of North America, LLC [SWRNA], January 2011, Revised June 2011) determined that groundwater contamination consisting of chlorinated volatile organic solvents (primarily tetrachloroethene, trichloroethene, and their degradation products) existed in a discrete area in the eastern/central portion of the Site (Figure 3).

A Remedial Action Work Plan (RAWP) was prepared by SWRNA (June 2011, Revised September 2011) which:

- 1. Identified the remedial goals and remedial action objectives
- 2. Discussed the remedy selection
- 3. Summarized remedial action pilot test findings
- 4. Summarized the sub-slab communication testing findings
- 5. Outlined the remedial design for the proposed remedial approach.

The proposed remedial approach was to remediate the Site to a Track 4 Restricted Use by meeting the Commercial Use Soil Cleanup Objectives (SCOs). This approach included implementation of a groundwater remedy and engineering/institutional controls. The groundwater remedy included in-situ chemical reduction (ISCR), which consisted of injection of approximately 11,100 lbs. of a granular carbon and zero valent iron powder mixed into a slurry with potable water and approximately 12 liters of a bacterial consortium (Dehalococcoides). The groundwater remedy was completed in a discrete area of the Site between February 2011 (pilot test) and July 2011 (full scale). The ECs consisted of maintaining the soil cover system and installing a sub-slab depressurization system (SSDS) in the existing on-Site building. The ICs included a Site groundwater use restriction, a Site use restriction limiting the use to commercial or industrial uses, and a requirement to maintain the current SSDS and install a SSDS in any future buildings constructed on Site.



An Environmental Easement (EE) for the Site was filed with the Onondaga County Clerk's Office on October 21, 2011. A Site Management Plan, which outlines Site restrictions and requirements of future maintenance and monitoring, was completed in November 2011, revised in February 2017, and approved by the NYSDEC and New York State Department of Health (NYSDOH). A Certificate of Completion (COC) allowing for commercial or industrial uses of the Site was received from the NYSDEC on December 22, 2011.

Based on a review of guarterly groundwater monitoring results compiled after the issuance of the COC and discussions with the NYSDEC, Syracuse Label implemented corrective measures to address the elevated concentrations of degradation byproducts identified in samples taken from specific Site groundwater monitoring wells. Corrective measure activities were implemented in accordance with the December 2012 Groundwater Monitoring Results and Corrective Measures Injection Work Plan letter report (GHD Consulting Engineers, LLC, April 2013), which was submitted to and approved by the NYSDEC. The corrective measures included ISCR, which consisted of injection of a total of approximately 25,500 lbs. of a granular carbon and zero valent iron powder mixed into a slurry with potable water and a total of approximately 58.5 liters of a concentrated bacterial consortium (Dehalococcoides). The corrective measures were completed in four discrete areas of the Site between December 8, 2012 and February 2, 2014. Groundwater monitoring data collected since implementation of corrective measures indicate that these activities have been effective at further reducing the concentrations of target compounds in Site groundwater, and the ongoing groundwater monitoring further evaluates the effectiveness of the corrective measures. Implementation procedures and findings of the supplemental injections were reported in a separate Construction Completion Report (GHD, March 2015).

The reader of this PRR may refer to previous reports for more detail, as needed. These reports include:

- *Remedial Investigation*, Brownfield Cleanup Program, 110 Luther Avenue Site, 110 Luther Avenue, Liverpool, Onondaga County, New York, BCP Site #C734118, S&W Redevelopment of North America, LLC, January 2011, Revised: June 2011.
- *Remedial Action Work Plan,* Brownfield Cleanup Program, 110 Luther Avenue Brownfield Site, 110 Luther Avenue, Liverpool, Onondaga County, New York, S&W Redevelopment of North America, LLC, June 2011, Revised: September 2011.
- *Site Management Plan,* 110 Luther Avenue Site, Onondaga County, New York, NYSDEC Site Number: C734118, S&W Redevelopment of North America, LLC, August 2011, Revised: November 2011.
- *Final Engineering Report,* 110 Luther Avenue Site, Onondaga County, New York, NYSDEC Site Number: C734118, S&W Redevelopment of North America, LLC, September 2011, Revised: November 2011.
- December 2012 Groundwater Monitoring Results and Corrective Measures Injection Work Plan, 110 Luther Avenue BCP Site, Liverpool, New York, NYSDEC BCP Site #C734118, GHD Consulting Engineers, LLC, April 1, 2013.
- *Periodic Review Report July 1, 2013 March 17, 2014,* 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., May 2014.



- *Construction Completion Report,* 110 Luther Avenue BCP Site (Site #C734118), GHD Consulting Services Inc., March 2015.
- *Periodic Review Report March 17, 2014 March 17, 2015,* 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., April 13, 2015.
- *3rd and 4th Quarter 2015 Off-Site Soil Vapor Sampling Results,* 110 Luther Avenue BCP Site, GHD Consulting Services Inc., February 10, 2016.
- Periodic Review Report March 17, 2015 March 17, 2016, 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., April 13, 2016.
- *Off-Site Soil Vapor Well Sampling*, 110 Luther Avenue BCP Site, GHD Consulting Services Inc., August 23, 2016.
- 3rd Quarter 2016 Groundwater Monitoring Results and Request to Modify the Site Monitoring *Plan,* 110 Luther Avenue BCP Site, GHD Consulting Services Inc., October 12, 2016.
- *3rd* Quarter 2016 Groundwater Monitoring Results and Request to Modify the Site Monitoring Plan Response Letter, NYSDEC, November 30, 2016.
- Site Management Plan, Revised by: GHD Consulting Services Inc., February 2017.
- *Monitoring Well Decommissioning 110 Luther Avenue BCP Site,* GHD Consulting Services Inc., March 7, 2017.
- Periodic Review Report March 17, 2016 March 17, 2017, 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., April 12, 2017.
- Periodic Review Report March 17, 2017 March 17, 2018, 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., March 30, 2018.
- *Request for Site Monitoring Reductions,* 110 Luther Avenue BCP Site, GHD Consulting Services Inc., February 26, 2019.
- Periodic Review Report March 17, 2018 March 17, 2019, 110 Luther Avenue BCP Site (BCP Site #C734118), GHD Consulting Services Inc., April 2019.
- 2019 Monitoring Well Decommissioning, GHD Consulting Services Inc., April 26, 2019.
- Site Management Plan, Revised by: GHD Consulting Services Inc., May 2019.
- Fall 2019 Groundwater Monitoring Results, GHD Consulting Services Inc., January 23, 2020.



3. Institutional and Engineering Controls

Based on identified groundwater contamination, potential soil vapor contamination, and the Site's past and present use, ICs and ECs are utilized at the Site to limit exposure risks. An annual Site inspection was completed on March 17, 2020 (Appendix C) to observe the condition of the ICs and ECs. The ICs and ECS and their status at the time of the Site inspection are described below.

3.1 Institutional Controls

The ICs for this Site are outlined in the NYSDEC-approved SMP (SWRNA, August 2011; Revised November 2011; Revised February 2017 by GHD; Revised May 2019 by GHD), and include the following:

- 1. An EE filed with the Onondaga County Clerk's Office.
- 2. A restriction on the use of groundwater underlying the Site without treatment, rendering it safe for its intended purpose and prior written approval from the NYSDEC and NYSDOH.
- 3. An Excavation Work Plan providing guidance for future excavations conducted on Site.
- 4. A use restriction limiting future Site use to commercial or industrial without prior approval of the NYSDEC.
- 5. Monitoring for ownership changes of the adjacent property, 116 Luther Avenue Tax Identification 085.-12-10.0.

3.1.1 Environmental Easement

The EE was filed with the Onondaga County Clerk's Office and remains unchanged.

3.1.2 Groundwater

Groundwater is not being used at the Site.

3.1.3 Excavations

No excavation of soil has occurred on Site during this certification period.

3.1.4 Site Use

The Site use and ownership has changed since issuance of the COC by the NYSDEC on December 22, 2011. Syracuse Label prepared a 60-Day Advance Notification of Site Change of Use, Transfer of Certificate of Completion, and/or Ownership form and submitted it to the NYSDEC on November 8, 2018. Receipt was acknowledged by NYSDEC on February 13, 2019. Syracuse Label transferred the property to the new owner, Box Capital during April 2019. The COC was transferred to Box Capital on April 8, 2019 (Appendix G).



3.1.5 Ownership of Adjacent Property

Based on information from the Onondaga County Real Property Tax Services website (https://ocfintax.ongov.net/Imate/search.aspx) on March 25, 2020, the adjacent property located to the south of Syracuse Label has been owned by Salvatore A. Leonardi, Jr. since 1995. Based on field observations of the building signage, the property continues to be operated as Brannock Devices Company, Inc. (Appendix B).

3.2 Engineering Controls

The ECs for the Site are outlined in the NYSDEC-approved SMP (SWRNA, August 2011; Revised November 2011; Revised February 2017 by GHD; Revised May 2019 by GHD), and include the following:

3.2.1 Sub-Slab Depressurization System

A SSDS was installed in the existing Site building in July 2011 by Radon Home Services, Inc., a certified radon mitigation contractor. The SSDS is a high vacuum system utilizing 14 suction points positioned at locations throughout the building (Figure 4) and 2 blower fans mounted on the roof of the building. The system is designed to operate continuously to create a negative pressure differential between the sub-slab and the indoor building atmosphere in order to mitigate potential soil vapor intrusion issues. The extracted soil vapor is vented from the blower fan exhaust to the atmosphere.

System inspection forms were completed monthly by Syracuse Label personnel during the certification period, with the exception of the March 2020 inspection, which was performed by GHD on Syracuse Label's behalf (Appendix C). As indicated on the monthly inspection forms, the system was operating as intended during this PRR's certification period, with the exception of two necessary repairs to the SSDS identified during the March 17, 2020 system inspection. The March 17, 2020 inspection indicated that the ball valve in the SSDS piping leading to the southern-most blower fan, Fan 2 was dislodged and the "T" fitting was cracked and needed repair and that the supports for the PVC pipe leading to Fan 1 were in need of repair. On March 20, 2020, outside of this PRR's certification period, Box Capital personnel temporarily fixed the pipe supports leading to Fan 1 and reportedly ordered parts for a more permanent repair, which will occur at a later date. Documentation of the permanent repair will be included in next year's PRR. Box Capital intends to arrange for the repair of the broken "T" fitting and ball valve at S-14, which will occur at a later date; documentation will be included in next year's PRR. No other temporary shutdowns or repairs were reported during this PRR's certification period.

Additional information can be found on the Institutional and Engineering Controls Certification Form (Appendix A) and in the SSDS Inspection Checklists and documentation included in Appendix C.



3.2.2 Soil Cover Engineering Control

Direct contact with soil/fill at the Site is mitigated by a soil cover system in place at the Site. This soil cover system is comprised of existing asphalt pavement, existing concrete building slabs, and grassed areas. The layout of the soil cover system is depicted in Figure 5. Additional information can be found on the Institutional and Engineering Controls Certification Form (Appendix A).

During the Site visit on March 17, 2020, those areas that could be observed (accessible portions of building slab, asphalt pavement, and landscaped areas) appeared to be functioning as intended. However, isolated portions of the landscaped areas adjacent to Albion Avenue asphalt pavement, which is outside the BCP Site boundary, had some rutting apparently due to snow removal activities. These areas were reportedly regraded by Box Capital personnel on March 20, 2020, outside of this PRR's certification period.

There was no reported removal or breach of the soil cover system during this certification period.

Additional information can be found in the Inspection Checklists and documentation included in Appendix C.



4. **Operations and Monitoring**

During this PRR certification period, the NYSDEC-approved SMP (SWRNA, August 2011, Revised November 2011; Revised February 2017 by GHD; Revised May 2019 by GHD) required semi-annual groundwater monitoring of five groundwater monitoring wells (MW-1, MW-7, MW-8, MW-10, and MW-18) and reporting to demonstrate groundwater remedy effectiveness and the overall reduction in contamination on Site. In addition, semi-annual groundwater field conditions monitoring was required for one groundwater monitoring well (MW-19) to determine groundwater elevations. These monitoring events occurred on March 8, 2019 and November 25, 2019.

The spring 2019 monitoring event, which occurred on March 8, 2019, was completed earlier than usual, causing it to fall within the previous PRR's certification period. The March 8, 2019 monitoring event also included collecting samples for laboratory analysis from all 12 Site monitoring wells to support a request to decommission several Site monitoring wells if groundwater conditions remained favorable. Results of the spring 2019 monitoring event are briefly discussed again in this PRR.

Groundwater monitoring well purge water collected during monitoring events is containerized and staged on Site. The containerized water is characterized by Syracuse Label and disposed of off Site once containers are full. During this PRR certification period, purge water from previous monitoring events, contained in two 55-gallon drums, was disposed of off Site, on two separate occasions, at the American Recyclers Company facility in Tonawanda, NY. Disposal documentation is included in Appendix D.

The groundwater monitoring events were completed in accordance with the SMP (Figure 2 and Tables 1 and 2). The laboratory sample results obtained during this PRR certification period were transmitted to the NYSDEC and NYSDOH on:

- March 22, 2019 (spring 2019 sampling)
- January 23, 2020 (fall 2019 sampling)

Groundwater sampling results for each quarterly sampling event were also uploaded into the NYSDEC EQuIS Database, approved by the EQuIS Team, and are ready for use (Appendix E).

4.1 Groundwater Monitoring Results

Based on the data, concentrations of target compounds in groundwater have shown decreases over time as a result of the remedial action and corrective measures. The most current groundwater sample analytical results (November 2020 sampling event) indicate non-detect (ND) concentrations for PCE and TCE (Table 2 and Appendix F) for all groundwater samples. The majority of the wells also have ND concentrations of degradation byproducts DCE and VC, with the exception of the most recent round of samples taken from MW-1, MW-8, MW-10 (DCE only and below groundwater standards), and MW-18, which identified concentrations of these degradation byproducts above groundwater standards, as shown in the following summary tables.



| MW-1 | | |
|------------------|--|---------------------------------------|
| Target Compounds | Baseline Concentrations (February 2010) | Current Concentration (November 2019) |
| PCE | 60 µg/L | ND |
| TCE | 39 µg/L | ND |
| cis-DCE | 150 μg/L | 430 µg/L |
| trans-DCE | 0.91 µg/L | ND |
| VC | 33 µg/L | 550 μg/L |

| MW-7 | | |
|------------------|--|---------------------------------------|
| Target Compounds | Baseline Concentrations (February 2010) | Current Concentration (November 2019) |
| PCE | 27,000 μg/L | ND |
| TCE | 4,300 µg/L | ND |
| cis-DCE | 2,600 µg/L | ND |
| trans-DCE | ND | ND |
| VC | 260 µg/L | ND |

| MW-8 | | | | | | | |
|------------------|--|---------------------------------------|--|--|--|--|--|
| Target Compounds | Baseline Concentrations (February 2010) | Current Concentration (November 2019) | | | | | |
| PCE | 3,900 μg/L | ND | | | | | |
| TCE | 860 µg/L | ND | | | | | |
| cis-DCE | 2,500 μg/L | 21 µg/L | | | | | |
| trans-DCE | ND | ND | | | | | |
| VC | 250 μg/L | 28 μg/L | | | | | |

| MW-10 | | |
|------------------|--|---------------------------------------|
| Target Compounds | Baseline Concentrations (September 2011) | Current Concentration (November 2019) |
| PCE | ND | ND |
| TCE | ND | ND |
| cis-DCE | 93 µg/L | 1.8 μg/L |
| trans-DCE | ND | ND |
| VC | 13 µg/L | ND |



| MW-18 | | | | | | | |
|------------------|---|---------------------------------------|--|--|--|--|--|
| Target Compounds | Baseline Concentrations (October 2010) | Current Concentration (November 2019) | | | | | |
| PCE | ND | ND | | | | | |
| TCE | ND | ND | | | | | |
| cis-DCE | ND | 1,700 μg/L | | | | | |
| trans-DCE | ND | ND | | | | | |
| VC | 2.7 µg/L | 280 μg/L | | | | | |

Groundwater samples taken from the additional Site monitoring wells sampled in March 2019 (MW-6, MW-9, MW-11, MW-12, MW-13, MW-17, and MW-19) identified ND concentrations of PCE, TCE, cis-DCE, trans-DCE, and VC, consistent with previous analytical results.

Concentrations of cis-DCE and VC showed a sharp increase in most wells sampled following implementation of the pre-COC groundwater remedy (Table 2). The increases observed were expected as a result of the sequential degradation resulting from groundwater remediation efforts, which degraded PCE and TCE to cis-DCE and VC. The concentrations of cis-DCE and VC have generally shown a decreasing trend following implementation of the corrective measures as these compounds undergo further degradation (Table 2 and Appendix F). Laboratory analytical results of samples taken during November 2019 indicate that only samples taken from MW-1, MW-8 and MW-18 have concentrations of the degradation products cis-DCE and VC above groundwater standards. Concentrations of cis-DCE and VC in samples taken from MW-1 and MW-18 continue to identify increases since ISCR injections occurred; however, the concentrations of PCE and TCE in samples taken from these wells continue to generally be ND, with the exception of sporadic detections at relatively low concentrations in samples taken from MW-1. Trends in laboratory analytical results of samples taken from these two groundwater monitoring wells will continue to be evaluated for decreasing trends of degradation products cis-DCE and VC.

Based on the groundwater data received to date, the qualitative exposure assessment assumptions regarding on- and off-Site contamination have not changed and are still valid.

4.2 Monitoring Well Decommissioning

Based on the ongoing favorable groundwater sample laboratory analytical results following the March 8, 2019 monitoring event, coupled with the transfer of the property to a new owner during April 2019, Syracuse Label requested that NYSDEC allow for the decommissioning of six on-Site groundwater monitoring wells (MW-6, MW-9, MW-11, MW-12, MW-13, and MW-17). NYSDEC approved the decommissioning to be completed in accordance with NYSDEC CP-43 – Groundwater Monitoring Well Decommissioning Policy (NYSDEC, August 2009). The decommissioning occurred on March 29, 2019 and a monitoring well decommissioning report documenting these activities was prepared and submitted to NYSDEC on April 26, 2019. In addition, the SMP for the Site was revised and submitted to NYSDEC in May 2019 and subsequently approved by NYSDEC on May 20, 2019.

Currently, six groundwater monitoring wells remain at the Site, MW-1, MW-7, MW-8, and MW-10 on-Site between the building and Luther Avenue and MW-18 and MW-19 off-site across Luther Avenue.



5. **Recommendations**


Based on a review of the groundwater data, it is recommended the current ICs and ECs for the Site remain in place to ensure the continued effectiveness and protectiveness of the remedy. Groundwater monitoring should continue semi-annually at five of the six remaining Site wells (MW-1, MW-7, MW-8, MW-10, and MW-18). The sixth remaining Site well, MW-19, should continue to be monitored for field conditions (i.e., water levels and field parameters) at the same semi-annual frequency. The effectiveness of the remedy should continue to be evaluated based on the groundwater monitoring results. The groundwater monitoring program can be reviewed and modified as appropriate in the future, with the approval of the NYSDEC and NYSDOH.

The necessary repairs to SSDS suction riser S-14 and the permanent repairs to the supports for the PVC pipe leading to Fan 1 should be arranged and completed.


Monthly Site inspections should be continued to assess the proper functioning of the SSDS and that the soil cover ECs are in place and functioning as intended. The ICs should continue to be evaluated in accordance with the revised SMP, at a minimum, at the end of the next PRR certification period in March 2021.

Figures





Map Taken From: USGS 7.5 Minute Series Topographic Quadrangle; Syracuse West, NY (2019) (U.S. Geological Survey)



SCALE 1"=2000' AT ORIGINAL SIZE

Syracuse Label Company, Inc. Periodic Review Report for BCP Site #C734118 March 17, 2019 to March 17, 2020 Site Location Map

Job Number | 86-14941 Revision A Date 03.10.2020 Figure 1





ΗD

NEW YORK

QUADRANGLE LOCATION

Cad File No: G:\86\14941\PRRs lot Date: 10 March 2020 - 11:37 AM 19 to March 17, 2020\Figures\Figure 1.dwg










72'

SCALE 1"=36' AT ORIGINAL SIZE











Syracuse Label Company, Inc. Periodic Review Report for BCP Site #C734118 March 17, 2019 to March 17, 2020 Groundwater Monitoring Results and Flow Direction



2010.

One Remington Park Drive, Cazenovia NY 13035 USA T 1 315 679 5800 F 1 315 679 5801 E cazmail@ghd.com W www.ghd.com

Job Number | 86-14941 Revision A Date 03.10.2020 Figure 3








Job Number | 86-14941 Syracuse Label Company, Inc. Periodic Review Report for BCP Site #C734118 Revision A March 17, 2019 to March 17, 2020 Date 03.10.2020 Sub-Slab Depressurization Figure 4 System Layout

72'

SCALE 1"=36' AT ORIGINAL SIZE

One Remington Park Drive, Cazenovia NY 13035 USA T 1 315 679 5800 F 1 315 679 5801 E cazmail@ghd.com W www.ghd.com





NOTES: 1. SITE FEATURES BASED ON SITE SURVEY BY IANUZI & ROMANS, P.C. MARCH 2010 AND NOVEMBER



Job Number | 86-14941 Syracuse Label Company, Inc. Periodic Review Report for BCP Site #C734118 Revision A March 17, 2019 to March 17, 2020 Date 03.10.2020 Soil Cover Engineering Controls Figure 5

2010.

One Remington Park Drive, Cazenovia NY 13035 USA T 1 315 679 5800 F 1 315 679 5801 E cazmail@ghd.com W www.ghd.com

Tables

GHD | Periodic Review Report – March 17, 2019 to March 17, 2020 | 8614941 (203)



| Monitoring Well I.D. | Date | Reference Point | Reference Elevation (feet) | DTW (feet) | DOW (feet) | Water Elevation (feet) | Volume (gal) |
|-------------------------|-------------------------|--------------------|----------------------------------|---------------|----------------|------------------------------|-----------------|
| | 0/00/0014 | | (leet) | 0.40 | 11 11 | | 0.00 |
| | 9/22/2011 3/29/2012 | | | 2.10 2.32 | 11.11 11.11 | 95.65 95.43 | 0.36 0.35 |
| | 12/20/2012 | | | 2.32 | 11.11 | 95.43 95.34 | 0.35 |
| | 3/28/2012 | | | 2.41 | 11.11 | 95.34 95.30 | 0.35 |
| | 12/18/2013 | | | 2.45 | 11.11 | 95.20 | 0.34 |
| | 6/18/2014 | | | 2.33 | 11.20 | 95.44 | 0.34 |
| | 6/24/2015 | | | 2.01 | 11.20 | 95.74 | 0.30 |
| | 9/28/2015 | | | 2.35 | 11.20 | 95.40 | 0.35 |
| MW-1 | 7/6/2016 | Top of PVC | 97.75 | 2.65 | 11.25 | 95.10 | 0.34 |
| | 9/22/2016 | | | 1.66 | 11.25 | 96.09 | 0.34 |
| | 5/31/2017 | | | 1.64 | 11.48 | 96.11 | 0.39 |
| | 11/29/2017 | | | 1.55 | 11.40 | 96.20 | 0.39 |
| | 5/31/2018 | | | 1.75 | 11.45 | 96.00 | 0.40 |
| | 12/18/2018 | | | 1.70 | 11.43 | 96.00 96.05 | 0.39 |
| | 3/8/2019 | | | 1.62 | 11.48 | 96.03 96.13 | 0.39 |
| | 11/25/2019 | | | 2.66 | 11.40 | 90.13 95.09 | 0.39 |
| u | 12/19/2012 | | | 2.00 NM | NM | 95.09 NM | 0.35 NM |
| | 6/24/2015 | | | 2.11 | 16.25 | 95.38 | 2.26 |
| | 12/29/2015 | | 97.49 | 2.08 | 16.25 | 95.38 95.41 | 2.20 |
| MW-6 | | Top of PVC | | 2.08 NM | NM | 95.4 I NM | NM |
| 141 44 -0 | 5/31/2018 12/18/2018 | | | | 16.25 | | |
| | 3/8/2019 | | | 1.54 1.73 | 10.25 | 95.95 95.76 | 2.35 2.51 |
| | 3/29/2019 | | | 1.75 | 1 | mmissioned | |
| u | 6/23/2019 | | | 2.73 | 15.80 | 94.55 | 2.09 |
| | 8/30/2011 | | | 2.73 | 15.80 | 94.55 94.97 | 2.09 |
| | 9/22/2011 9/22/2011 | | | 3.35 | 15.71 | | 2.14 1.98 |
| | 3/29/2012 | | | 3.35 | 15.71 | 93.93 94.24 | 2.04 |
| | 6/28/2012 | | | 3.04 2.95 | 15.79 | 94.24 94.33 | 2.04 |
| | 9/13/2012 | | | 2.95 4.89 | 15.79 | 94.33 92.39 | 2.05 |
| | | | | | | | |
| | 12/21/2012 | | | 2.92 | 15.79 | 94.36 | 2.06 2.07 |
| | 3/28/2013 | | | 3.35 | 16.29 | 93.93 | 2.07 |
| | 6/27/2013 | | | 2.17 | 15.36 | 95.11 90.17 | 1.32 |
| | 9/26/2013 | | | 7.11 | 15.36 | | |
| | 12/18/2013 | | | 8.00 | 15.36 | 89.28 | 1.18 |
| | 3/26/2014 | | | 2.83 | 15.36 | 94.45 | 2.00 |
| | 6/18/2014 | | | 7.81 | 15.36 | 89.47 | 1.21 |
| NAVA / 7 | 9/29/2014 | | | 5.85 | 16.45 | 91.43 | 1.70 |
| MW-7 | 12/29/2014 | Top of PVC | 97.28 | 4.37 | 16.40 | 92.91 | 1.92 |
| | 3/30/2015 | | | 1.85 | 16.45 | 95.43 | 2.34 |
| | 6/24/2015 | | | 2.51 | 16.39 | 94.77 | 2.22 |
| | 9/28/2015 | | | 7.77 | 16.49 | 89.51 | 1.40 |
| | 12/28/2015 | | | 2.98 | 16.40 | 94.30 | 2.15 |
| | 3/30/2016 | | | 2.45 | 16.40 | 94.83 | 2.23 |
| | 7/6/2016 | | | 4.25 | 16.40 | 93.03 | 1.94 |
| | 9/22/2016 | | | 3.77 | 16.40 | 93.51 | 2.02 |
| | 12/20/2016 | | | 3.73 | 16.47 | 93.55 | 2.04 |
| | 5/31/2017 | | | 2.12 | 16.72 | 95.16 | 2.34 |
| | 11/29/2017 | | | 2.69 | 16.68 | 94.59 | 2.24 |
| | 5/31/2018 | | | 2.09 | 16.69 | 95.19 | 2.34 |
| | 12/18/2018 | | | 2.26 | 16.65 | 95.02 | 2.30 |
| | 3/8/2019 | | | 2.00 | 16.69 | 95.28 | 2.35 |
| | 11/25/2019 | | | 2.42 | 16.59 | 94.86 | 2.27 |



| Monitoring Well I.D. | Date | Reference Point | Reference Elevation (feet) | DTW (feet) | DOW (feet) | Water Elevation (feet) | Volume (gal) |
|-------------------------|------------|--------------------|----------------------------------|---------------|---------------|------------------------------|-----------------|
| | 6/23/2011 | | | 2.50 | 17.05 | 94.88 | 2.33 |
| | 8/30/2011 | | | 2.50 | 17.05 | 94.88 | 2.33 |
| | 9/22/2011 | | | 2.46 | 17.05 | 94.92 | 2.33 |
| | 3/30/2012 | | | 2.51 | 17.06 | 94.87 | 2.33 |
| | 6/28/2012 | | | 2.76 | 17.06 | 94.62 | 2.29 |
| | 9/13/2012 | | | 2.90 | 17.06 | 94.48 | 2.27 |
| | 12/21/2012 | | | 2.41 | 17.06 | 94.97 | 2.34 |
| | 3/28/2013 | | | 2.37 | 17.26 | 95.01 | 2.38 |
| | 6/27/2013 | | | 2.42 | 16.55 | 94.96 | 2.26 |
| | 9/26/2013 | | | 2.95 | 16.55 | 94.43 | 2.18 |
| | 12/18/2013 | | | 2.95 | 16.55 | 94.43 | 2.18 |
| | 3/26/2014 | | | 2.86 | 16.55 | 94.52 | 2.19 |
| | 6/18/2014 | | | 2.61 | 16.55 | 94.77 | 2.23 |
| | 9/29/2014 | | | 2.86 | 16.50 | 94.52 | 2.18 |
| MW-8 | 12/29/2014 | Top of PVC | 97.38 | 2.59 | 16.27 | 94.79 | 2.19 |
| | 3/30/2015 | | 01100 | 2.35 | 16.51 | 95.03 | 2.27 |
| | 6/24/2015 | | | 2.78 | 16.50 | 94.60 | 2.20 |
| | 9/29/2015 | | | 3.42 | 16.49 | 93.96 | 2.09 |
| | 12/29/2015 | | | NM | NM | NM | NM |
| | 3/30/2016 | | | 2.14 | 16.70 | 95.24 | 2.33 |
| | 7/6/2016 | | | 3.62 | 16.70 | 93.24 93.76 | 2.33 |
| | 9/22/2016 | | | | 16.75 | 93.76 91.34 | 2.10 |
| | 12/20/2016 | | | 6.04 | | 91.34 95.13 | |
| | | | | 2.25 | 16.81 | 95.13 95.04 | 2.33 2.35 |
| | 5/31/2017 | | | 2.34 | 17.00 | | |
| | 11/29/2017 | | | 3.25 | 17.02 | 94.13 | 2.20 |
| | 5/31/2018 | | | 2.20 | 17.00 | 95.18 | 2.37 |
| | 12/18/2018 | | | 2.26 | 17.00 | 95.12 | 2.36 |
| | 3/8/2019 | | | 2.11 | 17.04 | 95.27 | 2.39 |
| | 11/25/2019 | | | 2.39 | 16.95 | 94.99 | 2.33 |
| | 12/19/2012 | | | NM | NM | NM | NM |
| | 6/24/2015 | | | 2.11 | 14.96 | 95.03 | 2.06 |
| MW-9 | 5/31/2018 | Top of PVC | 97.14 | 2.20 | 14.96 | 94.94 | 2.04 |
| | 12/18/2018 | | | 2.12 | 14.96 | 95.02 | 2.05 |
| | 3/8/2019 | | | 1.73 | 16.15 | 95.41 | 2.31 |
| | 3/29/2019 | | | | | mmissioned | |
| | 9/22/2011 | | | 2.60 | 11.82 | 94.74 | 1.48 |
| | 3/29/2012 | | | 2.64 | 11.82 | 94.70 | 1.47 |
| | 12/21/2012 | | | 2.63 | 11.82 | 94.71 | 1.47 |
| | 3/28/2013 | | | 2.49 | 11.82 | 94.85 | 1.49 |
| | 12/18/2013 | | | 2.62 | 12.95 | 94.72 | 1.65 |
| | 6/18/2014 | | | 2.42 | 13.11 | 94.92 | 1.71 |
| MW-10 | 6/24/2015 | Top of PVC | 97.34 | 2.28 | 13.25 | 95.06 | 1.76 |
| | 7/6/2016 | | | 2.85 | 13.55 | 94.49 | 1.71 |
| | 11/29/2017 | | | 2.44 | 14.00 | 94.90 | 1.85 |
| | 5/31/2018 | | | 2.28 | 14.00 | 95.06 | 1.88 |
| | 12/18/2018 | | | NM | NM | NM | NM |
| | 3/8/2019 | | | 2.13 | 14.21 | 95.21 | 1.93 |
| | 11/25/2019 | | | 2.31 | 14.09 | 95.03 | 1.88 |

Table 1Groundwater Elevations



| Monitoring Well I.D. | Date | Reference Point | Reference Elevation (feet) | DTW (feet) | DOW (feet) | Water Elevation (feet) | Volume (gal) |
|-------------------------|------------|--------------------|----------------------------------|---------------|---------------|------------------------------|-----------------|
| | 6/23/2011 | | () | 2.51 | 14.30 | 95.38 | 0.47 |
| | 8/29/2011 | | | 2.48 | 14.34 | 95.41 | 0.47 |
| | 9/22/2011 | | | 4.22 | 14.34 | 93.67 | 0.40 |
| | 3/29/2012 | | | 2.43 | 14.35 | 95.46 | 0.48 |
| | 6/28/2012 | | | 2.81 | 14.35 | 95.08 | 0.46 |
| | 9/13/2012 | | | 3.28 | 14.35 | 94.61 | 0.44 |
| | 12/19/2012 | | | 2.67 | 14.35 | 95.22 | 0.47 |
| | 3/28/2013 | | | 2.23 | 14.35 | 95.66 | 0.48 |
| | 6/27/2013 | | | 1.59 | 13.91 | 96.30 | 0.49 |
| | 9/26/2013 | | | 2.10 | 13.91 | 95.79 | 0.43 |
| | 12/18/2013 | | | 2.10 | 13.91 | 95.43 | 0.46 |
| | 3/26/2013 | | | 2.40 | 13.91 | 95.43 95.48 | 0.46 |
| | | | | | | | |
| | 6/18/2014 | | | 2.39 | 13.91 | 95.50 | 0.46 |
| MW-11 | 9/29/2014 | Top of PVC | 97.89 | 2.72 | 13.91 | 95.17 | 0.45 |
| | 12/29/2014 | | | 2.23 | 13.91 | 95.66 | 0.47 |
| | 3/30/2015 | | | 1.96 | 13.91 | 95.93 | 0.48 |
| | 6/24/2015 | | | 2.01 | 13.91 | 95.88 | 0.48 |
| | 9/28/2015 | | | 2.66 | 13.91 | 95.23 | 0.45 |
| | 12/28/2015 | | | 2.46 | 13.91 | 95.43 | 0.46 |
| | 3/30/2016 | | | 2.05 | 13.91 | 95.84 | 0.47 |
| | 7/6/2016 | | | 2.80 | 13.91 | 95.09 | 0.44 |
| | 9/22/2016 | | | 2.58 | 13.91 | 95.31 | 0.45 |
| | 12/19/2016 | | | 2.31 | 13.91 | 95.58 | 0.46 |
| | 11/29/2017 | | | 2.23 | 13.91 | 95.66 | 0.47 |
| | 5/31/2018 | | | 2.06 | 13.91 | 95.83 | 0.47 |
| | 12/18/2018 | | | 2.05 | 15.34 | 95.84 | 0.53 |
| | 3/8/2019 | | | 1.82 | 15.34 | 96.07 | 0.54 |
| | 3/29/2019 | | | | Well Deco | mmissioned | |
| | 6/23/2011 | | | 2.27 | 15.60 | 95.75 | 0.53 |
| | 8/29/2011 | | | 2.12 | 15.60 | 95.90 | 0.54 |
| | 9/22/2011 | | | 2.32 | 15.60 | 95.70 | 0.53 |
| | 3/29/2012 | | | 2.16 | 15.61 | 95.86 | 0.54 |
| | 6/28/2012 | | | 2.05 | 15.61 | 95.97 | 0.54 |
| | 9/13/2012 | | | 3.08 | 15.61 | 94.94 | 0.50 |
| | 12/19/2012 | | | 2.25 | 15.60 | 95.77 | 0.53 |
| | 3/28/2013 | | | 2.00 | 15.60 | 96.02 | 0.54 |
| | 6/27/2013 | | | 2.02 | 15.60 | 96.00 | 0.54 |
| | 9/26/2013 | | | 2.34 | 15.60 | 95.68 | 0.53 |
| | 12/18/2013 | | | 2.30 | 15.60 | 95.72 | 0.53 |
| | 3/26/2014 | | | 2.35 | 15.60 | 95.67 | 0.53 |
| | 6/18/2014 | | | 1.35 | 15.60 | 96.67 | 0.57 |
| | 9/29/2014 | | | 2.47 | 15.60 | 95.55 | 0.53 |
| MW-12 | 12/29/2014 | Top of PVC | 98.02 | 1.95 | 15.60 | 96.07 | 0.55 |
| | 3/30/2015 | | | 1.68 | 15.60 | 96.34 | 0.56 |
| | 6/24/2015 | | | 1.81 | 15.60 | 96.21 | 0.55 |
| | 9/28/2015 | | | 2.44 | 15.60 | 95.58 | 0.53 |
| | 12/28/2015 | | | 2.17 | 15.60 | 95.85 | 0.54 |
| | 3/30/2016 | | | 1.87 | 15.73 | 96.15 | 0.55 |
| | 7/6/2016 | | | 2.75 | 15.73 | 95.27 | 0.52 |
| | 9/22/2016 | | | 2.75 | 15.73 | 95.27 95.77 | 0.52 |
| | 12/19/2016 | | | 2.25 | 15.73 | 95.93 | 0.54 |
| | 5/31/2017 | | | 2.09 | 16.00 | 95.93 96.42 | 0.55 |
| | | | | | | | |
| | 11/29/2017 | | | 2.08 | 15.98 | 95.94 | 0.56 |
| | 5/31/2018 | | | 1.93 | 15.98 | 96.09 | 0.56 |
| | 12/18/2018 | | | 1.88 | 16.00 | 96.14 | 0.56 |
| | 3/8/2019 | | | 1.81 | 16.00 | 96.21 | 0.57 |
| | 3/29/2019 | 1 | | | | mmissioned | |



Table 1Groundwater Elevations

| Monitoring Well I.D. | Date | Reference Point | Reference Elevation (feet) | DTW (feet) | DOW (feet) | Water Elevation (feet) | Volume (gal) |
|-------------------------|------------------------|--------------------|----------------------------------|---------------|----------------|------------------------------|-----------------|
| | 6/23/2011 | | () | 2.70 | 12.30 | 95.28 | 0.38 |
| | 8/29/2011 | | | 2.62 | 12.36 | 95.36 | 0.39 |
| | 9/22/2011 | | | 4.41 | 12.36 | 93.57 | 0.32 |
| | 3/29/2012 | | | 2.59 | 12.41 | 95.39 | 0.39 |
| | 6/28/2012 | | | 2.93 | 12.41 | 95.05 95.05 | 0.38 |
| | 9/13/2012 | | | 3.36 | 12.41 | 93.03 94.62 | 0.36 |
| | 12/19/2012 | | | 2.85 | 12.41 | 94.02 95.13 | 0.38 |
| | | | | | | 95.13 95.56 | |
| | 3/28/2013 | | | 2.42 | 12.41 | | 0.40 |
| | 6/27/2013 | | | 2.47 | 14.19 | 95.51 | 0.47 |
| | 9/26/2013 | | | 2.32 | 14.19 | 95.66 | 0.47 |
| | 12/18/2013 | | | 2.81 | 14.19 | 95.17 | 0.46 |
| | 3/26/2014 | | | 2.97 | 14.19 | 95.01 | 0.45 |
| | 6/18/2014 | | | 2.66 | 14.19 | 95.32 | 0.46 |
| | 9/29/2014 | | | 2.97 | 14.19 | 95.01 | 0.45 |
| MW-13 | 12/29/2014 | Top of PVC | 97.98 | 2.54 | 14.19 | 95.44 | 0.47 |
| | 3/30/2015 | | | 2.15 | 14.19 | 95.83 | 0.48 |
| | 6/24/2015 | | | 2.42 | 14.19 | 95.56 | 0.47 |
| | 9/28/2015 | | | 2.96 | 14.19 | 95.02 | 0.45 |
| | 12/28/2015 | | | 2.72 | 14.19 | 95.26 | 0.46 |
| | 3/30/2016 | | | 2.32 | 14.19 | 95.66 | 0.47 |
| | 7/6/2016 | | | 3.15 | 14.19 | 94.83 | 0.44 |
| | 9/22/2016 | | | 2.79 | 14.19 | 95.19 | 0.46 |
| | 12/19/2016 | | | 2.60 | 14.19 | 95.38 | 0.46 |
| | 5/31/2017 | | | 2.07 | 14.19 | 95.91 | 0.48 |
| | 11/29/2017 | | | 2.56 | 14.10 | 95.42 | 0.46 |
| | 5/31/2018 | | | 2.40 | 16.04 | 95.58 | 0.55 |
| | 12/18/2018 | | | 2.40 | 16.10 | 95.55 | 0.55 |
| | 3/8/2019 | | | 2.40 | 16.10 | 95.77 | 0.56 |
| | 3/29/2019 | | | 2.21 | | mmissioned | 0.50 |
| | 6/23/2011 | | | 2.05 | 13.00 | 95.84 | 1.75 |
| | | | | 1.95 | | 95.94 95.94 | 1.70 |
| | 8/29/2011 9/22/2011 | | | 1.95 3.72 | 12.60 12.60 | 95.94 94.17 | 1.70 |
| | | | | | | | |
| | 3/29/2012 | | | 1.95 | 12.52 | 95.94 | 1.69 |
| | 6/28/2012 | | | 2.33 | 12.52 | 95.56 | 1.63 |
| | 9/13/2012 | | | 2.86 | 12.52 | 95.03 | 1.55 |
| | 12/19/2012 | | | 2.15 | 12.52 | 95.74 | 1.66 |
| | 3/28/2013 | | | 1.73 | 12.52 | 96.16 | 1.73 |
| | 6/27/2013 | | | 1.56 | 12.52 | 96.33 | 1.75 |
| | 9/26/2013 | | | 1.89 | 12.52 | 96.00 | 1.70 |
| | 12/18/2013 | | | 1.79 | 12.52 | 96.10 | 1.72 |
| | 3/26/2014 | | | 1.71 | 12.52 | 96.18 | 1.73 |
| | 6/18/2014 | | | 1.76 | 12.52 | 96.13 | 1.72 |
| MW-17 | 9/29/2014 | Top of PVC | 97.89 | 2.01 | 12.52 | 95.88 | 1.68 |
| | 12/29/2014 | | | 1.61 | 12.52 | 96.28 | 1.75 |
| | 3/30/2015 | | | 1.31 | 12.52 | 96.58 | 1.79 |
| | 6/24/2015 | | | 1.10 | 12.52 | 96.79 | 1.83 |
| | 9/28/2015 | | | 2.01 | 12.52 | 95.88 | 1.68 |
| | 12/28/2015 | | | 1.87 | 12.52 | 96.02 | 1.70 |
| | 3/30/2016 | | | 1.59 | 12.52 | 96.30 | 1.75 |
| | 7/6/2016 | | | 2.32 | 12.52 | 90.30 95.57 | 1.63 |
| | | | | | | | |
| | 9/22/2016 | | | 1.96 | 12.52 | 95.93 | 1.69 |
| | 12/19/2016 | | | 1.80 | 12.52 | 96.09 | 1.72 |
| | 5/31/2018 | | | 1.65 | 12.52 | 96.24 | 1.74 |
| | 12/18/2018 | | | 1.65 | 12.52 | 96.24 | 1.74 |
| | 3/8/2019 | | | 1.52 | 13.50 | 96.37 | 1.92 |
| | 3/29/2019 | | | | | mmissioned | |



| Monitoring Well I.D. | Date | Reference Point | Reference Elevation (feet) | DTW (feet) | DOW (feet) | Water Elevation (feet) | Volume (gal) |
|-------------------------|------------|--------------------|----------------------------------|---------------|---------------|------------------------------|-----------------|
| | 9/22/2011 | | | 4.19 | 12.61 | 92.67 | 1.35 |
| | 3/29/2012 | | | 2.44 | 12.61 | 94.42 | 1.63 |
| | 12/20/2012 | | | 2.36 | 12.58 | 94.50 | 1.64 |
| | 6/19/2014 | | | 2.57 | 12.64 | 94.29 | 1.61 |
| | 12/29/2014 | | | 2.99 | 12.59 | 93.87 | 1.54 |
| | 6/24/2015 | | | 2.46 | 12.55 | 94.40 | 1.61 |
| | 12/30/2015 | | | 2.25 | 12.58 | 94.61 | 1.65 |
| MW-18 | 7/7/2016 | Top of PVC | 96.86 | 2.78 | 12.60 | 94.08 | 1.57 |
| | 9/22/2016 | | | 2.48 | 12.60 | 94.38 | 1.62 |
| | 5/31/2017 | | | 2.05 | 12.80 | 94.81 | 1.72 |
| | 11/29/2017 | | | 2.42 | 12.80 | 94.44 | 1.66 |
| | 5/31/2018 | | | 2.26 | 12.78 | 94.60 | 1.68 |
| | 12/18/2018 | | | 2.21 | 12.78 | 94.65 | 1.69 |
| | 3/8/2019 | | | 2.20 | 12.79 | 94.66 | 1.69 |
| | 11/25/2019 | | | 2.24 | 12.70 | 94.62 | 1.67 |
| | 9/22/2011 | | | 4.26 | 13.11 | 92.88 | 1.42 |
| | 3/29/2012 | | | 2.52 | 13.11 | 94.62 | 1.69 |
| | 12/20/2012 | | | 2.35 | 13.10 | 94.79 | 1.72 |
| | 6/19/2014 | | | 2.61 | 13.11 | 94.53 | 1.68 |
| | 12/29/2014 | | | 2.17 | 13.09 | 94.97 | 1.75 |
| | 6/24/2015 | | | 2.39 | 13.05 | 94.75 | 1.71 |
| MW-19 | 12/30/2015 | Top of PVC | 97.14 | 2.25 | 13.10 | 94.89 | 1.74 |
| | 7/7/2016 | 100 011 10 | 07.11 | 3.02 | 13.05 | 94.12 | 1.60 |
| | 9/22/2016 | | | 2.65 | 13.05 | 94.49 | 1.66 |
| | 11/29/2017 | | | 2.56 | 13.28 | 94.58 | 1.72 |
| | 5/31/2018 | | | 2.55 | 13.28 | 94.59 | 1.72 |
| | 12/18/2018 | | | 2.35 | 13.27 | 94.79 | 1.75 |
| | 3/8/2019 | | | 2.47 | 13.28 | 94.67 | 1.73 |
| | 11/25/2019 | | | 2.53 | 13.23 | 94.61 | 1.71 |



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|------------------------|--------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| | | μg/L | µg/L | μg/L | μg/L | μg/L |
| | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 2/10/2010 | 60 | 39 | 150 | 0.91J | 33 |
| | 9/11/2011 | 72 | 34 | 110 | <0.76U | 12 |
| | 3/30/2012 | 45 | 19 | 100 | <1U | 29 |
| | 12/20/2012 | 25 | 21 | 78 | <1U | 25 |
| | 6/19/2014 | 0.92J | 1.9 | 59 | <1U | 17 |
| | 6/25/2015 | <1U | 0.59J | 130 | <1U | 42 |
| | 9/29/2015 | 1.3J | 2.4 | 220 | <2U | 94 |
| MW-01 | 7/7/2016 | 1.1J | 7.2 | 2,500 | 3.4 | 1,100 |
| | 9/23/2016 | <0.36U | 1.7 | 410 | 1.3 | 160 |
| | 5/31/2017 | <3.6U | 6.4J | 910 | <9U | 250 |
| | 11/29/2017 | <3.6U | <4.6U | 440 | <9U | 290 |
| | 5/31/2018 | <3.6U | <4.6U | 1,000 | <9U | 580 |
| | 12/18/2018 | <3.6U | <4.6U | 550 | <9U | 380 |
| | 3/8/2019 | 1.7J | 11 | 560 | 2 | 200 |
| | 11/25/2019 | <3.6U | <4.6U | 430 | <9U | 550 |
| | 6/25/2015 | <1U | <1U | <1U | <1U | <1U |
| NUM 05 | 12/29/2015 | <1U | <1U | <1U | <1U | <1U |
| MW-06 | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decomm | issioned | |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series (June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|------------------------|--------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| | | μg/L | μg/L | μg/L | μg/L | μg/L |
| | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 1/1/2008 | 14,000 | 1,700 | 2,600 | <200U | 560 |
| | 2/11/2010 | 27,000 | 4,300 | 2,600 | <150U | 260J |
| | 2/11/2011 | 17,000 | 2,600 | 2,600 | <150U | 620J |
| | 3/11/2011 | 6,900 | 3,600 | 14,000 | <76U | 460J |
| | 4/11/2011 | 370J | 150J | 17,000 | <150U | 690J |
| | 6/11/2011 | 1,600 | 3,300 | 19,000 | <190U | 1,100J |
| | 8/11/2011 | 240J | 520J | 24,000 | <190U | 8,500 |
| | 9/11/2011 | 240J | 380 | 7,400 | <38U | 4,300 |
| | 3/29/2012 | 34 | 170J | 11,000 | 36 | 4,300 |
| | 6/28/2012 | <200U | 140J | 26,000 | <200U | 8,400 |
| | 9/13/2012 | <400U | <400U | 27,000 | <400U | 8,900 |
| | 12/21/2012 | <400U | <400U | 16,000 | <400U | 8,100 |
| | 3/28/2013 | <400U | <400U | 18,000 | <400U | 7,900 |
| | 6/27/2013 | <80U | <80U | 4,300 | <80U | 3,300 |
| | 9/26/2013 | <80U | <80U | 6,300 | <80U | 3,000 |
| | 12/18/2013 | <40U | <40U | 2,300 | <40U | 2,400 |
| MW-07 | 3/26/2014 | <20U | <20U | 1,400 | <20U | 1,500 |
| | 6/18/2014 | <20U | <20U | 510 | <20U | 720 |
| | 9/29/2014 | <4U | <4U | 32 | <4U | 88 |
| | 12/29/2014 | <1.8U | <2.3U | 39 | <4.5U | 31 |
| | 3/30/2015 | <5U | <5U | 22 | <5U | 38 |
| | 6/25/2015 | <5U | <5U | 6.5 | <5U | 24 |
| | 9/28/2015 | <5U | <5U | 21 | <5U | 46 |
| | 12/28/2015 | <5U | <5U | <5U | <5U | 9.9 |
| | 3/30/2016 | <5U | <5U | 4.9J | <5U | 18 |
| | 7/6/2016 | <0.36U | <0.46U | 1.6 | <0.9U | 6.3 |
| | 9/22/2016 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 12/20/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 5/31/2017 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 11/29/2017 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 5/31/2018 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 12/18/2018 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 11/25/2019 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|-------------------------|----------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1, 2-dichloroethene | trans-1, 2-dichlor oethene | Vinyl chloride |
| | | μg/L | μg/L | μg/L | μg/L | μg/L |
| | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 1/2/2008 | 6,200 | 920 | 1,600 | <200U | 290 |
| | 2/1/2010 | 3,900 | 860 | 2,500 | <15U | 250 |
| | 6/11/2011 | 1,500 | 540 | 1,700 | <19U | 200 |
| | 8/11/2011 | 380J | 140J | 5,100 | 100J | 4,000 |
| | 9/11/2011 | 1,100J | 420J | 7,900 | 83J | 2,800 |
| | 3/30/2012 | 82 | 22 | 140 | 1.1 | 66 |
| | 6/28/2012 | 1,000 | 460 | 4,000 | 21 | 1,300 |
| | 9/13/2012 | 9,500 | 1,900 | 8,000 | 34 | 2,100 |
| | 12/21/2012 | 1,800 | 470 | 6,600 | <100U | 2,700 |
| | 3/28/2013 | 800 | 380 | 9,400 | <200U | 4,300 |
| | 6/27/2013 | 17J | <40U | 2,100 | <40U | 2,000 |
| | 9/26/2013 | <40U | <40U | 160 | <40U | 67 |
| | 12/18/2013 | <40U | <40U | <40U | <40U | 110 |
| | 3/26/2014 | <5U | <5U | 330 | <5U | 380 |
| MW-08 | 6/18/2014 | <5U | <5U | 110 | <5U | 67 |
| 10100-08 | 9/29/2014 | <1U | <1U | 0.46J | <1U | <1U |
| | 12/29/2014 | <1.8U | <2.3U | <4.1U | <4.5U | <4.5U |
| | 3/30/2015 | <40U | <40U | 2,100 | <40U | 1,300 |
| | 6/25/2015 | <40U | <40U | 1,500 | <40U | 430 |
| | 9/29/2015 | <10U | <10U | 310 | <10U | 160 |
| | 3/30/2016 | <10U | <10U | 610 | <10U | 310 |
| | 7/6/2016 | <3.6U | <4.6U | 810 | <9U | 460 |
| | 9/22/2016 | <3.6U | <4.6U | 430 | <9U | 760 |
| | 12/20/2016 | <0.72U | <0.92U | 96 | <1.8U | 63 |
| | 5/31/2017 | <3.6U | <4.6U | 490 | <9U | 310 |
| | 11/29/2017 | <0.36U | <0.46U | 1 | <0.9U | <0.9U |
| | 5/31/2018 | <3.6U | <4.6U | 620 | <9U | 740 |
| | 12/18/2018 | <1.4U | <1.8U | 120 | <3.6U | 110 |
| | 3/8/2019 | <0.72U | <0.92U | 5.5 | <1.8U | 12 |
| | 11/25/2019 | <0.36U | <0.46U | 21 | <0.9U | 28 |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively 7. Bold and highlighted result indicates an exceedance of applicable Regulatory Standard



| | | VOCs by EPA Method 8260 | | | | |
|-----------|--------------|-------------------------|-----------------|------------------------|--------------------------|------------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| Regulato | ry Standard | μg/L 5 | μg/L 5 | μg/L 5 | μg/L 5 | μg/L 2 |
| Sample ID | Date Sampled | | | | | |
| | 6/25/2015 | <1U | <1U | <1U | <1U | <1U |
| MW-09 | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decomm | issioned | |
| | 9/11/2011 | <0.81U | <0.62U | 93 | <0.76U | 13 |
| | 3/30/2012 | <1U | <1U | 56 | <1U | 13 |
| | 12/20/2012 | <1U | <1U | 90 | <1U | 13 |
| | 6/19/2014 | <5U | <5U | <5U | <5U | <5U |
| MW-10 | 6/25/2015 | <5U | <5U | <5U | <5U | <5U |
| 10100-10 | 7/7/2016 | <0.36U | <0.46U | <0.81U | <0.9U | 0.98J |
| | 11/29/2017 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 12/18/2018 | - | - | - | - | - |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 11/25/2019 | <0.36U | <0.46U | 1.8 | <0.9U | <0.9U |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series (June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|----------------------------|-------------------|-----------------|------------------------|--------------------------|------------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| Dogulator | · Stondard | μg/L 5 | μg/L 5 | μg/L 5 | μg/L 5 | μg/L 2 |
| Sample ID | y Standard Date Sampled | | 5 | 5 | 5 | 2 |
| Sample ID | | 14,000 | 2,400 | | <1,000U | <1,000U |
| | 3/1/2008 2/11/2010 | 20,000 | 6,100 | 4,400 | <76U | 270J |
| | 2/11/2010 | 42,000 | 6,300 | 3,800 | <380U | <500U |
| | 3/11/2011 | 4,200 | 1,100 | 39,000 | <150U | <200U |
| | 4/11/2011 | 2,200J | <310U | 77,000 | <380U | <500U |
| | 6/11/2011 | <810U | <620U | 58,000 | <760U | <990U |
| | 8/11/2011 | <410U | 390J | 49,000 | <380U | 1,100J |
| | 9/11/2011 | 370J | 480J | 45,000 | <300U | 680J |
| | 3/30/2012 | 58 | 40 | 53,000 | 16 | 2,700 |
| | 6/28/2012 | <40U | <40U | 47,000 | <40U | 3,500 |
| | 9/14/2012 | <800U | <800U | 59,000 | <800U | 4,300 |
| | 12/21/2012 | <800U | <800U | 45,000 | <800U | 4,200 |
| | 3/28/2013 | <800U | <800U | 37,000 | <800U | 4,900 |
| | 6/28/2013 | <100U | <100U | 9,600 | <100U | 560 |
| | 9/27/2013 | <200U | <200U | 20,000 | <200U | 3,200 |
| | 12/19/2013 | <50U | <50U | 3,300 | <500 | 1,800 |
| MW-11 | 3/27/2014 | <40U | <40U | 2,800 | <40U | 3,200 |
| | 6/19/2014 | <20U | <20U | 500 | <20U | 930 |
| | 9/30/2014 | <25U | <25U | 110 | <25U | 250 |
| | 12/30/2014 | <1.4U | <1.8U | 68 | <3.6U | 190 |
| | 3/31/2015 | <4U | <4U | 63 | <4U | 110 |
| | 6/25/2015 | <4U | <4U | <4U | <4U | 5.6 |
| | 9/29/2015 | <4U | <4U | <4U | <4U | 5.4 |
| | 12/29/2015 | <4U | <4U | <4U | <4U | <4U |
| | 3/31/2016 | <4U | <4U | <4U | <4U | <4U |
| | 7/7/2016 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 9/23/2016 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 12/20/2016 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 11/29/2017 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 12/18/2018 | <1.4U | <1.8U | <3.2U | <3.6U | <3.6U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decomm | issioned | |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|-----------------------|-------------------|-----------------|------------------------|--------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| | | μg/L | μg/L | μg/L | μg/L | μg/L |
| | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | 1 200 | 200 | - | (2011 | 12011 |
| | 3/1/2008 | 1,200 220 | 280 79 | - 670 | <20U <3.8U | <20U 18J |
| | 2/1/2010 6/11/2011 | 220 23J | <12U | 1,000 | <15U | 45J |
| | 8/11/2011 | 20J | 16J | 480 | <7.6U | 100 |
| | 9/11/2011 | 17 | 15 | 350 | <1.5U | 66 |
| | 3/30/2012 | 8.1 | 6.9 | 280 | <1U | 95 |
| | 6/28/2012 | 7.4 | 6.8 | 250 | <50 | 57 |
| | 9/14/2012 | 22 | 17 | 310 | <5U | 64 |
| | 12/21/2012 | 13 | 15 | 250 | <5U | 58 |
| | 3/29/2013 | <50 | <5U | 93 | <5U | 4.9J |
| | 6/28/2013 | 33 | 26 | 2,400 | <5U | 63 |
| | 9/27/2013 | <40U | <40U | 1,800 | <40U | 220 |
| | 12/19/2013 | <10U | <10U | 500 | <10U | 130 |
| | 3/27/2014 | <5U | <5U | 54 | <5U | 18 |
| | 6/19/2014 | <5U | <5U | 8.9 | <5U | <5U |
| MW-12 | 9/30/2014 | <1.7U | <1.7U | 2.8 | <1.7U | 1.2J |
| | 12/30/2014 | <0.36U | <0.46U | 1.7 | <0.9U | <0.9U |
| | 3/31/2015 | <1U | <1U | 1 | <1U | <1U |
| | 6/25/2015 | <1U | <1U | <1U | <1U | <1U |
| | 9/29/2015 | <1U | <1U | 0.82J | <1U | <1U |
| | 12/29/2015 | <1U | <1U | 0.88J | <1U | <1U |
| | 3/31/2016 | <1U | <1U | 0.82J | <1U | <1U |
| | 7/7/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 9/23/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 12/20/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 5/31/2017 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 11/29/2017 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 5/31/2018 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 12/18/2018 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decommi | issioned | |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series (June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively





| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|------------------------|--------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichloroethene | Vinyl chloride |
| | | µg/L | µg/L | μg/L | μg/L | μg/L |
| | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 3/1/2008 | 900 | 470 | - | <100U | <100U |
| | 2/1/2010 | 410 | 600 | 780 | 12J | 29 |
| | 6/11/2011 | 1,300 | 1,300 | 12,000 | <150U | 300J |
| | 8/11/2011 | 2,500 | 1,800 | 11,000 | <150U | 220J |
| | 9/11/2011 | 2,800 | 2,000 | 7,800 | <76U | 140J |
| | 3/30/2012 | 1,900 | 1,300 | 8,900 | 14 | 470 |
| | 6/28/2012 | 2,400 | 1,400 | 9,200 | <100U | 290 |
| | 9/14/2012 | 3,300 | 1,900 | 9,700 | <100U | 440 |
| | 12/21/2012 | 5,100 | 2,600 | 8,400 | <100U | 480 |
| | 3/29/2013 | 4,600 | 2,500 | 9,600 | <100U | 500 |
| | 6/28/2013 | 4,100 | 2,300 | 11,000 | <100U | 220 |
| | 9/27/2013 | 4,000 | 2,100 | 11,000 | <200U | 450 |
| | 12/19/2013 | 2,100 | 1,100 | 16,000 | <200U | 370 |
| | 3/27/2014 | 250 | 160J | 35,000 | <200U | 1,100 |
| | 6/19/2014 | <800U | <800U | 37,000 | <800U | <800U |
| MW-13 | 9/30/2014 | <830U | <830U | 12,000 | <830U | 1,500 |
| | 12/30/2014 | <180U | <230U | 24,000 | <450U | 6,300 |
| | 3/31/2015 | <200U | <200U | 8,200 | <200U | 3,100 |
| | 6/25/2015 | <200U | <200U | 9,500 | <200U | 3,400 |
| | 9/29/2015 | <200U | <200U | 7,300 | <200U | 3,700 |
| | 12/29/2015 | <200U | <200U | 5,200 | <200U | 3,600 |
| | 3/31/2016 | <200U | <200U | 4,700 | <200U | 5,300 |
| | 7/7/2016 | <18U | <23U | 1,500 | <45U | 3,200 |
| | 9/23/2016 | <18U | <23U | 330 | <45U | 1,200 |
| | 12/20/2016 | <72U | <92U | 1,100 | <180U | 5,200 |
| | 5/31/2017 | <0.72U | <0.92U | 22 | <1.8U | 200 |
| | 11/29/2017 | <0.72U | <0.92U | 2.6 | <1.8U | 23 |
| | 5/31/2018 | <0.72U | <0.92U | <1.6U | <1.8U | 1.9J |
| | 12/18/2018 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decommi | issioned | |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998).

2. U - Analyzed for but not detected above laboratory detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for 5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|------------------------|-----------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichlor oe the ne | Vinyl chloride |
| | | μg/L | µg/L | μg/L | μg/L | μg/L |
| Regulator | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 2/1/2010 | 14,000 | 2,000 | 750 | <76U | <99U |
| | 2/11/2011 | 8,800 | 1,400 | 1,000 | <76U | <99U |
| | 3/11/2011 | 6,300 | 1,200 | 780 | <30U | <40U |
| | 4/11/2011 | 6,900 | 1,800 | 1,400 | <38U | <50U |
| | 6/11/2011 | 7,600 | 1,000 | 940 | <76U | <99U |
| | 8/11/2011 | <200U | <160U | 21,000 | <190U | 360J |
| | 9/11/2011 | <81U | <62U | 12,000 | <76U | 1,800 |
| | 3/30/2012 | 9.7 | 6.5 | 2,700 | 6.6 | 990 |
| | 6/28/2012 | 3.6 | 7 | 4,300 | <1U | 1,800 |
| | 9/14/2012 | <50U | <50U | 3,500 | <50U | 1,200 |
| | 12/21/2012 | <50U | <50U | 3,800 | <50U | 2,100 |
| | 3/29/2013 | <10U | <10U | 570 | <10U | 410 |
| | 6/28/2013 | <10U | <10U | 560 | <10U | 320 |
| | 9/27/2013 | <10U | <10U | 360 | <10U | 470 |
| MW-17 | 12/19/2013 | <10U | <10U | 2,400 | 14 | 1,200 |
| | 3/27/2014 | <10U | <10U | <10U | <10U | 38 |
| | 6/19/2014 | <1U | <1U | 4.4 | <1U | 32 |
| | 9/30/2014 | <4U | <4U | <4U | <4U | 37 |
| | 12/30/2014 | <0.36U | <0.46U | 1.1 | <0.9U | 20 |
| | 3/31/2015 | <1U | <1U | <1U | <1U | 16 |
| | 6/25/2015 | <1U | <1U | 1.1 | <1U | 9.5 |
| | 9/29/2015 | <1U | <1U | <1U | <1U | 14 |
| | 12/29/2015 | <1U | <1U | <1U | <1U | 1.6 |
| | 3/31/2016 | <1U | <1U | <1U | <1U | <1U |
| | 7/7/2016 | <0.36U | <0.46U | <0.81U | <0.9U | 1.1 |
| | 9/23/2016 | <0.36U | <0.46U | <0.81U | <0.9U | 1.9 |
| | 12/20/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/29/2019 | | Well | Decommi | issioned | |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998).

2. U - Analyzed for but not detected above laboratory

detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for

5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively



| | | | VOCs b | y EPA Me | thod 8260 | |
|-----------|--------------|-------------------|-----------------|------------------------|-----------------------------|----------------|
| | | Tetrachloroethene | Trichloroethene | cis-1,2-dichloroethene | trans-1,2-dichlor oe the ne | Vinyl chloride |
| | | μg/L | μg/L | μg/L | μg/L | μg/L |
| Regulator | y Standard | 5 | 5 | 5 | 5 | 2 |
| Sample ID | Date Sampled | | | | | |
| | 10/2/2010 | <0.81U | <0.62U | <0.99U | <0.76U | 2.7J |
| | 9/11/2011 | <0.81U | <0.62U | 13 | <0.76U | 17 |
| | 3/30/2012 | <1U | <1U | 29 | <1U | 9.2 |
| | 12/20/2012 | <1U | <1U | 5.5 | <1U | <1U |
| | 6/19/2014 | <1U | <1U | 230 | <1U | 30 |
| | 12/29/2014 | <1.8U | <2.3U | 75 | <4.5U | 9 |
| | 6/25/2015 | <5U | <5U | 350 | <5U | 31 |
| NANA 10 | 12/30/2015 | <5U | <5U | 160 | <5U | 15 |
| MW-18 | 7/7/2016 | <1.8U | <2.3U | 460 | <4.5U | 58 |
| | 9/22/2016 | <1.8U | <2.3U | 65 | <4.5U | <4.5U |
| | 5/31/2017 | <1.8U | <2.3U | 610 | <4.5U | 86 |
| | 11/29/2017 | <1.8U | <2.3U | 470 | <4.5U | 92 |
| | 5/31/2018 | <1.8U | <2.3U | 670 | <4.5U | 96 |
| | 12/18/2018 | <1.8U | <2.3U | 940 | <4.5U | 140 |
| | 3/8/2019 | <0.72U | <0.92U | 970 | <1.8U | 130 |
| | 11/25/2019 | <7.2U | <9.2U | 1,700 | <18U | 280 |
| | 10/2/2010 | <0.81U | <0.62U | <0.99U | <0.76U | <0.99U |
| | 9/11/2011 | <0.81U | <0.62U | <0.99U | <0.76U | <0.99U |
| | 3/30/2012 | <1U | <1U | <1U | <1U | <1U |
| | 12/20/2012 | <1U | <1U | <1U | <1U | <1U |
| | 6/19/2014 | <1U | <1U | <1U | <1U | <1U |
| | 12/29/2014 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| MW-19 | 6/25/2015 | <1U | <1U | <1U | <1U | <1U |
| | 12/30/2015 | <1U | <1U | <1U | <1U | <1U |
| | 7/7/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 9/22/2016 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 11/29/2017 | <0.36U | <0.46U | <0.81U | <0.9U | <0.9U |
| | 12/18/2018 | <0.72U | <0.92U | <1.6U | <1.8U | <1.8U |
| | 3/8/2019 | <0.72U | <0.92U | <1.6 | <1.8U | <1.8U |

1. Regulatory Standard - Class GA Groundwater Quality Standard or Guidance Value from New York State Department of Environmental Conservation (NYSDEC) Division of Water Technical and Operational Guidance Series

(June 1998). 2. U - Analyzed for but not detected above laboratory

detection limit indicated 3. J - Indicates an estimated value

4. (-) - Not analyzed for

5. Feb-11, Mar-11, and Apr-11 data represents pilot test baseline, 1st post-pilot test sampling event, and 2nd post-pilot test sampling event, respectively

6. Jun-11, Aug-11, and Sep-11 data represents full scale ISCR injection baseline, 1st post-ISCR sampling event, and 2nd

post-ISCR sampling event, respectively

Appendices

Appendix A Institutional and Engineering Controls Certification Form



Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



| Sit | e No. | C734118 | Site Details | | Box 1 | |
|------------|---|---|----------------------------|---------------------------|----------|------|
| Sit | e Name 11 | 0 Luther Ave. Site | | | | |
| Cit Co | e Address: y/Town: Liv unty:Onond e Acreage: | laga | Zip Code: 13088 | | | |
| Re | porting Perio | od: March 17, 2019 to Ma | arch 17, 2020 | | | |
| | | | | | YES | NO |
| 1. | Is the infor | mation above correct? | | | Х | |
| | If NO, inclu | ude handwritten above or | on a separate sheet. | | | |
| 2. | | or all of the site property nendment during this Rep | | merged, or undergone a | Х | |
| 8. | | been any change of use a CRR 375-1.11(d))? | at the site during this Re | eporting Period | Х | |
| ŀ. | | federal, state, and/or loca e property during this Rep | | discharge) been issued | | Х |
| | | wered YES to questions mentation has been pre- | | | | |
| 5. | Is the site | currently undergoing deve | elopment? | | | Х |
| | | | | | | |
| | | | | | Box 2 | |
| | | | | | YES | NO |
| j. | | ent site use consistent wit al and Industrial | h the use(s) listed belov | N? | Х | |
| 7 . | Are all ICs | /ECs in place and function | ning as designed? | | Х | |
| | IF TI | HE ANSWER TO EITHER DO NOT COMPLETE TH | | · • | and | |
| 4 (| Corrective M | leasures Work Plan must | be submitted along wi | th this form to address t | hese iss | ues. |
| | | | | _ | | |
| Sig | inature of Ov | vner, Remedial Party or De | signated Representative | Date | | |

| | | Box 2 | A |
|------|---|-------|----|
| | | YES | NO |
| 8. | Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid? | | X |
| | If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. | | |
| 9. | Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) | Х | |
| | If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. | | |
| SITI | SITE NO. C734118 | | |
| | Description of Institutional Controls | | |

Parcel 085-12-04.1 Owner Box Capital, LLC Institutional Control

Monitoring Plan

IC/EC Plan Ground Water Use Restriction Site Management Plan Landuse Restriction O&M Plan

A sub-slab depressurization system (SSDS) was installed in the existing Site building in 2011. The SSDS is a high vacuum system utilizing fourteen (14) suction points positioned at location shown on Figure 9. Photographs of the system installation are included in Appendix B of this SMP. The fourteen (14) suction points are identified herein, and will be referenced in the future, as S-1, S-2, S-3, and S-4 (clockwise around warehouse starting in the southwest corner); S-5, S-6, and S-7 (south to north along office area wall); S-8 and S-9 (northeastern rooms of building), and S-10, S-11, S-12, S-13, and S-14 (southeastern rooms of building).

Each SSDS suction point consists of a 4 inch hole cored through the existing concrete slab. Each suction riser was constructed of 3 inch diameter schedule 40 polyvinyl chloride (PVC) piping. Each suction riser was connected to a single fan on the roof utilizing a trunk line network consisting of 4 inch diameter PVC piping. Each riser pipe is outfitted with a magnehelic pressure gauge, to allow for monitoring of system performance, and an interior baffle that can be adjusted to regulate airflow. All floor, wall, and roof penetrations were sealed with a VOC compliant urethane sealant. Design details are presented in the Operation and Maintenance Plan (Section 4 of this SMP).

Procedures for monitoring the system, including inspections in the event that an identified severe condition occurs, are included in the Monitoring Plan (Section 3 of this SMP). Procedures for operating and maintaining the SSDS are documented in the Operation and Maintenance Plan (Section 4 of this SMP).

A series of Institutional Controls is required by the RAWP to: (1) implement, maintain and monitor Engineering Control systems; (2) prevent future exposure to remaining contamination by controlling disturbances of the subsurface contamination; and, (3) limit the use and development of the Site to Commercial or Industrial uses only. Adherence to these Institutional Controls on the Site is required by the Environmental Easement and will be implemented under this Site Management Plan. These Institutional Controls are:

• Compliance with the Environmental Easement and this SMP by the Grantor and the Grantor's successors and assigns;

• All Engineering Controls must be operated and maintained as specified in this SMP;

• All Engineering Controls on the Controlled Property must be inspected at a frequency and in a manner defined in the SMP;

• Groundwater and other environmental or public health monitoring must be performed as defined in this SMP; and

• Data and information pertinent to Site Management of the Controlled Property must be reported at the frequency and in a manner defined in this SMP.

Institutional Controls identified in the Environmental Easement may not be discontinued without an amendment to or extinguishment of the Environmental Easement.

The Site has a series of Institutional Controls in the form of Site restrictions. Adherence to these Institutional Controls is required by the Environmental Easement. Site restrictions that apply to the Controlled Property are:

• The property may only be used for Commercial or Industrial use provided that the long-term Engineering and Institutional Controls included in this SMP are employed;

• The property may not be used for a higher level of use, such as unrestricted, residential, or restricted residential use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;

• All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with this SMP and the Excavation Work Plan (Appendix C);

• The use of the groundwater underlying the property is prohibited without treatment rendering it safe for intended use;

• The potential for vapor intrusion must be evaluated for any buildings developed onsite, and any potential impacts that are identified must be monitored or mitigated;

Vegetable gardens and farming on the property are prohibited;

The Site owner or remedial party will submit to NYSDEC a written statement that certifies, under

penalty of perjury, that: (1) controls employed at the Controlled Property are unchanged from the previous certification or that any changes to the controls were approved by the NYSDEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and environment or that constitute a violation or failure to comply with the SMP. NYSDEC retains the right to access such Controlled Property at any time in order to evaluate the continued maintenance of any and all controls. This certification shall be submitted annually, or an alternate period of time that NYSDEC may allow and will be made by an expert that the NYSDEC finds acceptable; and

• The Site owner is required to monitor whether there is a change in ownership of the adjacent property currently owned by The Brannock Device Company, located at 116 Luther Avenue. If a change in ownership occurs the current owner will need to be notified of the environmental conditions of the 110 Luther Avenue Site and afforded the option to evaluate the potential for soil vapor intrusion into the building. Notification must also be made to the NYSDEC if the adjacent property is sold or ownership is transferred.

2.3.1 Excavation Work Plan

The Site has been remediated for commercial use. Any future intrusive work that will encounter or disturb the remaining contamination, including any modifications or repairs to the existing cover system will be performed in compliance with the Excavation Work Plan (EWP) that is attached as Appendix C to this SMP. Any work conducted pursuant to the EWP must also be conducted in accordance with the procedures defined in a Health and Safety Plan (HASP) and Community Air Monitoring Plan (CAMP) prepared for the Site. A sample HASP and CAMP are attached as Appendix D to this SMP that is in current compliance with DER-10, and 29 CFR 1910, 29 CFR 1926, and all other applicable Federal, State and local regulations. Based on future changes to State and federal health and safety requirements, and specific methods employed by future contractors, the HASP and CAMP will be updated and re-submitted with the notification provided in Section C-1 of the EWP. Any intrusive construction work will be performed in compliance with the EWP, HASP and CAMP, and will be included in the periodic inspection and certification reports submitted under the Site Management Reporting Plan (See Section 5).

The Site owner and associated parties preparing the remedial documents submitted to the State, and parties performing this work, are completely responsible for the safe performance of all intrusive work, the structural integrity of excavations, proper disposal of excavation de-water, control of runoff from open excavations into remaining contamination, and for structures that may be affected by excavations (such as building foundations and bridge footings). The Site owner will ensure that Site development activities will not interfere with, or otherwise impair or compromise, the engineering controls described in this SMP.

2.3.2 Soil Vapor Intrusion Evaluation

Prior to the construction of any enclosed structures at the Site, an SVI evaluation will be performed to determine whether any mitigation measures are necessary to eliminate potential exposure to vapors in the proposed structure. Alternatively, an SVI mitigation system may be installed as an element of the building foundation without first conducting an investigation. This mitigation system will include a vapor barrier and passive sub-slab depressurization system that is capable of being converted to an active system. Prior to conducting an SVI investigation or installing a mitigation system, a work plan will be developed and submitted to the NYSDEC and NYSDOH for approval. This work plan will be developed in accordance with the most recent NYSDOH "Guidance for Evaluating Vapor Intrusion in the State of New York". Measures to be employed to mitigate potential vapor intrusion will be evaluated, selected, designed, installed, and maintained based on the SVI evaluation, the NYSDOH guidance, and construction details of the proposed structure.

Preliminary (unvalidated) SVI sampling data will be forwarded to the NYSDEC and NYSDOH for initial review and interpretation. Upon validation, the final data will be transmitted to the agencies, along with a recommendation for follow-up action, such as mitigation. If any indoor air test results exceed NYSDOH guidelines, relevant NYSDOH fact sheets will be provided to all tenants and occupants of the property within 15 days of receipt of validated data.

SVI sampling results, evaluations, and follow-up actions will also be summarized in the next Periodic Review Report.

085-12-05.0

Box Capital, LLC

Monitoring Plan

IC/EC Plan Landuse Restriction O&M Plan Ground Water Use Restriction

Site Management Plan

A sub-slab depressurization system (SSDS) was installed in the existing Site building in 2011. The SSDS

is a high vacuum system utilizing fourteen (14) suction points positioned at location shown on Figure 9. Photographs of the system installation are included in Appendix B of this SMP. The fourteen (14) suction points are identified herein, and will be referenced in the future, as S-1, S-2, S-3, and S-4 (clockwise around warehouse starting in the southwest corner); S-5, S-6, and S-7 (south to north along office area wall); S-8 and S-9 (northeastern rooms of building), and S-10, S-11, S-12, S-13, and S-14 (southeastern rooms of building).

Each SSDS suction point consists of a 4 inch hole cored through the existing concrete slab. Each suction riser was constructed of 3 inch diameter schedule 40 polyvinyl chloride (PVC) piping. Each suction riser was connected to a single fan on the roof utilizing a trunk line network consisting of 4 inch diameter PVC piping. Each riser pipe is outfitted with a magnehelic pressure gauge, to allow for monitoring of system performance, and an interior baffle that can be adjusted to regulate airflow. All floor, wall, and roof penetrations were sealed with a VOC compliant urethane sealant. Design details are presented in the Operation and Maintenance Plan (Section 4 of this SMP).

Procedures for monitoring the system, including inspections in the event that an identified severe condition occurs, are included in the Monitoring Plan (Section 3 of this SMP). Procedures for operating and maintaining the SSDS are documented in the Operation and Maintenance Plan (Section 4 of this SMP).

A series of Institutional Controls is required by the RAWP to: (1) implement, maintain and monitor Engineering Control systems; (2) prevent future exposure to remaining contamination by controlling disturbances of the subsurface contamination; and, (3) limit the use and development of the Site to Commercial or Industrial uses only. Adherence to these Institutional Controls on the Site is required by the Environmental Easement and will be implemented under this Site Management Plan. These Institutional Controls are:

• Compliance with the Environmental Easement and this SMP by the Grantor and the Grantor's successors and assigns;

• All Engineering Controls must be operated and maintained as specified in this SMP;

• All Engineering Controls on the Controlled Property must be inspected at a frequency and in a manner defined in the SMP;

• Groundwater and other environmental or public health monitoring must be performed as defined in this SMP; and

• Data and information pertinent to Site Management of the Controlled Property must be reported at the frequency and in a manner defined in this SMP.

Institutional Controls identified in the Environmental Easement may not be discontinued without an amendment to or extinguishment of the Environmental Easement.

The Site has a series of Institutional Controls in the form of Site restrictions. Adherence to these Institutional Controls is required by the Environmental Easement. Site restrictions that apply to the Controlled Property are:

• The property may only be used for Commercial or Industrial use provided that the long-term Engineering and Institutional Controls included in this SMP are employed;

• The property may not be used for a higher level of use, such as unrestricted, residential, or restricted residential use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;

• All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with this SMP and the Excavation Work Plan (Appendix C);

• The use of the groundwater underlying the property is prohibited without treatment rendering it safe for intended use;

• The potential for vapor intrusion must be evaluated for any buildings developed onsite, and any potential impacts that are identified must be monitored or mitigated;

• Vegetable gardens and farming on the property are prohibited;

• The Site owner or remedial party will submit to NYSDEC a written statement that certifies, under penalty of perjury, that: (1) controls employed at the Controlled Property are unchanged from the previous certification or that any changes to the controls were approved by the NYSDEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and environment or that constitute a violation or failure to comply with the SMP. NYSDEC retains the right to access such Controlled Property at any time in order to evaluate the continued maintenance of any and all controls. This certification shall be submitted annually, or an alternate period of time that NYSDEC may allow and will be made by an expert that the NYSDEC finds acceptable; and

• The Site owner is required to monitor whether there is a change in ownership of the adjacent property currently owned by The Brannock Device Company, located at 116 Luther Avenue. If a change in ownership occurs the current owner will need to be notified of the environmental conditions of the 110 Luther Avenue Site and afforded the option to evaluate the potential for soil vapor intrusion into the building.

Notification must also be made to the NYSDEC if the adjacent property is sold or ownership is transferred.

2.3.1 Excavation Work Plan

The Site has been remediated for commercial use. Any future intrusive work that will encounter or disturb the remaining contamination, including any modifications or repairs to the existing cover system will be performed in compliance with the Excavation Work Plan (EWP) that is attached as Appendix C to this SMP. Any work conducted pursuant to the EWP must also be conducted in accordance with the procedures defined in a Health and Safety Plan (HASP) and Community Air Monitoring Plan (CAMP) prepared for the Site. A sample HASP and CAMP are attached as Appendix D to this SMP that is in current compliance with DER-10, and 29 CFR 1910, 29 CFR 1926, and all other applicable Federal, State and local regulations. Based on future changes to State and federal health and safety requirements, and specific methods employed by future contractors, the HASP and CAMP will be updated and re-submitted with the notification provided in Section C-1 of the EWP. Any intrusive construction work will be performed in compliance with the EWP, HASP and CAMP, and will be included in the periodic inspection and certification reports submitted under the Site Management Reporting Plan (See Section 5).

The Site owner and associated parties preparing the remedial documents submitted to the State, and parties performing this work, are completely responsible for the safe performance of all intrusive work, the structural integrity of excavations, proper disposal of excavation de-water, control of runoff from open excavations into remaining contamination, and for structures that may be affected by excavations (such as building foundations and bridge footings). The Site owner will ensure that Site development activities will not interfere with, or otherwise impair or compromise, the engineering controls described in this SMP.

2.3.2 Soil Vapor Intrusion Evaluation

Prior to the construction of any enclosed structures at the Site, an SVI evaluation will be performed to determine whether any mitigation measures are necessary to eliminate potential exposure to vapors in the proposed structure. Alternatively, an SVI mitigation system may be installed as an element of the building foundation without first conducting an investigation. This mitigation system will include a vapor barrier and passive sub-slab depressurization system that is capable of being converted to an active system. Prior to conducting an SVI investigation or installing a mitigation system, a work plan will be developed and submitted to the NYSDEC and NYSDOH for approval. This work plan will be developed in accordance with the most recent NYSDOH "Guidance for Evaluating Vapor Intrusion in the State of New York". Measures to be employed to mitigate potential vapor intrusion will be evaluated, selected, designed, installed, and maintained based on the SVI evaluation, the NYSDOH guidance, and construction details of the proposed structure.

Preliminary (unvalidated) SVI sampling data will be forwarded to the NYSDEC and NYSDOH for initial review and interpretation. Upon validation, the final data will be transmitted to the agencies, along with a recommendation for follow-up action, such as mitigation. If any indoor air test results exceed NYSDOH guidelines, relevant NYSDOH fact sheets will be provided to all tenants and occupants of the property within 15 days of receipt of validated data.

SVI sampling results, evaluations, and follow-up actions will also be summarized in the next Periodic Review Report.

085-12-06.1

Box Capital, LLC

Ground Water Use Restriction

Site Management Plan Monitoring Plan Landuse Restriction O&M Plan IC/EC Plan

A sub-slab depressurization system (SSDS) was installed in the existing Site building in 2011. The SSDS is a high vacuum system utilizing fourteen (14) suction points positioned at location shown on Figure 9. Photographs of the system installation are included in Appendix B of this SMP. The fourteen (14) suction points are identified herein, and will be referenced in the future, as S-1, S-2, S-3, and S-4 (clockwise around warehouse starting in the southwest corner); S-5, S-6, and S-7 (south to north along office area wall); S-8 and S-9 (northeastern rooms of building), and S-10, S-11, S-12, S-13, and S-14 (southeastern rooms of building).

Each SSDS suction point consists of a 4 inch hole cored through the existing concrete slab. Each suction riser was constructed of 3 inch diameter schedule 40 polyvinyl chloride (PVC) piping. Each suction riser was connected to a single fan on the roof utilizing a trunk line network consisting of 4 inch diameter PVC piping. Each riser pipe is outfitted with a magnehelic pressure gauge, to allow for monitoring of system performance, and an interior baffle that can be adjusted to regulate airflow. All floor, wall, and roof

penetrations were sealed with a VOC compliant urethane sealant. Design details are presented in the Operation and Maintenance Plan (Section 4 of this SMP).

Procedures for monitoring the system, including inspections in the event that an identified severe condition occurs, are included in the Monitoring Plan (Section 3 of this SMP). Procedures for operating and maintaining the SSDS are documented in the Operation and Maintenance Plan (Section 4 of this SMP).

A series of Institutional Controls is required by the RAWP to: (1) implement, maintain and monitor Engineering Control systems; (2) prevent future exposure to remaining contamination by controlling disturbances of the subsurface contamination; and, (3) limit the use and development of the Site to Commercial or Industrial uses only. Adherence to these Institutional Controls on the Site is required by the Environmental Easement and will be implemented under this Site Management Plan. These Institutional Controls are:

• Compliance with the Environmental Easement and this SMP by the Grantor and the Grantor's successors and assigns;

• All Engineering Controls must be operated and maintained as specified in this SMP;

• All Engineering Controls on the Controlled Property must be inspected at a frequency and in a manner defined in the SMP;

• Groundwater and other environmental or public health monitoring must be performed as defined in this SMP; and

• Data and information pertinent to Site Management of the Controlled Property must be reported at the frequency and in a manner defined in this SMP.

Institutional Controls identified in the Environmental Easement may not be discontinued without an amendment to or extinguishment of the Environmental Easement.

The Site has a series of Institutional Controls in the form of Site restrictions. Adherence to these Institutional Controls is required by the Environmental Easement. Site restrictions that apply to the Controlled Property are:

• The property may only be used for Commercial or Industrial use provided that the long-term Engineering and Institutional Controls included in this SMP are employed;

• The property may not be used for a higher level of use, such as unrestricted, residential, or restricted residential use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;

• All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with this SMP and the Excavation Work Plan (Appendix C);

• The use of the groundwater underlying the property is prohibited without treatment rendering it safe for intended use;

• The potential for vapor intrusion must be evaluated for any buildings developed onsite, and any potential impacts that are identified must be monitored or mitigated;

• Vegetable gardens and farming on the property are prohibited;

• The Site owner or remedial party will submit to NYSDEC a written statement that certifies, under penalty of perjury, that: (1) controls employed at the Controlled Property are unchanged from the previous certification or that any changes to the controls were approved by the NYSDEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and environment or that constitute a violation or failure to comply with the SMP. NYSDEC retains the right to access such Controlled Property at any time in order to evaluate the continued maintenance of any and all controls. This certification shall be submitted annually, or an alternate period of time that NYSDEC may allow and will be made by an expert that the NYSDEC finds acceptable; and

• The Site owner is required to monitor whether there is a change in ownership of the adjacent property currently owned by The Brannock Device Company, located at 116 Luther Avenue. If a change in ownership occurs the current owner will need to be notified of the environmental conditions of the 110 Luther Avenue Site and afforded the option to evaluate the potential for soil vapor intrusion into the building. Notification must also be made to the NYSDEC if the adjacent property is sold or ownership is transferred.

2.3.1 Excavation Work Plan

The Site has been remediated for commercial use. Any future intrusive work that will encounter or disturb the remaining contamination, including any modifications or repairs to the existing cover system will be performed in compliance with the Excavation Work Plan (EWP) that is attached as Appendix C to this SMP. Any work conducted pursuant to the EWP must also be conducted in accordance with the procedures defined in a Health and Safety Plan (HASP) and Community Air Monitoring Plan (CAMP) prepared for the Site. A sample HASP and CAMP are attached as Appendix D to this SMP that is in current compliance with DER-10, and 29 CFR 1910, 29 CFR 1926, and all other applicable Federal, State and local regulations. Based on future changes to State and federal health and safety requirements, and

specific methods employed by future contractors, the HASP and CAMP will be updated and re-submitted with the notification provided in Section C-1 of the EWP. Any intrusive construction work will be performed in compliance with the EWP, HASP and CAMP, and will be included in the periodic inspection and certification reports submitted under the Site Management Reporting Plan (See Section 5).

The Site owner and associated parties preparing the remedial documents submitted to the State, and parties performing this work, are completely responsible for the safe performance of all intrusive work, the structural integrity of excavations, proper disposal of excavation de-water, control of runoff from open excavations into remaining contamination, and for structures that may be affected by excavations (such as building foundations and bridge footings). The Site owner will ensure that Site development activities will not interfere with, or otherwise impair or compromise, the engineering controls described in this SMP.

2.3.2 Soil Vapor Intrusion Evaluation

Prior to the construction of any enclosed structures at the Site, an SVI evaluation will be performed to determine whether any mitigation measures are necessary to eliminate potential exposure to vapors in the proposed structure. Alternatively, an SVI mitigation system may be installed as an element of the building foundation without first conducting an investigation. This mitigation system will include a vapor barrier and passive sub-slab depressurization system that is capable of being converted to an active system. Prior to conducting an SVI investigation or installing a mitigation system, a work plan will be developed and submitted to the NYSDEC and NYSDOH for approval. This work plan will be developed in accordance with the most recent NYSDOH "Guidance for Evaluating Vapor Intrusion in the State of New York". Measures to be employed to mitigate potential vapor intrusion will be evaluated, selected, designed, installed, and maintained based on the SVI evaluation, the NYSDOH guidance, and construction details of the proposed structure.

Preliminary (unvalidated) SVI sampling data will be forwarded to the NYSDEC and NYSDOH for initial review and interpretation. Upon validation, the final data will be transmitted to the agencies, along with a recommendation for follow-up action, such as mitigation. If any indoor air test results exceed NYSDOH guidelines, relevant NYSDOH fact sheets will be provided to all tenants and occupants of the property within 15 days of receipt of validated data.

SVI sampling results, evaluations, and follow-up actions will also be summarized in the next Periodic Review Report.

085-12-08.0

Box Capital, LLC

IC/EC Plan

Landuse Restriction Monitoring Plan O&M Plan Ground Water Use Restriction Site Management Plan

A sub-slab depressurization system (SSDS) was installed in the existing Site building in 2011. The SSDS is a high vacuum system utilizing fourteen (14) suction points positioned at location shown on Figure 9. Photographs of the system installation are included in Appendix B of this SMP. The fourteen (14) suction points are identified herein, and will be referenced in the future, as S-1, S-2, S-3, and S-4 (clockwise around warehouse starting in the southwest corner); S-5, S-6, and S-7 (south to north along office area wall); S-8 and S-9 (northeastern rooms of building), and S-10, S-11, S-12, S-13, and S-14 (southeastern rooms of building).

Each SSDS suction point consists of a 4 inch hole cored through the existing concrete slab. Each suction riser was constructed of 3 inch diameter schedule 40 polyvinyl chloride (PVC) piping. Each suction riser was connected to a single fan on the roof utilizing a trunk line network consisting of 4 inch diameter PVC piping. Each riser pipe is outfitted with a magnehelic pressure gauge, to allow for monitoring of system performance, and an interior baffle that can be adjusted to regulate airflow. All floor, wall, and roof penetrations were sealed with a VOC compliant urethane sealant. Design details are presented in the Operation and Maintenance Plan (Section 4 of this SMP).

Procedures for monitoring the system, including inspections in the event that an identified severe condition occurs, are included in the Monitoring Plan (Section 3 of this SMP). Procedures for operating and maintaining the SSDS are documented in the Operation and Maintenance Plan (Section 4 of this SMP).

A series of Institutional Controls is required by the RAWP to: (1) implement, maintain and monitor Engineering Control systems; (2) prevent future exposure to remaining contamination by controlling disturbances of the subsurface contamination; and, (3) limit the use and development of the Site to Commercial or Industrial uses only. Adherence to these Institutional Controls on the Site is required by the Environmental Easement and will be implemented under this Site Management Plan. These Institutional Controls are:

• Compliance with the Environmental Easement and this SMP by the Grantor and the Grantor's successors and assigns;

• All Engineering Controls must be operated and maintained as specified in this SMP;

• All Engineering Controls on the Controlled Property must be inspected at a frequency and in a manner defined in the SMP;

• Groundwater and other environmental or public health monitoring must be performed as defined in this SMP; and

• Data and information pertinent to Site Management of the Controlled Property must be reported at the frequency and in a manner defined in this SMP.

Institutional Controls identified in the Environmental Easement may not be discontinued without an amendment to or extinguishment of the Environmental Easement.

The Site has a series of Institutional Controls in the form of Site restrictions. Adherence to these Institutional Controls is required by the Environmental Easement. Site restrictions that apply to the Controlled Property are:

• The property may only be used for Commercial or Industrial use provided that the long-term Engineering and Institutional Controls included in this SMP are employed;

• The property may not be used for a higher level of use, such as unrestricted, residential, or restricted residential use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;

• All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with this SMP and the Excavation Work Plan (Appendix C);

• The use of the groundwater underlying the property is prohibited without treatment rendering it safe for intended use;

• The potential for vapor intrusion must be evaluated for any buildings developed onsite, and any potential impacts that are identified must be monitored or mitigated;

· Vegetable gardens and farming on the property are prohibited;

• The Site owner or remedial party will submit to NYSDEC a written statement that certifies, under penalty of perjury, that: (1) controls employed at the Controlled Property are unchanged from the previous certification or that any changes to the controls were approved by the NYSDEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and environment or that constitute a violation or failure to comply with the SMP. NYSDEC retains the right to access such Controlled Property at any time in order to evaluate the continued maintenance of any and all controls. This certification shall be submitted annually, or an alternate period of time that NYSDEC may allow and will be made by an expert that the NYSDEC finds acceptable; and

• The Site owner is required to monitor whether there is a change in ownership of the adjacent property currently owned by The Brannock Device Company, located at 116 Luther Avenue. If a change in ownership occurs the current owner will need to be notified of the environmental conditions of the 110 Luther Avenue Site and afforded the option to evaluate the potential for soil vapor intrusion into the building. Notification must also be made to the NYSDEC if the adjacent property is sold or ownership is transferred.

2.3.1 Excavation Work Plan

The Site has been remediated for commercial use. Any future intrusive work that will encounter or disturb the remaining contamination, including any modifications or repairs to the existing cover system will be performed in compliance with the Excavation Work Plan (EWP) that is attached as Appendix C to this SMP. Any work conducted pursuant to the EWP must also be conducted in accordance with the procedures defined in a Health and Safety Plan (HASP) and Community Air Monitoring Plan (CAMP) prepared for the Site. A sample HASP and CAMP are attached as Appendix D to this SMP that is in current compliance with DER-10, and 29 CFR 1910, 29 CFR 1926, and all other applicable Federal, State and local regulations. Based on future changes to State and federal health and safety requirements, and specific methods employed by future contractors, the HASP and CAMP will be updated and re-submitted with the notification provided in Section C-1 of the EWP. Any intrusive construction work will be performed in compliance with the EWP, HASP and CAMP, and will be included in the periodic inspection and certification reports submitted under the Site Management Reporting Plan (See Section 5).

The Site owner and associated parties preparing the remedial documents submitted to the State, and parties performing this work, are completely responsible for the safe performance of all intrusive work, the structural integrity of excavations, proper disposal of excavation de-water, control of runoff from open excavations into remaining contamination, and for structures that may be affected by excavations (such as building foundations and bridge footings). The Site owner will ensure that Site development activities will not interfere with, or otherwise impair or compromise, the engineering controls described in this SMP.

2.3.2 Soil Vapor Intrusion Evaluation

Prior to the construction of any enclosed structures at the Site, an SVI evaluation will be performed to determine whether any mitigation measures are necessary to eliminate potential exposure to vapors in the proposed structure. Alternatively, an SVI mitigation system may be installed as an element of the building foundation without first conducting an investigation. This mitigation system will include a vapor barrier and passive sub-slab depressurization system that is capable of being converted to an active system.

Prior to conducting an SVI investigation or installing a mitigation system, a work plan will be developed and submitted to the NYSDEC and NYSDOH for approval. This work plan will be developed in accordance with the most recent NYSDOH "Guidance for Evaluating Vapor Intrusion in the State of New York". Measures to be employed to mitigate potential vapor intrusion will be evaluated, selected, designed, installed, and maintained based on the SVI evaluation, the NYSDOH guidance, and construction details of the proposed structure.

Preliminary (unvalidated) SVI sampling data will be forwarded to the NYSDEC and NYSDOH for initial review and interpretation. Upon validation, the final data will be transmitted to the agencies, along with a recommendation for follow-up action, such as mitigation. If any indoor air test results exceed NYSDOH guidelines, relevant NYSDOH fact sheets will be provided to all tenants and occupants of the property within 15 days of receipt of validated data.

SVI sampling results, evaluations, and follow-up actions will also be summarized in the next Periodic Review Report.

085-12-09.0

Box Capital, LLC

Ground Water Use Restriction Monitoring Plan Site Management Plan

Landuse Restriction O&M Plan IC/EC Plan

A sub-slab depressurization system (SSDS) was installed in the existing Site building in 2011. The SSDS is a high vacuum system utilizing fourteen (14) suction points positioned at location shown on Figure 9. Photographs of the system installation are included in Appendix B of this SMP. The fourteen (14) suction points are identified herein, and will be referenced in the future, as S-1, S-2, S-3, and S-4 (clockwise around warehouse starting in the southwest corner); S-5, S-6, and S-7 (south to north along office area wall); S-8 and S-9 (northeastern rooms of building), and S-10, S-11, S-12, S-13, and S-14 (southeastern rooms of building).

Each SSDS suction point consists of a 4 inch hole cored through the existing concrete slab. Each suction riser was constructed of 3 inch diameter schedule 40 polyvinyl chloride (PVC) piping. Each suction riser was connected to a single fan on the roof utilizing a trunk line network consisting of 4 inch diameter PVC piping. Each riser pipe is outfitted with a magnehelic pressure gauge, to allow for monitoring of system performance, and an interior baffle that can be adjusted to regulate airflow. All floor, wall, and roof penetrations were sealed with a VOC compliant urethane sealant. Design details are presented in the Operation and Maintenance Plan (Section 4 of this SMP).

Procedures for monitoring the system, including inspections in the event that an identified severe condition occurs, are included in the Monitoring Plan (Section 3 of this SMP). Procedures for operating and maintaining the SSDS are documented in the Operation and Maintenance Plan (Section 4 of this SMP).

A series of Institutional Controls is required by the RAWP to: (1) implement, maintain and monitor Engineering Control systems; (2) prevent future exposure to remaining contamination by controlling disturbances of the subsurface contamination; and, (3) limit the use and development of the Site to Commercial or Industrial uses only. Adherence to these Institutional Controls on the Site is required by the Environmental Easement and will be implemented under this Site Management Plan. These Institutional Controls are:

• Compliance with the Environmental Easement and this SMP by the Grantor and the Grantor's successors and assigns;

• All Engineering Controls must be operated and maintained as specified in this SMP;

• All Engineering Controls on the Controlled Property must be inspected at a frequency and in a manner defined in the SMP;

• Groundwater and other environmental or public health monitoring must be performed as defined in this SMP; and

• Data and information pertinent to Site Management of the Controlled Property must be reported at the frequency and in a manner defined in this SMP.

Institutional Controls identified in the Environmental Easement may not be discontinued without an amendment to or extinguishment of the Environmental Easement.

The Site has a series of Institutional Controls in the form of Site restrictions. Adherence to these Institutional Controls is required by the Environmental Easement. Site restrictions that apply to the Controlled Property are:

• The property may only be used for Commercial or Industrial use provided that the long-term Engineering and Institutional Controls included in this SMP are employed;

• The property may not be used for a higher level of use, such as unrestricted, residential, or restricted residential use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;

• All future activities on the property that will disturb remaining contaminated material must be conducted in accordance with this SMP and the Excavation Work Plan (Appendix C);

• The use of the groundwater underlying the property is prohibited without treatment rendering it safe for intended use;

• The potential for vapor intrusion must be evaluated for any buildings developed onsite, and any potential impacts that are identified must be monitored or mitigated;

· Vegetable gardens and farming on the property are prohibited;

• The Site owner or remedial party will submit to NYSDEC a written statement that certifies, under penalty of perjury, that: (1) controls employed at the Controlled Property are unchanged from the previous certification or that any changes to the controls were approved by the NYSDEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and environment or that constitute a violation or failure to comply with the SMP. NYSDEC retains the right to access such Controlled Property at any time in order to evaluate the continued maintenance of any and all controls. This certification shall be submitted annually, or an alternate period of time that NYSDEC may allow and will be made by an expert that the NYSDEC finds acceptable; and

• The Site owner is required to monitor whether there is a change in ownership of the adjacent property currently owned by The Brannock Device Company, located at 116 Luther Avenue. If a change in ownership occurs the current owner will need to be notified of the environmental conditions of the 110 Luther Avenue Site and afforded the option to evaluate the potential for soil vapor intrusion into the building. Notification must also be made to the NYSDEC if the adjacent property is sold or ownership is transferred.

2.3.1 Excavation Work Plan

The Site has been remediated for commercial use. Any future intrusive work that will encounter or disturb the remaining contamination, including any modifications or repairs to the existing cover system will be performed in compliance with the Excavation Work Plan (EWP) that is attached as Appendix C to this SMP. Any work conducted pursuant to the EWP must also be conducted in accordance with the procedures defined in a Health and Safety Plan (HASP) and Community Air Monitoring Plan (CAMP) prepared for the Site. A sample HASP and CAMP are attached as Appendix D to this SMP that is in current compliance with DER-10, and 29 CFR 1910, 29 CFR 1926, and all other applicable Federal, State and local regulations. Based on future changes to State and federal health and safety requirements, and specific methods employed by future contractors, the HASP and CAMP will be updated and re-submitted with the notification provided in Section C-1 of the EWP. Any intrusive construction work will be performed in compliance with the EWP, HASP and CAMP, and will be included in the periodic inspection and certification reports submitted under the Site Management Reporting Plan (See Section 5).

The Site owner and associated parties preparing the remedial documents submitted to the State, and parties performing this work, are completely responsible for the safe performance of all intrusive work, the structural integrity of excavations, proper disposal of excavation de-water, control of runoff from open excavations into remaining contamination, and for structures that may be affected by excavations (such as building foundations and bridge footings). The Site owner will ensure that Site development activities will not interfere with, or otherwise impair or compromise, the engineering controls described in this SMP.

2.3.2 Soil Vapor Intrusion Evaluation

Prior to the construction of any enclosed structures at the Site, an SVI evaluation will be performed to determine whether any mitigation measures are necessary to eliminate potential exposure to vapors in the proposed structure. Alternatively, an SVI mitigation system may be installed as an element of the building foundation without first conducting an investigation. This mitigation system will include a vapor barrier and passive sub-slab depressurization system that is capable of being converted to an active system. Prior to conducting an SVI investigation or installing a mitigation system, a work plan will be developed and submitted to the NYSDEC and NYSDOH for approval. This work plan will be developed in accordance with the most recent NYSDOH "Guidance for Evaluating Vapor Intrusion in the State of New York". Measures to be employed to mitigate potential vapor intrusion will be evaluated, selected, designed, installed, and maintained based on the SVI evaluation, the NYSDOH guidance, and construction details of the proposed

structure.

Preliminary (unvalidated) SVI sampling data will be forwarded to the NYSDEC and NYSDOH for initial review and interpretation. Upon validation, the final data will be transmitted to the agencies, along with a recommendation for follow-up action, such as mitigation. If any indoor air test results exceed NYSDOH guidelines, relevant NYSDOH fact sheets will be provided to all tenants and occupants of the property within 15 days of receipt of validated data.

SVI sampling results, evaluations, and follow-up actions will also be summarized in the next Periodic Review Report.

| | | Box 4 |
|------------------------------|---|-------|
| Description of Engi | neering Controls | |
| <u>Parcel</u> 085-12-04.1 | Engineering Control Vapor Mitigation | |
| | Cover System | |
| 085-12-05.0 | Cover System Vapor Mitigation | |
| 085-12-06.1 | Vapor Mitigation Cover System | |
| 085-12-08.0 | Cover System Vapor Mitigation | |
| 085-12-09.0 | Vapor Mitigation Cover System | |

| | | Box 5 |
|---|-------|---------|
| Periodic Review Report (PRR) Certification Statements | | |
| I certify by checking "YES" below that: | | |
| a) the Periodic Review report and all attachments were prepared under the direction or reviewed by, the party making the certification; | of, a | and |
| b) to the best of my knowledge and belief, the work and conclusions described in this are in accordance with the requirements of the site remedial program, and generally a engineering practices; and the information presented is accurate and compete. | | |
| YES | ; | NO |
| X | | |
| If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all o following statements are true: | | |
| (a) the Institutional Control and/or Engineering Control(s) employed at this site is uncl since the date that the Control was put in-place, or was last approved by the Departme | | |
| (b) nothing has occurred that would impair the ability of such Control, to protect public the environment; | : he | alth an |
| (c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control; | | |
| (d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and | | |
| (e) if a financial assurance mechanism is required by the oversight document for the mechanism remains valid and sufficient for its intended purpose established in the doc | | |
| YES | ; | NO |
| X | | |
| IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue. | | |
| A Corrective Measures Work Plan must be submitted along with this form to address these i | รรเ | les. |
| | | |
| Signature of Owner, Remedial Party or Designated Representative Date | | |

| | IC CERTIFICATIONS SITE NO. C734118 | | | | | | | |
|---|---|---|--|--|--|--|--|--|
| | | Box 6 | | | | | | |
| SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the | | | | | | | | |
| Penal Law. Kathleen Alaimo | Syracuse Label & 200 Stewart Drive at 13212 | Surround Printing , North Syracuse, New York | | | | | | |
| print name | print busines | s address | | | | | | |
| am certifying as Re | medial Party | (Owner or Remedial Party) | | | | | | |
| for the Site named in the Site Det | ails Section of this form. | | | | | | | |
| Kathles all Signature of Owner, Remedial Pa Rendering Certification | 421120 Date | | | | | | | |

| | TIFICATIONO |
|--|---|
| IC/EC CER | TIFICATIONS |
| | Box 7 |
| Professional | Engineer Signature |
| certify that all information in Boxes 4 and 5 are tr unishable as a Class "A" misdemeanor, pursuant | rue. I understand that a false statement made herein is to Section 210.45 of the Penal Law. |
| | Consulting Services Inc., 5788 waters Pkwy, Syracuse, New York 13214 |
| print name | print business address |
| m certifying as a Professional Engineer for the _ | Remedial Party |
| | (Owner or Remedial Party) |

Appendix B Property Ownership Information for Adjoining Property

SDG

Property Description Report For: 116 Luther Ave, Municipality of Town of Salina

| | | Status: | Active |
|-----------------------|------------------|----------------------|--------------------------------------|
| | | Roll Section: | Taxable |
| | | Swis: | 314889 |
| | | Tax Map ID #: | 08512-10.0 |
| No Dhata | | Property #: | |
| No Photo Available | | Property Class: | 710 - Manufacture |
| Avallable | | Site: | COM 1 |
| | | In Ag. District: | No |
| | | Site Property Class: | 710 - Manufacture |
| | | Zoning Code: | 06 |
| | | Neighborhood Code: | 48070 |
| Total Acreage/Size: | 90 x 90 | School District: | Liverpool |
| Land Assessment: | 2019 - \$18,000 | Total Assessment: | 2019 - \$116,000 |
| Full Market Value: | 2019 - \$116,000 | | |
| Equalization Rate: | | Property Desc: | Buckley Gardens Lts 434 435 & 436 |
| Deed Book: | 4013 | Deed Page: | 42 |
| Grid East: | 610957 | Grid North: | 1125115 |

Owners

Leonardi Salvatore A Jr 116 Luther Ave Liverpool NY 13088-6726

Sales

| Sale Date | Price | Property Class | Sale Type | Prior Owner | Value Usable | | Addl. Parcels | Deed Book and Page |
|-----------|-----------|----------------------|--------------------|-------------------------|-----------------|-----|------------------|-----------------------|
| 7/12/1995 | \$125,000 | 710 - Manufacture | Land & Building | Masterpol Nicholas J | Yes | Yes | No | 4013/42 |
| 1/4/1995 | \$75,000 | 710 - Manufacture | Land & Building | Krull Duane | Yes | Yes | No | 3977/76 |
| Utilities | | | | | | | | |

| Sewer Type: | Comm/public | Water Supply: | Comm/public |
|--------------------------------|-------------|------------------------------|-------------|
| Utilities: | Gas & elec | | |
| Inventory | | | |
| Overall Eff Year Built: | 0 | Overall Condition: | Normal |
| Overall Grade: | Economy | Overall Desirability: | 3 |

Buildings

Eff

| AC% | Sprinkler% | Alarm% | Elevators | Basement Type | | ar ilt Condition | Quality | Gross Floor Area (sqft) | Stories |
|---------|------------|--------|-------------|------------------|-------------|---------------------|---------|----------------------------|---------|
| 67 | 0 | 0 | 0 | | 1960 | Normal | Average | 4113 | 1 |
| Site L | Jses | | | | | | | | |
| Use | | Re | entable Are | ea (sqft) | Total Units | 5 | | | |
| Light r | nfg | | | 4,113 | | 0 | | | |
| Impro | ovements | | | | | | | | |
| Struct | ture | Size | | Grade | • | Conditio | n | Year | |
| Canpy | -w/slab | 24.00 | sq ft | Econo | my | Fair | | 1960 | |
| Pavng | -asphlt | 3900 > | : 4 | Avera | ge | Fair | | 1970 | |
| Land | Types | | | | | | | | |
| | | Si | ze | | | | | | |
| Туре | | |) × 90 | | | | | | |

| Description | Units | Percent | Туре | Value |
|-------------------------------|-------|---------|------|-------|
| FP014-Liverpool fire prot | 0 | 0% | | 0 |
| EM003-Salina ambulance | 0 | 0% | | 0 |
| CWR40-County water | 0 | 0% | | 0 |
| WT044-Salina cons wat sup | 1 | 0% | | 0 |
| SX208-Buckley 7th n sew om | 1 | 0% | | 0 |
| CDR50-Beartrap I c drg co | 0 | 0% | | 0 |
| CSW15-Onon co san un | 1 | 0% | | 0 |
| SX243-Cons Sewer 3 GalevII | 1 | 0% | | 0 |

Exemptions

| Year | Description | Amount | Exempt % | Start Yr | End Yr | V Flag | H Code | Own % | |
|------|-------------|--------|----------|----------|--------|--------|--------|-------|--|
|------|-------------|--------|----------|----------|--------|--------|--------|-------|--|

Taxes

| iption |
|--------|
| ip |

Amount

* Taxes reflect exemptions, but may not include recent changes in assessment.

Appendix C Sub-Slab Depressurization System Inspection Checklists / Annual Inspection Form / Representative Photographs

| Sub-Slab Depressurization System | | Date: | 3-14-19 |
|--|---------------------------------------|-----------------------------|------------------|
| Inspection Checklist | | Insepctors Name: | Kellin Gagnon |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | | Company: | STRLSP |
| | | Inspector Initials: | G |
| I. Pressure Readings Suction Riser Pressure | II. Fan Inspection | | \sim |
| Identification Reading (inWC) | 1. Operational? | Y | <u> </u> |
| S-1 | | | N . |
| S-2 <u> </u> | 2. Fan/Controls Clear of obs | structions? Y | <u> </u> |
| S-3 <u>5</u> | | | |
| S-4 <u>3 · 1</u> | 3. Rapair needs? | Y | N <u>X</u> |
| S-5 <u>3.4</u> | | | 1 |
| S-6 <u>3</u> | A. Observations/comments: | | |
| 3-7 | | | |
| | | | N |
| S-9 <u>1, C</u> S-10 <u>2, 1</u> | | | |
| S-11 2,8 | | | |
| S-12 7.1 | | | |
| S-13 3 | | | |
| S-14 2.8 | | | |
| | | | |
| Notes: | | | |
| Locations of suction risers can be found on attached Figure. | | | |
| System details are included in Appendix B. | | | |
| | Attach photographs as appropriate | | |
| III. Piping/Penetrations | | | |
| 1. Is piping intact? (Y) or N) | B. Actions taken: | | |
| 2. Are floor/wall penetrations sealed? (Y or N) | | | |
| | | | |
| If 'No' to either of the above, provide observations | | <u></u> | |
| and describe corrective actions taken | C. Recommended Maintena | ince/Pensire' | |
| | C. Recommended Maintena | inden (epairs. | |
| | | | |
| | | | |
| | | | |
| | | | |
| Do any of the pressure gages require repair or replace | ment? Y | N | |
| If so, indicate locations, and actions taken: | | | |
| | | | |
| | | | |
| | · · · · · · · · · · · · · · · · · · · | | tom? (Describe) |
| IV. Building Modifications: Have building modifications | been made that could affect th | te operation of the SSD Sys | acine (Describe) |
| None at this time | | | |
| | | | |
| | | | |
| Additional Comments: | | | |
| | 1 1 | | |
| Checkeb both Conden. | sation traps | all dry | |
| Report all maintenance/r | epair needs immediately to b | ouilding facility manager | |

| Sub-Slab Depr | essurization System | | | Date: | | 4-27 | 3-19 | |
|----------------------|--|------|---------------------------------|-------------------|---------|-----------|------|--------------|
| Inspection Che | - | | | Insepctors Nan | e: | | Gene | inan |
| - | el, 110 Luther Avenue, Liverpool, NY | | | Company: | | SYRL | SP |) |
| I. Pressure Re | adinac | | Fan Inspection | Inspector Initial | s: | Kc, | | |
| Suction Riser | Pressure | ". | ranmspection | | | | | |
| Identification | Reading (inWC) | 1. | Operational? | | Y | X | Ν | |
| S-1 | | - | | | | × | | |
| S-2 | | 2. | Fan/Controls Clear of obstruct | ions? | Y | <u> </u> | N | |
| S-3 | 5.8 | ~ | Densis | | V | | | \mathbf{N} |
| S-4 | 3,1 | 3. | Rapair needs? | | Y | | N | × |
| S-5 . | 2 2 | | Observations | | | | | |
| S-6 | 20 | A. | Observations/comments: | | | | | |
| S-7 | 6.0 | | | | | | | |
| S-8 | 10 | | | | | | | |
| S-9 | 2.0 | | | | | | | |
| S-10 | 30 | | | | | | | |
| S-11 | 2 2 | | | | | | | |
| S-12 | 312 | | | | | | | |
| S-13 S-14 | 2,9 | | | | | | | |
| 5-14 | | | | | | | | |
| Notes: | | | | | | | | |
| | risers can be found on attached Figure. | | | | | | | |
| | ncluded in Appendix B. | | | | | | | |
| Oystem details are a | | Atta | ch photographs as appropriate | | | | | |
| III. Piping/Pene | trations | | | | <u></u> | | | |
| 1. Is piping intac | | В. | Actions taken: | | | | | |
| | penetrations sealed? (Y or N) | | | | | | | |
| | | | | | | | | |
| If 'No' to either o | f the above, provide observations | | | | | | | |
| and describe col | rrective actions taken | | | | | | | <u>.</u> |
| | | C. | Recommended Maintenance/F | Repairs: | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| L | | L | | ~! | | | | |
| | essure gages require repair or replacen | nent | ? Y | N <u>×</u> | | | | |
| | ations, and actions taken: | | | | | | | |
| | | | 2 | ÷. | | | | |
| | | | | | | | | |
| IV Building Moo | lifications: Have building modifications | beer | n made that could affect the op | eration of the SS | D Syste | m? (Descr | ibe) | |
| | | | | | | , | | |
| NOr | ve at this time | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Additional Comm | | | | | | | | |
| C.a | ndensation trups dr | - | 2 | | | | | |
| | in the second se | 7 | · Kg | | | | | |
| | Depart all maintenants for | mai | needs immediately to building | na facility mana | ner | | | |
| | керон ан <i>тап</i> телансе/ге | pail | neeus mineulately to bullon | 'y naonity mana | | | | |

| Sub Slob Door | essurization System | | | Date: | | 5-29 | -19 | |
|---------------------------------|--|-----|---------------------------------------|-------------------|--------|--------------|------|------|
| Inspection Che | • | | | Insepctors Nam | ie. | Kevin | Ga | enon |
| - | el, 110 Luther Avenue, Liverpool, NY | | | Company: | | SYRL | ςρ`` | 7 |
| Syracuse Labe | a, 110 Luner Avenue, Liverpool, NT | | | Inspector Initial | s: | KG | | · |
| I. Pressure Re | | 11. | Fan Inspection | | | | | |
| Suction Riser Identification | Pressure Reading (inWC) | 1. | Operational? | | Y | <u> </u> | Ν | |
| S-1 | 2.9 | | | | v | | NI. | |
| S-2 | <u> </u> | 2. | Fan/Controls Clear of obstruct | ions? | Y | | Ν | |
| S-3 | <u></u> | ~ | Developments (| | v | | NI S | |
| S-4 | <u> </u> | 3. | Rapair needs? | | Y | | Ν | 1 |
| S-5 | 3.6 | 1. | <u>Ohan and in a family a star</u> | | | | | |
| S-6 | 3.4 | A. | Observations/comments: | | | | | |
| S-7 | 11.5 | | | | | | | |
| S-8 | | | | | | | | |
| S-9 | 3,3 | | | | | | | |
| S-10 S-11 | 3.1 | | | | | | | |
| S-11 S-12 | 3.3 | | | | | | | |
| S-12 S-13 | 3.4 | | | | | | | |
| S-14 | 3.1 | | | | | | | |
| | | | | | | | | |
| Notes: | | | | | | | | |
| Locations of suction | risers can be found on attached Figure. | | | | | | | |
| System details are i | ncluded in Appendix B. | | | | | | | |
| | | Att | ach photographs as appropriate | | | | | |
| III. Piping/Pene | etrations | | | | | | | 7 |
| 1. Is piping inta | ct2 (Por N) | В. | Actions taken: | | | | | |
| 2. Are floor/wall | penetrations sealed?(Y or N) | | | | | | | |
| | ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ | | | | | | | |
| If 'No' to either o | of the above, provide observations | | | | | | | |
| and describe co | rrective actions taken | | | | | | | |
| | | C. | Recommended Maintenance/I | Repairs: | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | vo V | N _X | | | | |
| If so, indicate lo | essure gages require repair or replacer cations, and actions taken: | nen | lf I | - <u> </u> | | | | |
| | | | | | | | | |
| ····· | | | | | | | | |
| | | | | | | | | |
| IV. Building Mo | difications: Have building modifications | bee | n made that could affect the op | eration of the SS | D Syst | em? (Descril | be) | |
| Mart | e at this time. | | | | | | | |
| NON | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Additional Comr | nents: | | in la | | | | | |
| C | heic Condensation | . 1 | imps-ary. Ke | | | | | |
| | | | · · · · · · · · · · · · · · · · · · · | | | | | |
| | Report all maintenance/re | epa | ir needs immediately to build | ing facility mana | nger | | | I |

| Sub-Slab Depressurization System | | | Date: | | 10-7 | 6.19 | ī |
|--|------------|--|------------------|---------|-----------|---------|---------------------------------------|
| Inspection Checklist | | | Insepctors Na | me: | Kevin | (Tag) | 0.02 |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | | | Company: | | SYRL | (P | 1cm |
| | | | Inspector Initia | ils: | KÇ | <i></i> | |
| I. Pressure Readings Suction Riser Pressure | 11. | Fan Inspection | | | \ \ | | |
| Identification Reading (inWC) | 1. | Operational? | | Y | <u>\</u> | Ν | ************* |
| S-1 <u>3,4</u> | | | | | | | |
| s-2 <u>2,9</u> s-3 <u>5,8</u> | 2. | Fan/Controls Clear of obstruct | ions? | Y | | Ν | manifest de service de paragraphe con |
| S-3 <u>5,8</u> S-4 5.0 | 3 | Rapair needs? | | Y | | N | X |
| s-5 <u>3, (</u> | 0. | i capati noodo. | | • | | | |
| s-6 3, 2 | A | Observations/comments: | | | | | |
| s-7 2.1 | | | | | | | |
| S-8 4,5 | | | | | | | |
| S-9 1,9 | | | | | | | |
| s-10 3.Z | | | | | | | |
| s-11 2.9 | | | | | | | |
| | | | | | | | |
| S-12 <u>3.0</u> | | | | | | | |
| s-13 <u>3,2</u> s-14 3,0 | | | | | | | |
| S-14 <u>5, 0</u> | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | |
| System details are included in Appendix B. | | | | | | | |
| | Att | ach photographs as appropriate | | | | | |
| III. Piping/Penetrations | _ | | | | | | |
| 1. Is piping intact?(Y)or N) | B. | Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed?((Y or N) | | | | | | | |
| | | | | | | | |
| If 'No' to either of the above, provide observations | L | an a | | | | | |
| and describe corrective actions taken | | Decommonded Meintenenes | longin: | | | | |
| | <u>с</u> . | Recommended Maintenance/F | kepairs: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 20. 1 ⁰⁰ | | | | | | | |
| | | 0 V | N X | | | | |
| Do any of the pressure gages require repair or replacen If so, indicate locations, and actions taken: | nen | ? Y | N <u>~</u> | | | | |
| | | | | | | | |
| | | 2 | 21. | | | | |
| | | | | | | | |
| IV. Building Modifications: Have building modifications | bee | n made that could affect the op | eration of the S | SD Syst | em? (Desc | ribe) | |
| | | | | | | | |
| None at this time. | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Additional Comments: | | | | | | | |
| (ad the i | | | | | | | |
| Condensation traps dr | 4 | KG | | | | | |
| Report all maintenance/re | epai | r needs immediately to buildi | ng facility man | ager | | | |

| Sub-Slab Depressurization System | | | Date: | | 7-2 | 9-19 | |
|--|------|---------------------------------|----------------|-------------------|-------------|----------|-----|
| Inspection Checklist | | | Insepctors I | Jame [.] | Keizin | Gan | nih |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | | | Company: | turno. | SYRL | | |
| | | | Inspector In | itials: | Ka | | |
| I. Pressure Readings Suction Riser Pressure | 11. | Fan Inspection | | | , | | Kr |
| Identification Reading (inWC) | 1. | Operational? | | Y | X | Ν | K |
| s-1 <u>3,4</u> | | | | | | | |
| s-2 <u>3,9</u> | 2. | Fan/Controls Clear of obstruct | ions? | Y | <u>X</u> | Ν | |
| S-3 <u>5.6</u> | | | | | | | 12 |
| S-4 <u>5.0</u> | 3. | Rapair needs? | | Y | | N | X |
| S-5 <u>3,4</u> | _ | | | | | | |
| S-6 <u>3.2</u> | A. | Observations/comments: | | | | | |
| S-7 <u>5</u> () | | | | | | | |
| S-8 <u>4.5</u> | | | | | | | |
| S-9 1./ | | | | | | | |
| S-10 2.8 | | | | | | | |
| $S-11 = \frac{2}{2} \cdot \frac{6}{5}$ | | | | | | | |
| s-12 <u>2/3</u> s-13 3,7 | | | | | | | |
| s-14 3,9 | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | |
| System details are included in Appendix B. | | | | | | | |
| | Atta | ch photographs as appropriate | | | | | |
| III. Piping/Penetrations | | | | | | | |
| 1. Is piping intact? (Yor N) | В. | Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed? (Y or N) | | | | | | | |
| | | | | | | | |
| If 'No' to either of the above, provide observations | | | | | | | |
| and describe corrective actions taken | | | | | | | |
| | C. | Recommended Maintenance/F | Repairs: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Do any of the pressure gages require repair or replacer | nent | ? Y | NX | | | | |
| If so, indicate locations, and actions taken: | | | | | | | |
| | | .1 | | | | | |
| | | | | | | | |
| | | | | 000 0 | 0 (Daaa | wile a \ | |
| IV. Building Modifications: Have building modifications | bee | n made that could affect the op | eration of the | ୦୦୦ Syst | em (Desci | nue) | |
| None at this time | 1 | | | | | | |
| ivun a pris time | - (| 14) | | | | | |
| | | | | | | | |
| Additional Comments: | | | | | | | |
| | | | | | | | |
| Condensation traps d | 14 | (KG) | | | | | |
| Penort all maintananta/n | enai | r needs immediately to buildi | na facility m | anager | | |] |

| Sub-Slab Depressurization System | | | Date: | | 8-29 | -19 | |
|--|----------|---------------------------------------|--|-------------------------------|------------------------|-------|----------|
| Inspection Checklist | | | | | 17 | Grana | - |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | | k = 1 | Insepctors Nam | le. | SYRLS | | <u>N</u> |
| | | | Company: Inspector Initial | 5: | KG | 54 | |
| I. Pressure Readings Suction Riser Pressure | 11. | Fan Inspection | nen finder einen dem einen gester son der einen einen gester einen der einen der einen der einen der einen der | | | | |
| Identification Reading (inWC) | 1. | Operational? | | Y | <u> </u> | N | |
| S-1 <u>3.4</u> | | | | | | | |
| S-2 2.9 | 2. | Fan/Controls Clear of obstruc | tions? | $Y \in$ | <u></u> | N | |
| S-3 <u>5.9</u> | | | | | | | N |
| S-4 <u>3,0</u> | 3. | Rapair needs? | | Y | berry ward to a state. | Ν | <u>X</u> |
| S-5 <u>3</u> , <u>G</u> | — | | an dia mangkana ang mangkana ang mangkana dia kana dia kana dia mangkana dia kana dia mangkana dia kana dia ka | | | | |
| S-6 <u>3,2</u> | A. | Observations/comments: | | | | | |
| S-7 <u>2.9</u> S-8 <u>4</u> ,8 | | | | | | | |
| s-9 2.1 | | | | | | | |
| S-10 2.9 | | | | | | | |
| S-11 3 0 | | | | | | | |
| s-12 3,3 | | | | | | | |
| S-13 3.4 | | | | | | | |
| S-14 3,Z | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | |
| System details are included in Appendix B. | | | | | | | |
| | Atta | ch photographs as appropriate | | | | | |
| III. Piping/Penetrations | | | | | П | | |
| 1. Is piping intact? (Y or N) | В. | Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed?(Y or N) | | | | | | | |
| | | | | | | | |
| If 'No' to either of the above, provide observations | | | | ina kana ina distrika kana ka | | | |
| and describe corrective actions taken | — | | | | <u></u> | | |
| | C. | Recommended Maintenance/ | Repairs: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | 2 V | NX | | | | |
| Do any of the pressure gages require repair or replacen If so, indicate locations, and actions taken: | nent | <u>و</u> | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | · · · · · · · · · · · · · · · · · · · | | | | | |
| IV. Building Modifications: Have building modifications | bee | n made that could affect the op | eration of the SSI |) Syste | m? (Descri | be) | |
| the the | | | | | | | |
| None at this time | | | | | | | |
| | | | | | | | |
| Page 2010 100 100 100 100 100 100 100 100 10 | | | | | | | ······ |
| Additional Comments: | | | | | | | |
| Condensation traps dry | | (Cc) | | | | | |
| | | | | | | | |
| Papart all maintenance/re | | · · · · · · · · · · · · · · · · · · · | - fooilite mono | TOF | | | |

Sub-Slab Depressurization System Date: **Inspection Checklist** Insepctors Name: no Syracuse Label, 110 Luther Avenue, Liverpool, NY Company: Inspector Initials: I. Pressure Readings II. Fan Inspection Suction Riser Pressure Identification Reading (inWC) 1. Operational? N S-1 S-2 2. Fan/Controls Clear of obstructions? Ν S-3 S-4 3. Rapair needs? N S-5 S-6 Observations/comments: Α S-7 S-8 S-9 S-10 S-11 S-12 S-13 S-14 Notes: Locations of suction risers can be found on attached Figure. System details are included in Appendix B. Attach photographs as appropriate III. Piping/Penetrations 1. Is piping intact? (Y or N) B. Actions taken: 2. Are floor/wall penetrations sealed (Y) or N) If 'No' to either of the above, provide observations and describe corrective actions taken C. Recommended Maintenance/Repairs: N 🗙 Y Do any of the pressure gages require repair or replacement? If so, indicate locations, and actions taken: IV. Building Modifications: Have building modifications been made that could affect the operation of the SSD System? (Describe) None at this time Additional Comments: Condensation traps dry -

Report all maintenance/repair needs immediately to building facility manager

| | | а | | | , | 1 | |
|--|----------|---------------------------------|---------------------------|--------------|----------|-------|-----|
| Sub-Slab Depressurization System | | | Date: | | 10/2 | 9/ (9 | |
| Inspection Checklist | | | Insepctors N | lame: | Kevir | Gay | nan |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | | | Company: Inspector Ini | | SYRL | | |
| I. Pressure Readings | II. | Fan Inspection | mapeotor mi | ticito. | | | |
| Suction Riser Pressure Identification Reading (inWC) | 4 | OnevelienalO | | V | M | | |
| Identification Reading (inWC) | 4. | Operational? | | Ŷ | 2 | N | |
| 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | ~ | | | | 10 | | |
| | 2. | Fan/Controls Clear of obstruct | ions? | Y . | X | N | |
| S-3 <u>c.</u> | _ | | | | | | ~ (|
| S-4 <u>5</u> , 5 | 3. | Rapair needs? | | Y | | N | X |
| | <u> </u> | | | | | | |
| S-6 <u>3.(</u> | A. | Observations/comments: | | | | | |
| S-7 2.2 | | | | | | | |
| S-8 <u>5 D</u> | | | | | | | |
| S-9 <u>2,4</u> | | | | | | | |
| S-10 <u>3:0</u> | | | | | | | |
| S-11 <u>2.9</u> | | | | | | | |
| S-12 2,9 | | | | | | | |
| S-13 <u>3 Z</u> | | | | | | | |
| S-14 <u>2.9</u> | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | |
| System details are included in Appendix B. | | | | | | | |
| | Atta | ch photographs as appropriate | | | | | |
| III. Piping/Penetrations | | | | | | | |
| 1. Is piping intact (Nor N) | В. | Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed?((Y)or N) | | | | | | | |
| | | | | | | | |
| If 'No' to either of the above, provide observations | | | | eveletinin (| | | |
| and describe corrective actions taken | r | | | | | | |
| | C. | Recommended Maintenance/F | Repairs: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | L | | | | | | |
| Do any of the pressure gages require repair or replacer | nent | ? Y | N X | | | | |
| If so, indicate locations, and actions taken: | | | · | | | | |
| | | 3 | × | | | | |
| | | | | | | | |
| | | | | | | | |
| IV. Building Modifications: Have building modifications | bee | n made that could affect the op | eration of the | SSD Syste | m? (Desc | ribe) | |
| | | | | | | | |
| None at this time, | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Additional Comments: | | _ | | | | | |
| Condensation traps dry. | R | | | | | | |
| | Ľ | , c) | | | | | |
| Report all maintenance/r | epai | needs immediately to buildi | ng facility ma | nager | | | |

| Sub-Slab Depressurization System | | | Date: | | 11- | 26-1 | Q |
|--|--------------|---|-------------------|----------|----------------------|-------|---|
| | | | Insepctors Nar | | | | UMFORD |
| Inspection Checklist Syracuse Label, 110 Luther Avenue, Liverpool, NY | | | Company: | | | RLS | |
| I. Pressure Readings | | Fan Inspection | Inspector Initia | IS: | | | |
| Suction Riser Pressure Identification Reading (inWC) | | Operational? | | Y | X | Ν | |
| S-1 <u>4.0</u> | | | | | 2 | | |
| $\begin{array}{c} s-2 \\ s-3 \\ \hline 6, 0 \\ \hline \end{array}$ | 2. | Fan/Controls Clear of obstruc | tions? | Y . | $\underline{\times}$ | Ν | and gradient of the first state of the second |
| s-4 <u>5.0</u> | 3. | Rapair needs? | | Y | | Ν | \times |
| S-5 646 3.5 | | · · · · · · · · · · · · · · · · · · · | | | | | |
| S-6 3.5 | Α. | Observations/comments: | | | | | |
| S-7 <u>2.5</u> | | | | | | | |
| S-8 5.0 | | | | | | | |
| s-9 <u>1,5</u> | | | | | | | |
| s-10 2.5 | | | | | | | |
| S-11 2.5 | | | | | | | |
| S-12 2.5 | | | | | | | |
| S-13 3.0 | 1 | | | | | | |
| S-14 2,5 | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | |
| • | | | | | | | |
| System details are included in Appendix B. | | | | | | | |
| | Atta | ach photographs as appropriate | | | | | |
| III. Piping/Penetrations | | | | | | | |
| 1. Is piping intact? (Por N) | B. | Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed? Øor N) | | | | | | | |
| ſ <u></u> | | | | | | | |
| If 'No' to either of the above, provide observations | L | ay any amaly is a set of the state state of the fact and a set of the fact and a set of the set of the set of the | | | | | |
| and describe corrective actions taken | r | | | | | | |
| | C. | Recommended Maintenance/ | Repairs: | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | . / | | | | |
| Do any of the pressure gages require repair or replacer | nent | ? Y | <u>N X</u> | | | | |
| If so, indicate locations, and actions taken: | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| IV. Building Modifications: Have building modifications | bee | n made that could affect the op | peration of the S | SD Syste | em? (Desc | ribe) | |
| NONE AT THIS TIM | 5 | | | | | | |
| I TOONLAT THIS TH | 5 | | | | | | |
| | | | | | | | |
| L | | | | | | | |
| Additional Comments: | - | | | | | | |
| | ∂c | A42 | | | | | |
| COMPENSATION THAT | > | Dhy. m | | | | | |
| Report all maintenance/r | enai | ir needs immediately to build | ing facility man | ager | | | |

| Sub-Slab Depressurization System | | Date: | | 230 | 19 |
|--|-------------------------------------|---|---------------------------|---------------|----|
| Syracuse Label, 110 Luther Avenue, Liverpool, N | Y | Insepctors Name Company: Inspector Initials | S | SYRLSI | 21 |
| I. Pressure Readings Suction Riser Pressure | II. Fan Inspection | Inspector mitials | * ******* | <u>(<'</u> | |
| Identification Reading (inWC) | 1. Operational? | | Υ | <u> </u> | Ν |
| S-2 <u>3.7</u> S-3 6.1 | 2. Fan/Controls Clear of obstru | ctions? | Y . | X_ | N |
| S-4 | 3. Rapair needs? | | Y _ | | N |
| S-5 <u>4.0</u> S-6 <u>3.9</u> | | | | | |
| S-6 <u>3,9</u> S-7 <u>3,9</u> | A. Observations/comments: | | | | |
| S-8 5.3 | | | | | |
| S-9 3.0 | | | | | |
| S-10 3.8 | | | | | |
| S-11 3.2 | | | | | |
| S-12 4.2 | | | | | |
| S-13 3.7 | | | | | |
| S-14 7,4 | | | | | |
| Notes; | | | | | |
| Notes: Locations of suction risers can be found on attached Figure. | | | | | |
| System details are included in Appendix B. | | | | | |
| - Joenna and Housean Hipponetic D. | Attach photographs as appropriate | | | | |
| III. Piping/Penetrations | | | | | |
| 1. Is piping intact? (Y or N) | B. Actions taken: | | | | |
| 2. Are floor/wall penetrations sealed? (Y or N) | | | | | |
| | | | | 2 | |
| If 'No' to either of the above, provide observations | | | terre dia contra foto est | | |
| and describe corrective actions taken | C. Decommonded Meintenenen | /Donaim(| | | |
| | C. Recommended Maintenance | rkepairs: | | | |
| | | | | | |
| | | | | | |
| - | | | | | |
| | | | | | |
| Do any of the pressure gages require repair or replace | ement? Y | _N <u>/</u> | | | |
| If so, indicate locations, and actions taken: | | | | | |
| | | - | ~ | | |
| | | | | | |
| IV. Building Modifications: Have building modification | s been made that could affect the o | peration of the SSD | System? | ? (Describ | e) |
| | | | \sim | | |
| Node at this time | | | | | |
| Noove as this time | | | | | |
| | | a an | | | |
| Additional Oceaning and a | | | | | |
| Additional Comments: | | | | | |

| Sub-Slab Depressurization System | | Date: | | 1-31- | 20 | _ |
|--|---|--|------------|---|---------|--|
| Inspection Checklist | | Insepctors Name | : | Kewin | Ga | ando |
| Syracuse Label, 110 Luther Avenue, Liverpool, NY | Company: | | | Kevin Gagni SYRLSP | | |
| I. Pressure Readings | II. Fan Inspection | Inspector Initials | | 19 | | and the second |
| Suction Riser Pressure Identification Reading (inWC) | 1. Operational? | | Y | V | N | |
| s-1 4,0 | | | | ~ | | |
| S-2 3.4 | 2. Fan/Controls Clear of obst | tructions? | Y | ~ | Ν | |
| s-3 <u>6 Z</u> | | | | | | |
| S-4 5.5 | 3. Rapair needs? | | Y | _ | N | Y |
| s-5 <u>3,9</u> | | and the specific sector | | | | |
| S-6 3.6 | A. Observations/comments: | 1 | | | | |
| S-7 2.8 | | | | | | |
| S-8 5.0 | | | | | | |
| S-9, 2,2 | | | | | | |
| S-10 3.4 | X | | | | | |
| s-11 3.1 | A | | | | | |
| S-12 3,6 | | | | | | |
| S-13 3, 6 | | | | | | |
| S-14 3.2 | | | | | | |
| | | | | | | |
| Notes: | | | | | | |
| ocations of suction risers can be found on attached Figure. | | | | | | |
| System details are included in Appendix B. | 10 m | | | | | } |
| | Attach photographs as appropriate | | | | | |
| III. Piping/Penetrations | procession in the second se | | | | | |
| 1. Is piping intact? (Y or N) | B. Actions taken: | | | | | |
| 2. Are floor/wall penetrations sealed? (Y or N) | | | | | | |
| | | | | | | |
| If 'No' to either of the above, provide observations | | | | ,117 - 11 - 11 - 11 - 11 - 11 - 11 - 11 | | |
| and describe corrective actions taken | | | | | | |
| | C. Recommended Maintena | nce/Repairs: | | | | |
| | | | | | | |
| | | | | | | 1 |
| | | | | | | |
| | | | | | | |
| | | and a finite manufacture of the second s | | | | |
| Do any of the pressure gages require repair or replace | ement? Y | N <u>X</u> | | | | |
| If so, indicate locations, and actions taken: | | | | | | |
| | | | | | | |
| - Andreas - | an a | | | | | |
| | and any many second | | | | | |
| IV. Building Modifications: Have building modification | s been made that could affect the | he operation of the SS | D Sys | tem? (Des | scribe) | |
| | | | | | | |
| | | | | | | |
| None at this time | | | | | | |
| - w wis me | | | | | | |
| Free contraction of the contract | | | a seguri a | | Hedr | |
| Additional Comments | | | | | | |
| Additional Comments: | * | | | | | |
| Additional Comments: Condensatives trups dry | | | | | | |

٠,

| Sub Club Damas inter Sector | 5 ÷ | Date: | | 2/29 | 1202 | 0 | | | |
|--|--|---|---------|-----------|--|----|--|--|--|
| Sub-Slab Depressurization System | | | | Hai Com | | | | | |
| Inspection Checklist Syracuse Label, 110 Luther Avenue, Liverpool, NY | | Insepctors Na Company: | | SYRLSP | | | | | |
| I. Pressure Readings | II. Fan Inspection | Inspector Initi | als: | Kg | | +1 | | | |
| Suction Riser Pressure Identification Reading (inWC) | 1. Operational? | | Y | Y | N | | | | |
| S-1 <u>3,7</u> | | | F. | - | | | | | |
| s-2 <u>3</u> 5 s-3 [] | 2. Fan/Controls Clear of ob | structions? | Y * | <u></u> | N | | | | |
| S-4 6 0 | 3. Rapair needs? | | Y | | N | y | | | |
| S-5 <u>3.9</u> | | and a subscription of the | | | | | | | |
| S-6 3.6 | A. Observations/comments | | | | | | | | |
| s-7 <u>2,5</u> | | | | | | | | | |
| S-8 <u>5:0</u> | | | | | | | | | |
| s-9 <u>2,2</u> | 1. Sec. 1. Sec | | | | | | | | |
| S-10 <u>5.1</u> | | | | | | | | | |
| S-11 <u>2.4</u> | | | | | | | | | |
| S-12 2.8 | | | | | | | | | |
| S-13 (494) 3.2 | | | | | | | | | |
| S-14 2,9 | | | | | | | | | |
| Notes: | | | | | | | | | |
| Locations of suction risers can be found on attached Figure. | | | | | | | | | |
| System details are included in Appendix B. | | | | | | | | | |
| | Attach photographs as appropriate | | | | | | | | |
| III. Piping/Penetrations | | and a start of the second s | | | | | | | |
| 1. Is piping intact? (Y or N) | B. Actions taken: | Constant of Management and Andrews and A | | | | | | | |
| 2. Are floor/wall penetrations sealed? (Yor N) | | | | | | | | | |
| 2. The hoor war percentions searcate (1 or 14) | | | | | | | | | |
| If 'No' to either of the above, provide observations | | | | | | | | | |
| | | and a second | | | | - | | | |
| and describe corrective actions taken | O Decemberded Mainton | aneo/Pongire | | | and the second | | | | |
| | C. Recommended Mainten | ance/repairs. | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Do any of the pressure gages require repair or replace | ment? Y | N | | | | | | | |
| If so, indicate locations, and actions taken: | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | Constitution (Constitution of States of Constitution) | 4.4 | | | | | | |
| IV. Building Modifications: Have building modification | s been made that could affect | the operation of the | SSD Sys | stem? (De | scribe) | | | | |
| | | | | | | | | | |
| Non Land | | | | | | | | | |
| NONe at this tim | , l | | | | | | | | |
| | andre and the first of the second | | | | | | | | |
| Additional Comments: | *. | | | | | | | | |
| Cordensation traps dry | V | | | | | | | | |
| | repair needs immediately to | | | | | - | | | |

Sub-Slab Depressurization System

Inspection Checklist

Syracuse Label, 110 Luther Avenue, Liverpool, NY

| Pressure Re Buction Riser | adings Pressure |
|------------------------------|--------------------|
| dentification | Reading (inWC) |
| S-1 | 4.0 |
| S-2 | 3,5 |
| S-3 | 6.0 |
| S-4 | 5.5 |
| S-5 | 3.75 |
| S-6 | 3.5 |
| S-7 | 2.25 |
| S-8 | 4.5 |
| S-9 | 11:75 |
| S-10 | 2.75 |
| S-11 | 2.5 |
| S-12 | 2.5 |
| S-13 | 3.0 |
| S-14 | 2.5 |

Notes:

Locations of suction risers can be found on attached Figure. System details are included in Appendix B.

III. Piping/Penetrations

1. Is piping intact? (Y or (i)) - 5 - 14 2. Are floor/wall penetrations sealed? (V)or N)

If 'No' to either of the above, provide observations and describe corrective actions taken Fiser 5-14 "T" his crack. Reported to Syracuse Label

Recommended Maintenance/Repairs: "T" S-14 and Seal ball value in place. Repair pipe supports on S-1 Repair soil cover ruthing and reseed C. Recommended Maintenance/Repairs:

Date:

II. Fan Inspection

2. Fan/Controls Clear of obstructions?

wall

1. Operational?

3. Rapair needs?

B. Actions taken:

Company: Inspector Initials:

Insepctors Name:

A. Observations/comments: " stilled from snow removed operations Some soil course rulted from snow removed operations Clean out adjacent to S-10 no lequids

5-14 ball value not sealed and "T" has crack in fire

S-1 For pipe supports should be repaired - no immediate impact to system function The bive way at MW-19/SUW-4 is getting more use and the area assurate fush more use and the area assurate

3-17-20

Ν

Ν

Novanetti

52

Do any of the pressure gages require repair or replacement? If so, indicate locations, and actions taken:

IV. Building Modifications: Have building modifications been made that could affect the operation of the SSD System? (Describe) New floor covering in sections of the building (north some door ways changed to accomode te new) layout Modifications should not impact SSDS

Additional Comments:

٠,

APPENDIX H 110 LUTHER AVENUE SITE INSPECTION FORM

Inspections should be done at a minimum of once a year.

More frequent inspections may be required in accordance with approved work plans in specific areas undergoing construction, and following any construction-related work that may expose site soils or affect the operation of the SSDS.

Inspections must be completed if an incident or accident occurs that may require corrective measures (i.e. damage to the SSDS or emergency actions that require soil removal).

Inspection Data Annually Construction Data Post-Construction 110 Luther Ave Loverpool Not Location: 3-17-20 Inspection Date: Inspected By: DJVanetto

| | | Y or N | Comments or Problem Identified/Action Taken |
|----|--|--------|---|
| 1. | Condition of pavement : Are there areas of pavement where sub-soil is exposed? | N | |
| 2. | Conditions of concrete slab: Is the concrete slab of the manufacturing facility intact? Are there cracks or gaps through which underlying soil is exposed? | YY | New floor covering with vinyl |
| 3. | Sediment/Erosion Control: Are erosion/storm water control devices in place in accordance with Stormwater Pollution Prevention Plan? | NA | NA |
| 4. | Excavation/Backfill: Has Excavation been completed in accordance with the site Excavation Work Plan? | | NA |
| 5. | Stockpiled Materials : Are temporary soil stockpiles or construction materials protected from erosion? | | NA |
| 6. | Dust Control : Have dust control measures been implemented as needed during the conduct of construction work? | | NA |
| 7. | CAMP: Has Community Air Monitoring been conducted in accordance with the CAMP? | | NA |
| 8. | SSDS: Has an inspection of the SSDS been completed? | 4 | |

If current inspection is construction or post-construction, describe the nature of the construction project: Has a Work Plan been prepared and approved by NYSDEC? Y____N

NA

Attach photographs as appropriate

If the current inspection is due to an incident or accident, describe the nature of the incident/accident and the corrective measures being taken.

Note: A Corrective Measure Report will need to be submitted to the NYSDEC.

NA

Attach photographs as appropriate



Photo 1 - View of minor soil cover system damage near southwestern corner of building. Reportedly repaired by Box Capital by regrading on March 20, 2020.



Photo 2 - View of minor soil cover system damage near northwestern portion of Site. Reportedly repaired by Box Capital by regrading on March 20, 2020





Photo 3 - View of northwestern portion of Site looking west.



Photo 4 - View of southwestern portion of Site looking northwest.





Photo 5 - View of eastern portion of Site along Luther Avenue looking northeast.



Photo 6 - View of northeastern portion of Site along Knapp Street looking southeast.





Photo 7 - View of Fan 1 pipe supports that need to be repaired. Temporary repairs were made by Box Capital on March 20, 2020 (outside of this PRR's certification period) until parts for permanent repair are available.



Photo 8

 View of Fan 1 pipe supports temporary repairs made by Box Capital on March 20, 2020 (outside of this PRR's certification period).



Site Photographs



Photo 9 - View of broken "T" fitting and dislodged ball valve on SSDS suction riser S-14 leading to Fan 2. Repairs will be arranged outside of this PRR's certification period.



Photo 10 - The dislodged ball valve was able to be temporarily re-inserted until repairs can be arranged outside of this PRR's certification period.



Site Photographs



Photo 11 - View of use of room and condition of concrete floor slab engineering control in vicinity of damaged SSDS suction riser S-14.



Photo 12 - View of use of room and condition on concrete floor slab engineering control in vicinity of former MW-13 and former MW-16.






Photo 13 - View of use of warehouse portion of Site building.




Photo 14 - View of remodeled former office space portion of building and current use as lighting showroom.





Photo 15 - View of interior concrete floor slab engineering control in vicinity of former MW-11.



Photo 16 - View of typical SSDS suction point riser and magnehelic gauge.



Site Photographs

Appendix D Groundwater Sampling Waste Disposal Documentation

| | RC Americ RECYCLERS CO 177 Wales Ave., Tonawanda, NY, 14150 NYR 000 030 809 | |
|---|---|---|
| CERTIF | ICATE OF DISPO | SAL for: |
| 110 | Syracuse Label Luther Ave., Liverpool, NY 13 EPA ID # NYD042350751 | 3088 |
| MANIFEST NUMBER: 29647 | | |
| TYPE | QUANTITY | APPROVAL NUMBER |
| Well Water | 1 Drum | B-6623IN |
| THIS IS TO CERTIFY THAT THE ABOVE DESCRIBED WA SIGNED: Julian Mastropo Facility Manage | | ANCE TO FEDERAL, STATE, AND LOCAL LAWS. |

177 Wales Ave., Tonawanda, NY, 14150

NYR 000 030 809

CERTIFICATE OF DISPOSAL for:

Syracuse Label 110 Luther Ave., Liverpool, NY 13088 EPA ID # NYD042350751

MANIFEST NUMBER: 30098

<u>TYPE</u>

QUANTITY

APPROVAL NUMBER

Well Water

1 Drum

B-6623IN

THIS IS TO CERTIFY THAT THE ABOVE DESCRIBED WASTE HAS BEEN DISPOSED OF IN ACCORDANCE TO FEDERAL, STATE, AND LOCAL LAWS.

SIGNED:

Julian Mastropoll Facility Manager DATE: <u>3/19/19</u>

Appendix E Approval Notifications for EQuIS Database Submittals

Ian McNamara

| From: Sent: To: Cc: Subject: Attachments: | dec.sm.NYENVDATA <nyenvdata@dec.ny.gov> Thursday, April 18, 2019 12:38 PM Dyson Sprouse Mannes, Christopher (DEC); Ian McNamara RE: EDDs for the 110 Luther Avenue BCP Site #C734118 - 2nd Qtr 2019 GW Monitoring 20190322 1433.C734118.NYSDEC_MERGE_201904181122_Summary.html; Chemistry 20190322 1433.C734118.NYSDEC_MERGE.zip</nyenvdata@dec.ny.gov> |
|--|---|
| OperatingCentre: | 86 |
| JobNo: | 14941 |
| CompleteRepository: | 8614941 |
| RepoEmail: | 8614941@ghd.com |
| Description: | Syracuse Label Monitoring 2012 |
| RepoType: | Job |

Dyson,

The dataset containing laboratory analytical results includes errors identified by the format published in January (see attached error log generated from 20190322 1433.C734118.NYSDEC_MERGE). Please do not submit data containing errors identified by the published format without comment, as it is not technically possible for us to load such data to the NYSDEC database without revision.

That said, in the particular case of EDDs like 20190322 1433.C734118.NYSDEC_MERGE, I have (for now) the authority to make the necessary revisions to the data in order to load it to the database. When data providers choose the wrong sample_source flag for their Trip Blank, Matrix Spike, or Matrix Spike Duplicate samples, the EIMS Team has granted me permission to prepare and load revised copies of such datasets (revised copy attached). The revised data was successfully uploaded to the NYSDEC EQUIS database, and is available for use within the system.

We also successfully uploaded the 1437 EDD without any need for further revisions.

Aaron NYSDEC EIMS Team

From: Dyson.Sprouse@ghd.com <Dyson.Sprouse@ghd.com>

Sent: Friday, March 22, 2019 2:52 PM

To: dec.sm.NYENVDATA <NYENVDATA@dec.ny.gov>

Cc: Mannes, Christopher (DEC) <christopher.mannes@dec.ny.gov>; Ian McNamara <Ian.McNamara@ghd.com> **Subject:** EDDs for the 110 Luther Avenue BCP Site #C734118 - 2nd Qtr 2019 GW Monitoring

ATTENTION: This email came from an external source. Do not open attachments or click on links from unknown senders or unexpected emails.

Hello,

Attached are 2 EDDs related to 2nd quarter 2019 groundwater monitoring that was conducted at the above referenced site in March 2019. One contains field results and groundwater elevations from the wells and the other contains laboratory analytical results from the wells. Please let me know if these need any edits to be acceptable.

Ian McNamara

| From: Sent: To: Cc: Subject: | dec.sm.NYENVDATA <nyenvdata@dec.ny.gov> Friday, March 6, 2020 3:52 PM Ian McNamara Mannes, Christopher (DEC); Morrison, Douglas (DEC) RE: EDDs for the 110 Luther Avenue BCP Site #C734118 - 4th Qtr 2019 GW Monitoring</nyenvdata@dec.ny.gov> |
|---|--|
| OperatingCentre: JobNo: CompleteRepository: RepoEmail: Description: | 86 14941 8614941 8614941@ghd.com Syracuse Label Monitoring 2012 |
| ВероТуре: | Job |

Ian,

Thank you for your EDD submission. NYSDEC has successfully uploaded the data from the EDDs "20191217 1641.C734118.NYSDEC_MERGE" and "20191217 1646.C734118.NYSDEC_MERGE" to 110 Luther Ave. Site in the NYSDEC database and the data is available for use within the system.



From: Ian McNamara <lan.McNamara@ghd.com>
Sent: Tuesday, December 17, 2019 4:49 PM
To: dec.sm.NYENVDATA <NYENVDATA@dec.ny.gov>
Cc: Mannes, Christopher (DEC) <christopher.mannes@dec.ny.gov>
Subject: EDDs for the 110 Luther Avenue BCP Site #C734118 - 4th Qtr 2019 GW Monitoring

ATTENTION: This email came from an external source. Do not open attachments or click on links from unknown senders or unexpected amails

Hello,

Attached are 2 EDDs related to 4th quarter 2019 groundwater monitoring that was conducted at the above referenced site in November 2019. One contains field results and groundwater elevations from the wells and the other contains laboratory analytical results from the wells. Please let me know if these need any edits to be acceptable.

Thank you, Ian


Ian McNamara Scientist Environment

GHD


Proudly employee owned T: +315 679 5732 | M: +315 368 8432 | E: ian.mcnamara@qhd.com One Remington Park Drive Cazenovia NY 13035 USA | www.ghd.com

Appendix F Time Series Plots













Appendix F Time Series Plots Chlorinated VOCs of Concern






Appendix F Time Series Plots Chlorinated VOCs of Concern












Appendix F Time Series Plots Chlorinated VOCs of Concern































Appendix G Change of Use and/or Ownership Documentation

NOTICE OF TRANSFER OF CERTIFICATE OF COMPLETION Brownfield Cleanup Program Pursuant to 6 NYCRR Part 375-1.9(f) Site Name: 110 Luther Ave Site, Site ID No. 734118 Site Address: 110 Luther Avenue, Liverpool, NY 13088

PLEASE TAKE NOTICE, that pursuant to Article 27, title 14 of the Environmental Conservation Law and 6 NYCRR 375-1.9(f), Syracuse Label Company, Inc. hereby transfer(s) the Certificate of Completion (COC) issued by the Department of Environmental Conservation on 12/22/2011 for the site described below. Such COC was issued upon satisfaction of the Commissioner, following review by the Department of the final engineering report and data submitted pursuant to the Brownfield Cleanup Agreement, as well as any other relevant information regarding the Site, that the remediation requirements set forth in ECL Article 27, title 14 had been or would be achieved in accordance with the time frame, if any, established in the remedial work plan.

PLEASE TAKE NOTICE, that 110 Luther Ave Site is located at 110 Luther Ave, Liverpool, Onondaga County. The Site is bearing DEC site number: 734118 and is more fully described on Schedule A attached hereto ("Site"). The Tax Map Identification Number(s) for site is/are:

085-12-04.1, 085-12-05.0, 085-12-06.1, 085-12-08.0, 085-12-09.0

PLEASE TAKE NOTICE, that a Notice of Certificate of Completion for the Site was filed in the Onondaga County Clerk's Office on 1/6/2012 in Liber 5186 Of Deeds at Page 644.

PLEASE TAKE NOTICE, that on 3/27/2019 Syracuse Label Co., Inc. conveyed title to the Site to Box Capital, LLC by Deed recorded in Instrument Number 2019-00011472.

PLEASE TAKE NOTICE, Syracuse Label Company, Inc. hereby transfers the Certificate to the following new property owner(s) as provided for pursuant to Article 27, title 14 of the Environmental Conservation Law and 6 NYCRR 375-1.9(f):

Box Capital, LLC (New Property Owner)

3883 Dawes Avenue, Clinton, NY 13323 (Address)

82-3122021 (Employer Identification Number)

Representative (if applicable)

(Address)

SCHEDULE "A" PROPERTY DESCRIPTION

Address of property: 110 Luther Ave, T/O Salina, Onondaga County, New York Tax Map: 085 - 12 - 4.1, 5.0, 6.1, 8.0 and 9.0.

All that tract or parcel of land, situate in the Town of Salina, County of Onondaga and State of New York, being Lot Nos. 427 - 433,437,438 and 467 - 478, on a map of Buckley Gardens dated May 18, 1914 made by A.L. Eliot, C.E. and filed in the Onondaga County Clerk's Office May 20, 1914 as Map No. 1484.

Also, all that tract of parcel of land, situate in the Town of Salina, County of Onondaga and State of New York, being part of Farm Lot 135 in said Town, being part of Buckley Gardens according to a map dated May 18, 1914, filed in the Onondaga County Clerk's Office May 20, 1914 as Map No. 1484, being part of Albion Avenue, formerly, according to said Buckley Gardens map, being a strip of land beginning at the intersection of the most northerly corner of Lot 468 Buckley Gardens with the southeasterly street boundary of Albion Avenue; thence N 43°59'30" W Deed, a distance of40.0 feet to a point; thence S 46°00'30" W Deed, distance of 60.0 feet to a point; thence S 43°59'30" E Deed, a distance of40.0 feet to a point; thence N 46°00'30" E Deed, a distance of 60.0 feet to the point and place of beginning. Intending to describe a strip of land conveyed to Syracuse Label Company, Inc. by deed recorded in Book 3972 of Deeds at page 48 & c. in the Onondaga County Clerk's Office.

Excepting and reserving a right of way over the above described parcel to and over the existing pavement of Albion Avenue for purpose of ingress and egress. Being a strip of land that is 15.0 feet in width and 60.0 feet in length.

The above described parcels of land are more particularly and correctly described together as follows:

All that tract or parcel of land situate in the Town of Salina, County of Onondaga and State of New York, being part of Buckley Gardens according to a map of said tract made by A.L. Eliot, C.E. dated May 18, 1914 and filed in the Onondaga County Clerk's Office May 20, 1914 as Map No. 1484, bounded and described as follows:

Beginning at the intersection of the southwesterly boundary of Knapp Street with the northwesterly boundary of Luther Avenue; running thence S 46°00'30" W, along said northwesterly boundary of Luther Avenue, a distance of 220.00 feet to a point therein, said point being the most southerly corner of Lot No. 433 in said Buckley Gardens; thence 43°36' 17" W, along the southwesterly boundary of said Lot No. 433, a distance of 90.00 feet to the most westerly corner thereof; thence S 46°00'30" W, along the southeasterly boundaries of Lot Nos. 471,470 and 469, respectively, a distance of 90.00 feet to the most northerly comer of Lot No. 437 in Buckley Gardens; thence S 43°36' 17" E, along the northeasterly boundary of said Lot No. 437, a distance of 90.00 feet to the most easterly corner thereof, said point being in the aforementioned northwesterly boundary of Luther Avenue; thence S 46°00'30" W, along said northwesterly boundary of Luther Avenue, a distance of 60.00 feet to the most southerly corner of Lot No. 438; thence N 43°36' 17" W, along the southwesterly boundaries of Lot Nos. 438 and 467, respectively, and its northwesterly prolongation, a distance of 220.00 feet to a point in the southeasterly boundary of Interstate Route No. 81; thence N 46°00'30" E, along said southwesterly boundary of Interstate Route No. 81, a distance of 60.00 feet to a point therein, said point being on the northwesterly prolongation of the northeasterly boundary of Lot No. 468;

thence S 43°36'17" E, along said northwesterly prolongation of said northeasterly boundary of Lot No. 468, a distance of 40.00 feet to the most northerly comer of said Lot No. 468, said point being in the southeasterly boundary of said Albion Avenue; thence N 46°00'30" E, along said southeasterly boundary of Albion Avenue, a distance an 310.00 feet to the intersection of the aforementioned southwesterly boundary of Knapp Street with said southeasterly boundary of Albion Avenue; thence S 43°36' 17" E, along said southwesterly boundary of Knapp Street, a distance of 180.00 feet to the point of beginning.

PLEASE TAKE FURTHER NOTICE, that if there is an environmental easement for this site, that Box Capital, LLC recognize(s) and agree(s) to implement the Department-approved Site Management Plan, and any amendments thereto, and to fully comply with all restrictions and affirmative obligations contained therein as well as in the Environmental Easement for the Site.

WHEREFORE, the undersigned have signed this Notice of Transfer of Certificate of Completion as of this $\underline{40}$ of April, 2019.

Syracuse Label Company, Inc.

ByKathleen alaimo

Sworn to before me this $4^{1/2}$ of April, 2019.

(notary signature) Jame Williers

LAURA WILLIAMS NOTARY PUBLIC, STATE OF NEW YORK Registration No. 01 WI6348303 Qualified in Onondaga County Commission Expires September 26, 2020

Box Capital, LLC

By anthony arincione

Sworn to before me this ______ of April, 2019.

una Williams (notary signature)

LAURA WILLIAMS NOTARY PUBLIC, STATE OF NEW YORK Registration No. 01W16348303 Qualified in Onondaga County Commission Expires September 26, 2020 **PLEASE TAKE FURTHER NOTICE,** that if there is an environmental easement for this site, that Box Capital, LLC recognize(s) and agree(s) to implement the Department-approved Site Management Plan, and any amendments thereto, and to fully comply with all restrictions and affirmative obligations contained therein as well as in the Environmental Easement for the Site.

WHEREFORE, the undersigned have signed this Notice of Transfer of Certificate of Completion as of this 4% of April, 2019.

Syracuse Label Company, Inc.

ByKathleen alaimo

Sworn to before me this 4^{+1} of April, 2019.

(notary signature) Jame Williams

STATE OF NEW YORK COUNTY OF ONONDAGA

On the $\underline{4}$ day of \underline{A} or $\underline{1}$, 2019 before me, the undersigned, a notary public in and for said state, personally appeared \underline{K} and \underline{K} before me, the undersigned, a notary public in and for said to me on the basis of satisfactory evidence, to be the individuals whose names are subscribed to the within instrument and acknowledged to me that they executed the same in their capacities, and that by their signatures on the instrument, the individuals or the persons upon behaling which the individuals acted, executed the instrument.

NOTARY PUBLIC

NOTARY FUBLIC, STATE OF NEW YORK Registration No. 01W16348303 Qualified in Onondaga County Commission Expires September 26, 2020

By Conthony Currincione

Sworn to before me this ______ of April, 2019.


(notary signature) Aura Williams

STATE OF NEW YORK COUNTY OF ONONDAGA

On the \mathcal{L} day of \mathcal{L} , 2019 before me, the undersigned, a notary public in and for said state, personally appeared \mathcal{L} , 2019 before me, the undersigned, a notary public in and for said to me on the basis of satisfactory evidence, to be the individuals whose names are subscribed to the within instrument and acknowledged to me that they executed the same in their capacities, and that by their signatures on the instrument, the individuals or the persons upon behalf of which the individuals acted, executed the instrument.

TARY PUBLIC

LAURA WILLIAMS NOTARY PUBLIC, STATE OF NEW YORK Registration No. 01W16348303 Qualified in Onondaga County Commission Expires September 26, 2020



Lisa Dell, County Clerk 401 Montgomery Street Room 200 Syracuse, NY 13202 (315) 435-2229

Onondaga County Clerk Recording Cover Sheet

Received From : SYRACUSE LABEL & SURROUND PRINTING 200 STEWART DR N SYRACUSE, NY 13212

Return To: SYRACUSE LABEL & SURROUND PRINTING 200 STEWART DR N SYRACUSE, NY 13212

First PARTY 1

SYRACUSE LABEL COMPANY INC

First PARTY 2 BOX CAPITAL LLC

Index Type : Land Records Instr Number : 2019-00012966 Book: Page : Type of Instrument : Certificate Type of Transaction : Deed Misc Wo Tp584 **Recording Fee:** \$76.00 7 of Onondaga, New York **Recording Pages :**

The Property affected by this instrument is situated in Salina, in the County

Recorded Information

State of New York

County of Onondaga

I hereby certify that the within and foregoing was recorded in the Clerk's office for Onondaga County, New York

via Deel

On (Recorded Date) : 04/09/2019

At (Recorded Time) : 12:13:23 PM

Doc ID - 034892970007

Lisa Deli, County Clerk





about GHD

GHD is one of the world's leading professional services companies operating in the global markets of water, energy and resources, environment, property and buildings, and transportation. We provide engineering, environmental, and construction services to private and public sector clients.

Damian Vanetti, P.E. damian.vanetti@ghd.com 315.802.0340

lan McNamara ian.mcnamara@ghd.com 315.802.0312

www.ghd.com