

**New York State Department of Environmental Conservation  
Waste Tire Stockpile Assessment Summary Sheet - Site 5-23**

## **East Side Auto Village of Hudson Falls**

**Region 5, Washington County**

**Site Setup:**

**Site of an operating automobile junkyard. Tire piles located adjacent to the road on the south side. The junkyard is located on the north side of the road. Site is located adjacent to residential areas and less than 1/4 mile from 2 schools.**



**Number of tire piles: 2 piles 15 feet apart**

**Dimensions of tire piles:**

**34'W X 120'L X 7'H and  
29'W X 120'L X 10'H**



**Number of Tires: 12,000 estimated**

**Condition of Tires:**

**Mostly passenger car tires. Two piles are segregated from other waste/debris.**

**Access:**

**Somewhat dilapidated fence with open gate. Tire piles are visible from road (approx 40 feet off road). Grassy field.**



**Concerns: Vectors, Fire, Aesthetics, Schools**