

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 6-09**

**Clark Property
(Formerly Davis Property)
Town of Morristown**

Region 6, St. Lawrence County

Site Setup:

The property is located on a town road. Site is flat and wet and mostly brush. Driveway is graveled near the road intersection and stable. The rest is grass.

Entire site is a brush lot with trails kept open for hunting access. Tires are 150 to 350 feet off the road. A couple of small scrap piles are on site and the tire piles are separated by 100 to 150 feet.

Number of tires: 3,000 estimated.

One large pile of 2,000 tires plus 3 small piles with volume ranging from 200 to 500 tires.

Condition of tires:

All relatively clean whole tires. 15% to 20 % of tires are on rims.

Access to Site:

There is only a grassy farm road to the tires. It would need to be improved prior to attempting to remove the tires. Vehicle access would not be difficult but could damage the property during the wetter seasons.

Concerns: Fire and vectors

