

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 9-12**

**Route 20 Auto Parts
Town of Angola**

Region 9, Erie County

Site Setup:

This site is an operating junkyard in a rural residential setting. There is fencing around most of the site with encroaching vegetation. There was a fire in one of the piles.

The owner purchased the facility about seven years ago with the tires already on site and has been steadily reducing the number of tires on the property.

Number of tires: 39,000 estimated

Condition of tires:

The tires are in 10 separate piles scattered around the yard ranging from 300 to 11,000 tires. Some of the tires are mixed with other scrap. Many have rims and are dirty. One or two of the piles also contains burned tires from a fire in 2001.

Access to Site:

Access is via the front gate to perimeter roads around the yard. The roads through the yard are narrow and may require moving auto bodies and other debris to access the tires.

Concerns: Vectors and fire

