Project: Spe Contractor: Env CDM Job No: D-0	CDM 100 Crossways Park Wes Woodbury, NY 11797							
CDM Project Manager: Joh	n Blau	DAILY RE	PORT		•	Telep		6.496.8400 6.496.8864
Day: S	МТ	W TH F S	WEATHER	Clear	Partly Cloudy	Overcast Drizzle	Rain	Snow
Date:		2-Apr-09	TEMP L/H		45/59			
REPORT No.		113	HUMIDITY	Dry	Moderate	High		
PAGE No.		1	WIND	Calm	Light	Moderate	High	
PREPARED BY: F.Ro	obinso	r TITLE: Inspector	WIND DIR	N NE	E SE	S SW	NW	
AVERAGE FIELD FORC		<u>mopootor</u>			02			
Name of Contractor			Hours Worked		Remarks			
EnviroTrac	Construction Manager		2x8 hrs		J.Szymanski, M.Rose			
EnviroTrac EnviroTrac	Operator Technician		2x8 hrs 2x8 hrs		B.Byrnes, B.Gimbel R.Maletta, K.Davies			
Environac			ZAO 1113			· ····································		
EQUIPMENT AT THE SI 20" Storage Container - W Case CX130 Excavator - W Case 621D Front End Loader - W Daewoo 450 skidder - W	ITE	I = Idle W	/ = Working					
HEALTH AND SAFETY Name	Ti	me (From - To)			Task/Le	vel of PPE		
		,	All workers onsite were in modified level D-PPE (tyvek and booties)				ooties)	
CONSTRUCTION ACTIV								
Site Representative: Frank   Health and Safety Site Office								
leanth and Salety Site Office	CI. IN	//\						
	DES	SCRIPTION OF W	ORK PERFOR	RMED A	ND OBSER	VED		
-Tailgate H&S meeting performed nonitoring for dust and VOC's was			•					2-Air
3-Continued to excavate the green of just the top 1' east foundation was				emoved 2	7' of the whole	east foundation w	all and an	additional 18
-The rest of the visibly contamina	ted soi	and concrete foundat	tion wall in the NE	corner s	hould be remo	ved tomorrow.		

x - Designates report is continued on additional pages

Project Manager: John Blaum

CDM Site Representative: F. Robinson

## PHOTOGRAPHIC LOG

## 2-Apr-09

## **CDM Job No. D-006956**

## **Spectrum Finishing Remedial Action**

## SITE No. 1-52-029

РНОТО	DATE	TIME	DESCRIPTION			
100_00314.jpg	4/2/2009	AM	Green contaminated concrete on east foundation wall, looking east			
100_00315.jpg	4/2/2009	AM	Green contaminated soil/chunks taken from the NE corner			
100_00316.jpg	4/2/2009	AM	Pile of contaminated soil/chunks taken from the NE corner			
100_00318.jpg	4/2/2009	PM	Excavation at the end of the day, looking north			
100_00320.jpg	4/2/2009	PM	Excavation at the end of the day, looking SE			
100_00321.jpg	4/2/2009	PM	Mt. Spectrum at the end of the day			

# PHOTOS 4/02/09



100\_00314.jpg - Green contaminated concrete on east foundation wall, looking east



100\_00315.jpg - Green contaminated soil/chunks taken from the NE corner



100\_00316.jpg - Pile of green contaminated soil/chunks taken from the NE corner




100\_00318.jpg - Excavation at the end of the day, looking north



100\_00320.jpg - Excavation at the end of the day looking SE



100\_00321.jpg - Mt. Spectrum at the end of the day.



CLIENT PROJECT Spectrum

DETAIL Sample Location COMPUTED BY CHECKED BY XSES-2 X SEB-5 40 Dale St. X SEB-4 X SEB-4 X SES-3 × SEB-3

Notes

1 square = 2'
SES = Sump Executation Sidewall Sample Location
SEB = Sump Executation Bottom Sample Location.

....