Contractor: En	roject: Spectrum Finishing - Remedial Action actor: EnviroTrac Environmental Services ab No: D-006956 Site No. 1-52-029 agger: John Blaum DAILY REPORT				CDM 100 Crossways Park Wes Woodbury, NY 11797 Telephone: 516.496.8400 Fax: 516.496.8864				
Day: S	M T W TH F S	WEATHER	Clear	Partly Cloudy	Overcast	Rain	Snow		
Date:	23-Apr-09	TEMP L/H		42/58					
REPORT No.	128	HUMIDITY	Dry	Moderate	High				
PAGE No.	1	WIND	Calm	Light	Moderate	High			
PREPARED BY: F.R	WIND DIR	N NE	E SE	S SW	W NW				
	 CE								
Name of Contractor			Hours Worked		Remarks				
EnviroTrac	Construction Manager	2x8 hrs		M.Rose, J.Szymanski					
EnviroTrac	Operator	2x8 hrs		B.Gimbel, J. Byrnes R.Maletta, K.Davies					
EnviroTrac	Technician	2x8 hrs		R.ivialetta, K.Davies					
EQUIPMENT AT THE S	ITE I = Idle W	/ = Working							
20" Storage Container - W Case CX130 Excavator - W									
Case 621D Front End Loader - W									
Daewoo 450 skidder - W									
Stow Cutter 3 Concrete Saw - W									
HEALTH AND SAFETY Name	Time (From - To)			Tack/Lo	vol of PDE				
Name	Time (From - 10)	Task/Level of PPE All workers onsite were in level D-PPE							
CONSTRUCTION ACTI	VITIES	1							
Site Representative: Frank	Robinson - CDM								
lealth and Safety Site Office	cer: N/A								
	DESCRIPTION OF W	ORK PERFOR	MFD A	ND OBSER	VFD				
-Tailgate H&S meeting performed				020211					
2-EnviroTrac finished backfilling ar			٠.						
3-EnviroTrac trimmed the perimeter	er of the concrete slab with a	walk behind conc	rete saw.						
	x	- Designates re	eport is	continued or	n additional pag	ges			

Project Manager: John Blaum

CDM Site Representative: F. Robinson

PHOTOGRAPHIC LOG

23-Apr-09

CDM Job No. D-006956

Spectrum Finishing Remedial Action

SITE No. 1-52-029

РНОТО	DATE	TIME	DESCRIPTION	
100_00455.jpg	4/23/2009	AM	Saw cutting concrete slab	
100_00456.jpg	4/23/2009	PM	Finished saw cutting north side of concrete slab	
100_00457.jpg	4/23/2009	PM	Finished saw cutting south side of concrete slab	
100_00458.jpg	4/23/2009	PM	Finished saw cutting west side of concrete slab	
100_00459.jpg	4/23/2009	PM	Excavation at the end of the day, looking east	
100_00460.jpg	4/23/2009	PM	Excavation at the end of the day, looking west	

PHOTOS 4/23/09



100_00455.jpg - Saw cutting concrete slab



100_00456.jpg - Finished saw cutting north side of concrete slab



100_00457.jpg - Finished saw cutting south side of concrete slab



100_00458.jpg - Finished saw cutting west side of concrete slab



100_00459.jpg - Excavation at the end of the day, looking east



100_00460.jpg - Excavation at the end of the day, looking west

