

December 22, 2023

Mr. Justin Starr Project Manager New York State Department of Environmental Conservation 625 Broadway Albany, New York 12233-7014

Subject: 2023 Annual Site Inspection Report RG&E Pavilion Former MGP Site 6903 Ellicott Street Road Town of Pavilion, Genesee County, New York 14525 NYSDEC Site No. 819024

Dear Mr. Starr:

On behalf of the Rochester Gas & Electric Corporation (RG&E), NEU-VELLE LLC (NEU-VELLE) has completed the fourth post-remediation annual Site Inspection of the RG&E Pavilion Former Manufactured Gas Plant (MGP) site [New York State Department of Environmental Conservation (NYSDEC) Site No. 819024], located at 6903 Ellicott Street Road in the Town of Pavilion, Genesee County, New York (referred to herein as the "Site"). A Site Management Plan (SMP) for the Site has been completed and approved by NYSDEC and is currently pending final signatures of remedial parties.

NEU-VELLE performed a visual inspection of the Site, including an evaluation of the surface cover system for evidence of disturbance, erosion or removal of cover materials, settlement, or other conditions that could potentially result in exposure to subsurface MGP residuals. Photographs were collected during this October 5, 2023 Site Inspection. The existing cover materials at the Site were observed to be in good condition, and there were no noticeable signs of significant deterioration of the surface cover. Additionally, the existing groundwater monitoring well network, comprised of five (5) wells finished with "stick-up" protective steel casings, was observed to be in good condition. Documentation of NEU-VELLE's inspection is provided as **Attachment A** of this letter report. Please feel free to contact me at (585) 478-3167 with any questions or concerns.

Sincerely,

ogan Klu

NEU-VELLE, LLC

Attachment A – Site Inspection Form and Photographs

cc: Mr. Jeremy Wolf, Avangrid



Attachment A



SITE-WIDE INSPECTION FORM

RG&E Pavilion Former MGP Site

| Date: 10/05/2023 | Time: | 13:00 | |
|--|------------------------|--------|---------|
| Weather Conditions: Sunny | | | _ |
| Temperature: $\pm 80^{\circ}$ F | Precipitation: | None | |
| Personnel and Company: Kyle R. | Miller, Neu-Velle, LLC | | |
| Signatures: | zRAM | | |
| | | | |
| Has ownership of the property changed since the last inspection? | | Yes No | |
| | | | |
| Are Institutional Controls/Engineering Controls (IC/ECs) in place and effective? | | | Yes/No |
| If not, explain why. | | | - |
| | | | |
| Are there any changes to the Site use that would affect the SMP or IC/ECs? | | Yes No | |
| | | | |
| Is the Site used for vegetable gardens or ag | ricultural purposes? | | Yes /No |
| | | | |



Is native soil, the geotextile fabric demarcation layer, or other signs of MGP impact (sheens, staining, tar-like material) visible?

 \sim

| | Yes /No |
|--|-----------|
| Is the site cover intact (i.e., no visible sign of excavations, erosion, damage)? | (Ye) / No |
| Is the site cover intact (i.e., no visible sign of excavations, erosion, damage): | 103/100 |
| Is groundwater used as a potable water source? | Yes /(No) |
| | |
| Are there any site changes (either surface or subsurface) since the last inspection event? | Yes / No |
| Photographs taken? | Yes / No |
| Photos Attached | |
| Are there any fencing changes since the last inspection event? | Yes /No |
| | |

Page 2 of 2



Training Building and Solar Panels on the Northeastern Portion of the Site -Viewing North



Gas Regulator Building and the Central Portion of the Site - Viewing Southeast



Western Portion of the Site - Viewing North



Office Building and Western Portion of the Site - Viewing South



Southern Portion of the Site - Viewing East



Central Portion of the Site - Viewing East



Eastern Portion of the Site – Viewing North



Gas Regulator Building and the Central Portion of the Site - Viewing Northwest