

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

B

Site Name: Erdle Perforating Class: 2 Number: 828072

O&M Funding Source: State Superfund Federal Superfund Municipal Responsible Party

O&M Information: O&M Start: 1997 End: — Annual Cost: \$ Estimated

Interim Remedial Measures/Operable Units in O&M Phase:

Drum Removal Soil Removal Tank Removal
 Cap/Cover Containment Structure Fence/Security
 Groundwater Recovery/Treatment Leachate Collection/Treatment Vapor Extraction/Treatment
 Air Sparging/Stripper System Treatment/Filtration Plant/System Potable Water Supply/System

Other: Dual Phase Vapor Extraction

Institutional Controls: Deed Restriction Discharge Permit Department of Health Sampling
 Other:

O&M Review Information:

Reports: _____

Inspection: See attached inspection sheet

Sampling: _____

Other: _____

Conclusions:

Remedy Effective? Yes No: IRM only - currently off

ROD Compliance? Yes No: N/A

Consent Order Compliance? Yes No: _____

Other: _____

Recommendations: RI fieldwork continuing. IRM has been off for several months.
Recommend complete RI & determine final remedy

ROD/Consent Order Modifications? No Yes (per above) Reclassify the Site? No Yes → Class:

Comments: _____

<p>Project Manager: <u>[Signature]</u> <u>2/9/01</u></p> <p>Signature Date</p> <p><u>DAVID G PRATT</u> <u>Reg. 8</u> <u>716 226 5355</u></p> <p>Name Region or Bureau Telephone</p>	<p>Reviewer: <u>[Signature]</u> <u>2/12/01</u></p> <p>Signature Date</p> <p><u>MaryJane Peachey/R-8</u> <u>716 226 5349</u></p> <p>Name Region or Bureau Telephone</p>
---	--

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION
INSPECTOR'S DAILY REPORT

EMUA

Site Code No. 828072
Site Name: EROLE PERFORATING
Location: GATES (S) NANTON (S)
Engineer: URS / RADIAN
Contractor: NOTHABLE DRIVING
Job Phone: ()

Date 12/19/00 I.R. No. 1
Sheet 1 of 1

	AM	PM
Weather	<u>Sunny</u>	
Temperature	<u>19</u>	<u>29</u>
Wind (Dir. & Vel.)	<u>0.5 mph</u>	

Health & Safety:

Level of protective clothing used: LEVEL D
Is the level of protection in conformance with the approved Health & Safety Plan?
Yes No If no, list the deviations under Items of Concern.
Are atmospheric monitoring results at acceptable levels? Yes No
Attach a copy of the monitoring log. ODM

Description of work performed during this report period:

1330 - R Long - SITE
SITE IS AN ACTIVE INDUSTRIAL COMPLEX
THE DUAL PHASE VAPOUR EXTRACTION SYSTEM IS NOT OPERATING
EQUIPMENT AND PIPING ARE IN PLACE AND FUNCTIONAL
THERE IS NO FENCING OR SIGNS ON THE SITE
MONITORING WELLS / PIEZOMETERS ARE LABELLED AND LOCKED
URS IS ON SITE WITH NOTHABLE DRIVING TO INSTALL ADDITIONAL
PIEZOMETER CLUSTERS ON THE SOUTH SIDE OF THE RR TRACKS.
EXISTING MONITORING WELLS ARE BEING PUMPED AND SAMPLES
PURGED WATER IS STORED ON SITE AND WILL BE TREATED.
SURFACE / SUBSURFACE SOIL SAMPLES ARE BEING COLLECTED AND
SUBMITTED FOR ANALYSIS.

Site Visitors KEITH DODRILL Representing URS / RADIAN Entered exclusion zone ---