## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

13/9/02 13/9/02

## Inactive Hazardous Waste Site Operations and Maintenance Review Report

	<del></del> -		Form Date 96.10.01
Site Name: Erdle Perforating	Class:	2	Number: 828072
O&M Funding Source:   State Superfun	d   Federal Superfund	☐ Municipal	X Responsible Party
O&M Information: O&M Start: 7/97	End:	Annual Cost:	\$ 🗆 Estimated
Interim Remedial Measures/Operable Units in O&M Phase:			
☐ Drum Removal ☐ S	Soil Removal	☐ Tank Re	emoval
☐ Cap/Cover ☐ C	Containment Structure	□ Fence/S	Security
☐ Groundwater Recovery/Treatment ☐ L	eachate Collection/Treatment	□ Vapor E	xtraction/Treatment
☐ Air Sparging/Stripper System ☐ T	reatment/Filtration Plant/System	□ Potable	Water Supply/System
X Other: Dual phase vapor extraction system	m		
Institutional Controls:   Deed Restriction	X Discharge Permit	□ Depa	rtment of Health Sampling
□ Other:	(to local POTW)		
O&M Review Information:			
Reports:11/02 - Additional Well Installation work plan			
Lacostica CO/20/20 City is the Double De-			
Inspection: 08/22/02 - Site visit by David Pra Sampling:			
Other:			
Conclusions:			
	tonoratina		
Remedy Effective?   Yes X No: No: No:	t operating	-	
ROD Compliance? ☐ Yes ☐ No:N/	A		
Consent Order Compliance? X Yes  No:			
Other:			
Recommendations: Erdle will be installing as results.	dditional off-site wells. Recomm	end installing t	he wells and reviewing the
<del></del>			
ROD/Consent Order Modifications? X No D	Yes (per above) Reclassify th	e Site? X No	Yes → Class:
Comments: Dual Phase System is NOT in operation. Erdle is waiting for final results of remedial investigation in			
order to proceed with final remedy.			
<del>_</del>			
Project Manager:	Reviewed:	usin	11-25-02
Signature / David Pratt, P.E. Region 8 585/22	26-5355 Bartholomew P	utzia P.E. E	Date Region 8 595/226-5349
Name Region or Bureau Teleph		Region or Bure	