NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

	Form Date 96.10.0
Site Name: Erdle Perforating	Class: 2 Number: 828072
O&M Funding Source: □ State Superfund □ Fede	ral Superfund ☐ Municipal X Responsible Party
O&M Information: O&M Start: 7/97 End	Annual Cost: \$ ☐ Estimated
Interim Remedial Measures/Operable Units in O&M Phase: □ Drum Removal □ Cap/Cover □ Containment □ Groundwater Recovery/Treatment □ Air Sparging/Stripper System □ Treatment/Fill X Other: Dual phase vapor extraction system Institutional Controls: □ Deed Restriction X Description	□ Tank Removal Structure □ Fence/Security ection/Treatment □ Vapor Extraction/Treatment ration Plant/System □ Potable Water Supply/System ischarge Permit □ Department of Health Sampling local POTW)
Inspection: Multiple site visits by David Pratt in 2003 Sampling: Other: Conclusions:	
Remedy Effective?	
Not operating	
ROD Compliance? Yes No: N/A	
Consent Order Compliance? X Yes □ No: albeit slowly and begrudgingly.	
Other:	
Recommendations: Erdle will be installing additional off-site wells and performing subslab vapor sampling. Recommend performing this work and reviewing the results. ROD/Consent Order Modifications? X No □ Yes (per above) Reclassify the Site? X No □ Yes → Class: Comments: Dual Phase System is NOT in operation. Erdle is waiting for final results of remedial investigation in order to proceed with final remedy.	
Project Manager: Signature David Pratt, P.E. Region 8 Name Region or Bureau Telephone Reviewer: Signature Signature Signature Date Bartholomew Putzig, P.E. Region 8 Name Region or Bureau Telephone Name Region or Bureau Telephone	