

Daily Activity Report

Seton Brilla Charter School 1956 Jerome Avenue, Bronx, NY

BCP No. C203152

General Si	te Informati	on
------------	--------------	----

Date: Monday, June 26, 2023
Weather: Rainy 69-81°
Wind Direction/Speed: N @ 4 mph
AKRF Personnel on Site: Lucas Belangia

AKRF Equipment on Site:

Mini RAE 3000 Photoionization Detector [(PID) x1], Roving SidePak Particulate Monitor (1), 2 Fixed Air Monitoring Stations [DustTrak Aerosol Monitors (x2) & MiniRAE 3000 PIDs (x2)].

Visitors: None

Contractor Information					
Contracting Company	Main Personnel	Equipment			
Casino Construction	Carlos	Excavator and a mini-excavator			

Description and Location of Work Activities Performed

- 1)Concrete pouring took place over pile caps in WC-01 and in WC-03.
- 2) Minor excavation in grid WC-02.
- 3) Formwork work in grid WC-04 and WC-03.

Destination Facility	Daily Trucks	Total Trucks	Daily Approx. Cubic Yds	Total Approx. Cubic Yds	Total Site Loads	Total Approximate Cubic Yards
Clean Earth Carteret	0	108	0	2,160		4,380
Clean Earth Southeastern Pennsylvania	0	80	0	1,600		
Clean Earth Bethlehem	0	31	0	620	219	
Concrete Disposal	0	27	0	540		
N/A	0	0	0	0		

CAMP Air Monitoring Results

CAMP Station	UPWIND			DOWNWIND		
Odors:	None	Number of Exceedances	Time of Exceedance(s)	None	Number of Exceedances	Time of Exceedance(s)
VOC Action Level Exceedance(s):	None			None		
Particulate Action Level Exceedance(s):	None			None		
Maximum VOC Level (15 min ppm):	N/A			N/A		
Maximum Particulate Level (15 min mg/m³):	N/A			N/A		

Notes: CAMP monitoring was not performed due to heaavy precipitation throughout the day. No odors related to site activities were noted throughout the day, and no visible dust was observed near the Site boundaries.


Additional Information

Planned Work Activity for Following Day/Week:

Install monitoring wells
 SSDS and SVE installation.

3) Grading gas permeable aggregate for SSDS installation.

Comments:



Site Photographs Photograph 1 - Site condition. Concrete pouring in grid WC-03. View facing Northeast. Photograph 2 -Pilecap concrete pouring in grid WC-01. View facing East. Photograph 3 -Concrete pouring in grid WC-03. View facing Southeast.