

Project	Bedford Beverly Brownfield	Report No.	9
	Site		
BCP Site	BCP Site No. C224384	Date	10/17/2023
Location	2359 and 2360 Bedford	File No.	0205432
	Avenue, Brooklyn, NY		
Client	Bedford Beverly Acquisitions	Temperature	50-64 °F
	LLC, Star Demolition (Star),		
	Maman Contracting (Maman)		
Contractor	Haley & Aldrich	Wind Direction	N to S, 14 mph
Weather	Mostly Sunny	Personnel on	D. Djombalic
		Site	
Humidity	78%	Time on Site	7:00am to 2:30pm

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich currently under review by NYSDEC and the NYSDEC-approved Change of Use dated 17 August 2023 to begin support of excavation work. Site observations are summarized below.

Daily Observations:

- Haley & Aldrich field personnel mobilized and set up two Aeroqual AQS1 series air quality monitors at the Site to perform community air monitoring.
- Contractor (Star) continued demolition of the former building on Lot 53 and stockpiled demolition debris for disposal.

Waste Disposal/Backfill Import Tracking:

Material Export:

- No soil was transported off-site.
- o C&D disposal is summarized below:

	Facility:	Flushing			
	Asphalt R	Recycling,			
	Flushi	ng NY			
	(Asp.	halt)	Totals:		
Today:	0 Loads 0 CY		0 Loads	0 CY	
<u>Total:</u>	31 Loads	620 CY	31 Loads	620 CY	

Material Import:

No material was imported to the Site.

Samples Collected:

No samples were collected.



CAMP Activities:

Air monitoring during ground-intrusive activities was performed at three locations during
ground intrusive work from 8:30 am to 2:15 pm. No 15-minute average concentration of
volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter
smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was
observed leaving the site perimeter.

Activities Planned for Coming Week:

- Contractor (Star) will continue demolition of the former building on Lot 53.
- Contractor (Maman) will continue stripping asphalt on both lots and stockpile throughout the Site for disposal.



Site Photographs:



Photo 1: View of demolition work, facing north.





Photo 2: View of contractor stockpiling C&D debris, facing east-northeast.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2023-10-17

Personnel : D. Djombalic

Weather : Mostly Sunny

Humidity: 78%

Wind Direction : N to S, 14 mph

Particulate Background (mg/m3): 0.003

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (mg/m3): > 0.15 for the 15-min average

	ute of ime	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
08	3:30	0.007		0.003		0.0		0.0			
08	3:45	0.006		0.003		0.0		0.0			
09	9:00	0.006		0.002		0.0		0.0			
09	9:15	0.005		0.002		0.0		0.0			
09	9:30	0.004		0.002		0.0		0.0			
09	9:45	0.006		0.002		0.0		0.0			
10	0:00	0.004		0.002		0.0		0.0			
10):15	0.006		0.002		0.0		0.0			
10):30	0.003		0.002		0.0		0.0			
10):45	0.007		0.003		0.0		0.0			

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	0.004		0.002		0.0		0.0			
11:15	0.006		0.002		0.0		0.0			
11:30	0.003		0.002		0.0		0.0			
11:45	0.005		0.002		0.0		0.0			
12:00	0.003		0.002		0.0		0.0			
12:15	0.002		0.002		0.0		0.0			
12:30	0.002		0.002		0.0		0.0			
12:45	0.004		0.002		0.0		0.0			
13:00	0.004		0.002		0.0		0.0			
13:15	0.009		0.002		0.0		0.0			
13:30	0.013		0.003		0.0		0.0			
13:45	0.011		0.003		0.0		0.0			
14:00	0.008		0.002		0.0		0.0			
14:15	0.003		0.002		0.0		0.0			