

Project	Bedford Beverly Brownfield	Report No.	10	
	Site			
BCP Site	BCP Site No. C224384	Date	10/18/2023	
Location	2359 and 2360 Bedford	File No.	0205432	
	Avenue, Brooklyn, NY			
Client	Bedford Beverly Acquisitions	Temperature	51-65 °F	
	LLC, Star Demolition (Star),			
	Maman Contracting (Maman)			
Contractor	Haley & Aldrich	Wind Direction	N to S, 10 mph	
Weather	Mostly Cloudy	Personnel on	D. Djombalic	
		Site		
Humidity	84%	Time on Site	6:45am to 2:30pm	

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich currently under review by NYSDEC and the NYSDEC-approved Change of Use dated 17 August 2023 to begin support of excavation work. Site observations are summarized below.

Daily Observations:

- Haley & Aldrich field personnel mobilized and set up two Aeroqual AQS1 series air quality monitors at the Site to perform community air monitoring.
- Contractor (Star) continued demolition of the former building on Lot 53 and stockpiled demolition debris for disposal.

Waste Disposal/Backfill Import Tracking:

Material Export:

- No soil was transported off-site.
- o C&D disposal is summarized below:

	Facility:	Flushing			
	Asphalt R	Recycling,			
	Flushi	ng NY			
	(Asp.	halt)	Totals:		
Today:	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	31 Loads	620 CY	31 Loads	620 CY	

Material Import:

No material was imported to the Site.

Samples Collected:

No samples were collected.



CAMP Activities:

 Air monitoring during ground-intrusive activities was performed at two locations during ground intrusive work from 8:00 am to 2:15 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities Planned for Coming Week:

- Contractor (Star) will continue demolition of the former building on Lot 53.
- Contractor (Maman) will continue stripping asphalt on both lots and stockpile throughout the Site for disposal.



Site Photographs:





Photo 1: View of demolition work, facing northwest.



Photo 2: View of demolition work, facing northwest.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2023-10-18

 Personnel :
 D. Djombalic

 Weather :
 Mostly Cloudy

 Humidity :
 84%

Wind Direction: N to S, 10 mph

Particulate Background (mg/m3): 0.008

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (mg/m3): > 0.15 for the 15-min average

Minute Time		Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
08:00	0.008		0.008		0.0		0.0			
08:15	0.006		0.005		0.0		0.0			
08:30	0.008		0.005		0.0		0.0			
08:45	0.006		0.005		0.1		0.1			
09:00	0.005		0.005		0.0		0.0			
09:15	0.005		0.005		0.0		0.0			
09:30	0.006		0.006		0.0		0.0			
09:45	0.005		0.005		0.0		0.0			
10:00	0.006		0.005		0.0		0.0			
10:15	0.006		0.005		0.0		0.0			
10:30	0.005		0.005		0.0		0.0			
10:45	0.004		0.004		0.0		0.0			

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	0.003		0.003		0.0		0.0			
11:15	0.004		0.004		0.0		0.0			
11:30	0.003		0.004		0.0		0.0			
11:45	0.003		0.003		0.0		0.0			
12:00	0.005		0.006		0.0		0.0			
12:15	0.007		0.006		0.0		0.0			
12:30	0.007		0.005		0.0		0.0			
12:45	0.007		0.004		0.0		0.0			
13:00	0.007		0.006		0.0		0.0			
13:15	0.004		0.004		0.0		0.0			
13:30	0.003		0.003		0.0		0.0			
13:45	0.006		0.003		0.0		0.0			
14:00	0.004		0.004		0.0		0.0			
14:15	0.004		0.003		0.0		0.0			