

Project	Bedford Beverly Brownfield	Report No.	23
Project	•	Report No.	25
	Site		
BCP Site	BCP Site No. C224384	Date	11/06/2023
Location	2359 and 2360 Bedford	File No.	0205432
	Avenue, Brooklyn, NY		
Client	Bedford Beverly Acquisitions	Temperature	44-56 °F
	LLC, Star Demolition (Star),		
	Maman Contracting (Maman),		
	International Concrete		
Contractor	Haley & Aldrich	Wind Direction	NNE to SSW, 21 mph
Weather	Mostly Sunny	Personnel on	D. Djombalic
		Site	
Humidity	69%	Time on Site	7:15am to 3:30pm

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich currently under review by NYSDEC and the NYSDEC-approved Change of Use dated 17 August 2023 to begin support of excavation work. Site observations are summarized below.

Daily Observations:

- Contractor (International Concrete) continued support of excavation (SOE) prep along the perimeter of Lot 14 and stockpiled soil in preparation for disposal.
- Contractor (Star) continued demolition of the former building on Lot 53 and stockpiled demolition debris for disposal.

Waste Disposal/Backfill Import Tracking:

Material Export:

No soil was transported off-site.

	Facility: Flushing Asphalt Recycling, Flushing NY		Material	: Mount s, Fairless (Asphalt)			
	(Asphalt)				Tota	ıls:	
Today:	0 Loads	0 CY	0 Loads	0 CY	0 Loads	0 CY	
<u>Total:</u>	<u>117 Loads</u>	2340 CY	<u>5 Loads</u>	<u>100 CY</u>	<u>122 Loads</u>	2440 CY	



C&D disposal is summarized below:

·	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Tota	ls:
Today:	6 Loads	120 CY	6 Loads	120 CY
Total:	16 Loads	320 CY	16 Loads	320 CY

^{*}Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

Material Import:

No material was imported to the Site.

Samples Collected:

No samples were collected.

CAMP Activities:

 Air monitoring during ground-intrusive activities was performed at four locations during ground intrusive work from 7:45 pm to 3:15 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities Planned for Coming Week:

- Contractor (Star) will continue demolition of the former building on Lot 53.
- Contractor (International Concrete) will continue stockpiling soil on the perimeter of Lot 14 for disposal.
- Contractor (International Concrete) will continue installing H piles as part of SOE installation on the perimeter of the site.



Site Photographs:




Photo 1: View of excavation for SOE installation along the perimeter of Lot 14, facing southwest.



Photo 2: View of contractor loading C&D of Lot 14, facing west.





2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Date: 2023-11-06

Personnel: D. Djombalic

Weather: Mostly Sunny

Humidity: 69%
Wind Direction: NNE to SSW, 21 mph

Particulate Background (ug/m3): 3.363

PID Background (ppm) : 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
07:45		4.305		3.939		0.0		0.0		
08:00	17.832	4.283	3.363	3.466	0.0	0.0	0.0	0.0		
08:15	14.031	4.856	3.214	4.250	0.0	0.0	0.0	0.0		
08:30	17.166	4.106	3.134	4.499	0.0	0.0	0.0	0.0		
08:45	23.539	3.889	3.224	4.603	0.1	0.0	0.0	0.0		
09:00	15.373	3.904	3.059	4.054	0.0	0.0	0.0	0.0		
09:15	13.314	3.463	3.059	5.774	0.0	0.0	0.0	0.0		
09:30	18.477	3.536	3.353	4.349	0.0	0.0	0.0	0.0		
09:45	28.032	3.676	3.733	12.604	0.0	0.0	0.0	0.0		
10:00	15.435	3.741	4.328	3.907	0.0	0.0	0.0	0.0		
10:15	23.839	4.293	3.881	4.641	0.0	0.0	0.0	0.0		
10:30	25.602	4.645	3.992	4.943	0.0	0.0	0.0	0.0		
10:45	17.235	5.122	4.689	4.810	0.0	0.0	0.0	0.0		

2360 Bedford Avenue, Brooklyn NY

Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	19.273	5.664	4.824	4.9	0.0	0.0	0.0	0.0		
11:15	20.890	5.592	4.601	5.0	0.0	0.0	0.0	0.0		
11:30	20.544	5.966	5.383	4.9	0.0	0.0	0.0	0.0		
11:45	22.128	8.865	4.443	6.3	0.0	0.0	0.0	0.0		
12:00	14.622	7.725	4.428	4.9	0.0	0.0	0.0	0.0		
12:15	16.492	6.230	4.185	5.0	0.0	0.0	0.0	0.0		
12:30	15.646	14.608	4.566	4.7	0.0	0.0	0.0	0.0		
12:45	15.222	11.505	5.032	8.9	0.0	0.0	0.0	0.0		
13:00	60.705	9.035	4.548	7.5	0.1	0.0	0.0	0.0		
13:15	18.690	6.790	4.609	5.2	0.0	0.0	0.0	0.0		
13:30	15.367	6.693	4.485	6.0	0.0	0.0	0.0	0.0		
13:45	22.676	5.384	6.915	5.0	0.0	0.0	0.0	0.0		
14:00	99.033	4.935	4.733	4.7	0.0	0.0	0.0	0.0		
14:15	87.460	4.519	4.390	4.8	0.0	0.0	0.0	0.0		
14:30	37.184	5.149	4.158	4.8	0.0	0.0	0.0	0.0		
14:45	37.268	4.480	4.146	5.5	0.0	0.0	0.0	0.0		
15:00	24.495	4.073	3.965	12.9	0.0	0.0	0.0	0.0		
15:15	23.458		4.106	38.3	0.0		0.0	0.0		