

Project	Bedford Beverly Brownfield	Report No.	28
	Site		
BCP Site	BCP Site No. C224384	Date	11/13/2023
Location	2359 and 2360 Bedford	File No.	0205432
	Avenue, Brooklyn, NY		
Client	Bedford Beverly Acquisitions	Temperature	32-49 °F
	LLC, Star Demolition (Star),		
	Maman Contracting (Maman),		
	International Concrete		
Contractor	Haley & Aldrich	Wind Direction	N to S, 4 mph
Weather	Sunny	Personnel on	N. Mooney & E. Nunez
		Site	
Humidity	76%	Time on Site	6:50am to 3:30pm

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the Remedial Action Work Plan (RAWP) prepared by Haley & Aldrich currently under review by NYSDEC and the NYSDEC-approved Change of Use dated 17 August 2023 to begin support of excavation work. Site observations are summarized below.

#### Daily Observations:

- Contractor (International Concrete) continued support of excavation (SOE) prep along the perimeter of Lot 14 and stockpiled soil in preparation for disposal.
- Contractor (Star) continued demolition of the former building on Lot 53 and stockpiled demolition debris for disposal.
- Contractor (International Concrete) loaded tri-axle trucks with C&D for off-site transport and disposal.

#### Waste Disposal/Backfill Import Tracking:

#### **Material Export:**

- Three (3) loads of asphalt were transported off-site to Mount Materials located in Fairless Hills, PA.
- Soil disposal is summarized below:

	Facility: Flushing Asphalt Recycling, Flushing NY		Materials	: Mount s, Fairless (Asphalt)		
	(Asph	•	, ,	(1.10)	Tota	ıls:
Today:	0 Loads	0 CY	3 Loads	60 CY	3 Loads	60 CY
Total:	<u>117 Loads</u>	2340 CY	8 Loads	<u>160 CY</u>	125 Loads	2500 CY



- Four (4) loads of C&D were transported off-site to Mount Materials located in Fairless Hills, PA.
- C&D disposal is summarized below:

	Facility:	Mount		
	Mate	rials,		
	Fairless I	Hills, PA		
	(Non-Haz	Concrete)	Total	ls:
Today:	4 Loads 80 CY		4 Loads	80 CY
Total:	34 Loads	680 CY	34 Loads	680 CY

<sup>\*</sup>Note, 1 truck estimated at 20 cubic yards. Final tonnages will be present in the Final Engineering Report (FER)

#### **Material Import:**

No material was imported to the Site.

#### Samples Collected:

No samples were collected.

#### **CAMP Activities:**

 Air monitoring during ground-intrusive activities was performed at four locations during ground intrusive work from 6:45 am to 3:15 pm. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

#### Activities Planned for Coming Week:

- Contractor (Star) will continue demolition of the former building on Lot 53.
- Contractor (International Concrete) will continue stockpiling soil on the perimeter of Lot 14 for disposal.
- Contractor (International Concrete) will continue installing H piles as part of SOE installation on the perimeter of the site.



## Site Photographs:




Photo 1: View of H piles and lagging installed in Lot 14, facing north-northwest.



Photo 2: View of excavation for SOE installation along the perimeter of Lot 14, facing southwest.





#### 2360 Bedford Avenue, Brooklyn NY

#### Air Monitoring Log

Date: 2023-11-13

Personnel: D. Djombalic & Eddy Nunez

Weather: Sunny
Humidity: 76%

Wind Direction: N to S, 4 mph

Particulate Background (ug/m3) : 5.145

PID Background (ppm): 0.0

Action Levels : <u>Downwind perimeter of work area above background levels</u>

PID (ppm): > 5 ppm for the 15-min average Dust (ug/m3): > 150 for the 15-min average

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
06:45	13.766	4.833	19.266	5.145	0.0	0.0	0.0	0.0		
07:00	11.779	8.472	14.874	5.418	0.0	0.0	0.0	0.1		
07:15	11.611	6.823	17.121	5.746	0.0	0.0	0.0	0.0		
07:30	10.120	6.270	14.317	12.755	0.0	0.0	0.0	0.0		
07:45	9.355	4.835	12.439	4.632	0.0	0.0	0.0	0.0		
08:00	8.246	6.294	10.155	6.912	0.0	0.0	0.0	0.0		
08:15	7.730	5.564	7.578	5.898	0.0	0.0	0.0	0.2		
08:30	6.770	4.893	6.109	4.621	0.0	0.0	0.0	0.1		
08:45	5.994	6.150	4.597	4.228	0.0	0.0	0.0	0.0		
09:00	5.728	4.844	4.164	3.995	0.0	0.0	0.0	0.0		
09:15	5.747	4.680	3.954	4.218	0.0	0.0	0.0	0.0		
09:30	5.753	4.449	3.851	4.076	0.0	0.0	0.0	0.0		
09:45	5.560	8.281	4.419	4.217	0.0	0.0	0.0	0.0		
10:00	5.855	42.852	6.266	4.623	0.0	0.0	0.0	0.0		
10:15	6.175	5.419	5.215	4.337	0.0	0.0	0.0	0.0		
10:30	5.682	4.890	4.147	4.261	0.0	0.0	0.0	0.0		
10:45	5.674	5.293	4.612	4.733	0.0	0.0	0.0	0.0		

### 2360 Bedford Avenue, Brooklyn NY

### Air Monitoring Log

Minute of Time	Avg. PM10 (Station1)	Avg. PM10 (Station2)	Avg. PM10 (Station3)	Avg. PM10 (Station4)	Avg. VOC(Station1)	Avg. VOC(Station2)	Avg. VOC(Station3)	Avg. VOC(Station4)	Odors	Notes Activities/ Additional Monitoring
11:00	5.096	4.280	4.125	4.2	0.0	0.0	0.0	0.0		
11:15	5.326	4.340	7.523	4.7	0.0	0.0	0.0	0.0		
11:30	5.375	4.421	4.158	4.4	0.0	0.0	0.0	0.0		
11:45	4.720	4.116	4.016	4.7	0.0	0.0	0.0	0.0		
12:00	4.639	4.188	3.758	5.6	0.0	0.0	0.0	0.0		
12:15	4.692	3.509	3.210	4.4	0.0	0.0	0.0	0.0		
12:30	4.246	3.917	3.586	4.0	0.0	0.0	0.0	0.0		
12:45	5.073	4.630	4.069	4.5	0.0	0.0	0.0	0.0		
13:00	5.226	4.881	4.312	5.1	0.0	0.0	0.0	0.0		
13:15	5.901	5.789	5.228	5.9	0.0	0.0	0.0	0.0		
13:30	6.165	5.517	5.212	6.2	0.0	0.0	0.0	0.0		
13:45	5.817	5.838	5.571	8.1	0.0	0.0	0.0	0.0		
14:00		6.724		23.7		0.0		0.0		
14:15		6.623		23.3		0.0		0.0		
14:30		7.746		10.4		0.0		0.0		
14:45		9.021		9.5		0.0		0.0		
15:00		8.598		8.8		0.0		0.0		
15:15		7.307		12.8		0.0		0.0		