

SITE OBSERVATION REPORT

PROJECT No.: 170381202

CLIENT:

Thursday, June 22, 2023 DATE:

PROJECT:

250 Water Street

250 Seaport District, LLC

WEATHER:

Overcast, 60 - 65 °F

c/o The Howard Hughes Corporation

Wind: NE @ 8 - 16 mph

LOCATION:

New York, NY

TIME:

6:50 am - 12:15 pm

BCP SITE ID: C231127 **MONITOR**

Jack Millman

EQUIPMENT:

CAT 335 Excavator ABI Mobilram Drill Rig Jerome J505 Mercury Vapor Analyzer RKI GX-6000 Photoionization Detector (PID)

PRESENT AT SITE:

Day 146

Langan (Environmental) Jack Millman

Suffolk Construction (Suffolk) (General Contractor) Anthony Galu East Coast Drilling, Inc. (ECD) (Foundation Contractor) Danny Rodgers **New York State Department of Environmental Conservation** (NYSDEC) Rafi Alam and Meghan Medwid

Aeroqual ASQ1 Air Monitoring Station

OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:

Langan was present to document remediation activities in accordance with the NYSDEC-approved November 2021 Remedial Action Work Plan (RAWP) at the 250 Water Street site (NYSDEC Brownfield Cleanup Program [BCP] Site No C231127).

Site Activities

Suffolk and ECD continued mobilizing equipment in preparation for the next phase of remediation.

CC.	ivi. Haygorodetsky, i . ivicivianon, ivi. Ad, 5. i rey	Dy.	LANGAN
Co:	M. Raygorodetsky, P. McMahon, M. Au, J. Frey	By:	Jack Millman



Page 2 of 5

SITE OBSERVATION REPORT

Material Tracking

- No material was exported from the site.
- No material was imported to the site.

Material Import Summary								
Facility Name Location Type of Material	Stone Industries, Inc. Haledon, NJ 1.5/2.5-inch Virgin Stone		Stone Industries, Inc. Haledon, NJ 0.75-inch Virgin Stone		Impact Reuse & Recovery Center or Impact Materials Jersey City, Lyndhurst/Jersey City, NJ 1.5-inch Clean Bluestone		Impact Reuse & Recovery Center, Lyndhurst, NJ General Fill	
Quantities	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)	No. of Loads	Approx. Volume (Tons)
Today	0	0	0	0	0	0	0	0
Project Total	8	184.42	0	0	15	339.65	336	8,216.79
NYSDEC Approved:	1,800 tons*				720 tons*		19,500 tons*	

*0.75-inch, 1.5-inch, and 2.5-inch virgin stone from the Stone Industries, Inc. facility and 1.5-inch clean bluestone from the Impact Reuse & Recovery Center (IRRC) facility were approved for import of 1,000 cubic yards (CY) and 400 CY, respectively. Assuming a conversion factor of 1.8, each quantity was converted to tons in order to accurately compare with import weight tickets. General fill from the IRRC facility was approved for import of 13,000 CY and a conversion factor of 1.5 is applied.

Material Export Summary (1 of 2)								
Facility Name Location Type of Material	Allocco Recycling Brooklyn, NY Construction & Demolition (C&D) Debris		IRRC Lyndhurst, NJ Construction & Demolition (C&D) Debris		Clean Earth of North Jersey Kearny, NJ Hazardous Lead-Impacted Soil/Fill		Clean Earth of North Jersey Kearny, NJ Non-hazardous Soil/Fill	
Quantities	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)
Today	0	0	0	0	0	0	0	0
Project Total	5	85	42	840	95	1,900	216	4,320

Material Export Summary (2 of 2)								
Facility Name Location Type of Material	Middlesex County Landfill East Brunswick, NJ Non-hazardous Soil/Fill		Keas	oil Management Bbey, NJ mpacted Soil/Fill	Clean Earth of Carteret, NJ Carteret, NJ Non-hazardous Soil/Fill			
Quantities	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)	No. of Loads	Approx. Volume (CY)		
Today 0 0 C		0	0	0	0			
Project Total	261	5,220	267	5,340	66	1,320		

Cc:	M. Raygorodetsky, P. McMahon, M. Au, J. Frey	Ву:	Jack Millman
			LANGAN



Page 3 of 5


SITE OBSERVATION REPORT

Sampli	<u>ing</u>		
•	No samples were collected.		
CAMP A	<u>Activities</u>		
•	The community air monitoring plan (CAMP) was reperformed.	not impl	emented because no ground-intrusive activities were
Anticip	pated Activities		
•	Suffolk and ECD will continue mobilization in prep	aration	for the next phase of remediation.
Cc:		5	
	M. Raygorodetsky, P. McMahon, M. Au, J. Frey	Ву:	Jack Millman



Page 4 of 5

SITE OBSERVATION REPORT





Page 5 of 5

SITE OBSERVATION REPORT

Select Site Photographs:



Photo 1: General view of the site (facing east)

Cc: M. Raygorodetsky, P. McMahon, M. Au, J. Frey By: Jack Millman

LANGAN