



Daily Report for June 1, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Installed Preprufe 200 in C6-C8, and D6-D8.
- Installed Bituthene and Hyrdoduct in C5 and D5.
- Backfilled in grid C5, C6, D5, and D6 for Building H with approved clean fill Building B (7-15) foot material.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in grid D5 and D5.



Photo 2- View of formwork and rebar installation in C7 and C8.



Photo 3- View
of installing
Bituthene in
C5.





Daily Report for June 2, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Installed Bituthene and Hyrdoduct in C5 and D5.
- Backfilled in grid C5, C6, D5, and D6 for Building H with approved clean fill Building B (7-15) foot material.
- Poured concrete in C7, C8, D7, and D8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in grid D5 and D5.



Photo 2- View of pouring concrete in C7 and C8.



Photo 3- View of formwork and rebar installation in A3, A4, B3, and B4.





Daily Report for June 3, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in grid C5, C6, D5, and D6 for Building H with approved clean fill Building B (7-15) foot material.
- Poured concrete in D3, D4, E3, and E4.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in grid D5 and D5.



Photo 2- View of formwork and rebar installation in C7 and C8.



Photo 3- View of pouring concrete, formwork and rebar installation in D3, D4, E3, and E4.





Daily Report for June 4, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in C6, C7, D6, and D7 for Building H with approved clean fill Building B (7-15) foot material.
- Installed Preprufe 200 in C5 and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in grid C7, C8, D7, and D8.



Photo 2- View of Preprufe 200 installation in C5 and D5.



Photo 3- View of formwork and rebar installation in D3, D4, E3, and E4.





Daily Report for June 5, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in C6, C7, D6, and D7 for Building H with approved clean fill Building B (7-15) foot material.
- Poured concrete in C6 and D5.
- Spread stone in C6, C7, D6 and D7.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling with clean fill in grid C7, C8, D7, and D8.



Photo 2- View of pouring concrete in D5 and D6.



Photo 3- View of formwork and rebar installation in A3, A4, B3, and B4.





Daily Report for June 8, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Spread stone in C5, C6, D5, and D6.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilled area with clean fill in C7, C8, D7, and D8.



Photo 2- View of utility work and spreading stone in C5, C6, and D5.



Photo 3- View
of formwork in
C5 and D5.





Daily Report for June 9, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in C7, C8, D7, and D8 with Building B (7-15) material.
- Installed Preprufe 200 in C5, C6, D5, and D6.
- Poured concrete in A1-A4, and B1-B4.

2. Locations of work and quantities of material imported and exported from the Site.

- 3 loads of non-hazardous soil were exported from the Site today to Clean Earth of Bethlehem in Bethlehem, PA from grids B5 (0-7) and C5 (0-7).
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling area with clean fill in C7, C8, D7, and D8.



Photo 2- View of utility work and Preprufe 200 installation in C5, C6, and D5.



Photo 3- View of loading out soil for export offsite.





Daily Report for June 10, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in C7, C8, D7, and D8 with Building B (7-15) material.
- Installed Preprufe 200 in C5, C6, D5, and D6.
- Poured concrete in A1-A4, and B1-B4.

2. Locations of work and quantities of material imported and exported from the Site.

- 3 loads of non-hazardous soil were exported from the Site today to Clean Earth of Bethlehem in Bethlehem, PA from grids B5 (0-7) and C5 (0-7).
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of backfilling area with clean fill in C7, C8, D7, and D8.



Photo 2- View of pouring concrete in C5, C6, and D5.



Photo 3- View of loading out soil for export offsite.





Daily Report for June 11, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled in C7, C8, D7, and D8 with Building B (7-15) material.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B tenth through twelfth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of trenching for utility installation in C7, C8, D7, and D8.



Photo 2- View of backfilling in C5, C6, and D5.



Photo 3- View of formwork, utility and rebar installation in A3, A4, B3, and B4.





Daily Report for June 12, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Trenched for utility installation in C7, C8, D7, and D8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of trenching for utility installation in C7, C8, D7, and D8.



Photo 2- View of utility installation in C6 and C7.



Photo 3- View of formwork, utility and rebar installation in D3, D4, E3, and E4.





Daily Report for June 15, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Trenched for utility installation in C7 and C8.
- Backfilled with $\frac{3}{4}$ " gravel in C5 and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- Imported 16 loads of $\frac{3}{4}$ " washed gravel from the Posillico site in Farmingdale, New York.
- No materials were exported from the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log


Photo 1- View of importing gravel.



Photo 2- View of backfilling with gravel in C5 and D5.



Photo 3- View of formwork, utility installation and trench work in C7 and C8.





Daily Report for June 16, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled with $\frac{3}{4}$ " gravel in C5 and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of formwork, rebar, and utility installation.



Photo 2- View of backfilling with gravel in C5 and D5.



Photo 3- View of formwork, rebar, and utility installation in A4, A4, B3, and B4.





Daily Report for June 17, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Backfilled with $\frac{3}{4}$ " gravel in C5 and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- Imported 24 loads of $\frac{3}{4}$ " washed gravel from the Posillico site in Farmingdale, New York.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of formwork, rebar, and utility installation in C6 and C7.



Photo 2- View of backfilling with gravel in C5 and D5.



Photo 3- View of formwork, rebar, and utility installation in A4, A4, B3, and B4.





Daily Report for June 18, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Poured concrete for Building C.
- Trenched soil in C6-C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of trenching soil in C6-C8.



Photo 2- View of formwork, rebar, and utilities installation in D3, D4, E3, and E4.



Photo 3- View
of pouring
concrete for
Building C.





Daily Report for June 19, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Poured concrete in C5, C6, D5, and D6.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of pouring concrete in C5, C6, D5, and D6.



Photo 2- View of formwork, rebar, and utilities installation in D3, D4, E3, and E4.



Photo 3- View of formwork, rebar and utilities installation in A3, A4, B3, and B4.





Daily Report for June 22, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Graded stone in C5 and C6.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fourth through sixth floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of grading stone in C5 and C6.



Photo 2- View of formwork, rebar, and utilities installation in D3, D4, E3, and E4.



Photo 3- View of formwork, rebar and utilities installation in A3, A4, B3, and B4.





Daily Report for June 23, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C7, D1- D5, E2- E4, and F2-F4.
- Graded stone in C7 and C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of grading stone in C7 and C8.



Photo 2- View of formwork, rebar, and utilities installation in D3, D4, E3, and E4.



Photo 3- View of formwork, rebar and utilities installation in A3, A4, B3, and B4.





Daily Report for June 24, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.
- Graded stone in C7 and C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of graded stone in C7 and C8.



Photo 2- View of formwork, rebar, and utilities installation in D3, D4, E3, and E4.



Photo 3- View
of rebar
installation in
C6 and C7.





Daily Report for June 25, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Graded soil in C7 and C8.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of graded soil in C7 and C8.



Photo 2- View of formwork, rebar, and utilities installation in A3, A4, B3, and B4.



Photo 3- View
of rebar and
formwork
installation in
C5 and C6.





Daily Report for June 26, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Graded soil in C7 and C8.
- Installed Preprufe 200 in C7 and C8.
- Poured concrete for Building C 13th floor.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of grading soil in C7 and C8.



Photo 2- View of pouring concrete in A3, A4, B3, and B4.



Photo 3- View
of installed
Preprufe 200 in
C7 and C8.





Daily Report for June 29, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Graded stone in C5 and D5.
- Installed Preprufe 200 in C5, C7, C8, and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View of grading stone in C5 and D5.



Photo 2- View of installing formwork, rebar, and waterproofing installation in C5 and D5.



Photo 3- View
of installed
Preprufe 200 in
C7 and C8.





Daily Report for June 30, 2020

**Far Rockaway Project
20-02 Mott Avenue
Far Rockaway, NY
BCP #C241224**

1. An update of progress made during the reporting day including references to alpha-numeric map for Site activities.

- Utility, rebar, and formwork installation in A1- A4, B1- B4, C5-C8, D1- D5, E2- E4, and F2-F4.
- Brickwork in C3, C4, and D4.
- Poured concrete in D5 and D6.
- Installed Preprufe 200 in C5, C7, C8, and D5.

2. Locations of work and quantities of material imported and exported from the Site.

- No materials were exported from the site today.
- No materials were imported to the site today.

3. A summary of any and all complaints with relevant details (names, phone numbers).

- No complaints.

4. A summary of CAMP findings (air and dust readings).

- No elevated PID or dust readings were identified.

5. An explanation of notable Site conditions.

- Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

6. Planned Activities

- Continue formwork and rebar installation for Building B twelfth through thirteenth floors.
- Continue formwork and rebar installation for Building C fifth through seventh floors.
- Continue formwork and rebar installation for Building H.

Photo Log

Photo 1- View
of installed
Preprufe 200 in
C5 and D5.



Photo 2- View
of pouring
concrete in D5
and D6.



Photo 3- View
of rebar and
formwork in C7
and C8.

