

### Daily Report for February 1, 2021

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Site closed due to snowstorm
- 2. Locations of work and quantities of material imported and exported from the Site.
- No material was exported from the site today.
- No material was imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.



### Daily Report for February 2, 2021

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2- F4.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No material was exported from the site today.
- -No material was imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of formwork and utility installation grids A3, A4, B3, and B4. Photo 2- View of formwork and utility installation grids D4, D5, E4, and E5.

Photo 3- View of formwork and utility installation grids C6-C8.





## Daily Report for February 3, 2021

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavated clean fill in A4 and B4 for utility installation.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No material was exported from the site today.
- -No material was imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of excavation in A4 and B4 for utility installation. Photo 2- View MI H WILLIAM of excavation in A4 and B4 for utility installation.

Photo 3- View of utility installation in B4.	



## Daily Report for February 4, 2021

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavated clean fill in A4 and B4 for utility installation.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -No material was exported from the site today.
- -No material was imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of excavation in A4 and B4 for utility installation. Photo 2- View of utility and formwork installation in D4, D5, E4, and E5.

Photo 3- View of utility and formwork installation in C6-C8.





## Daily Report for February 5, 2021

Far Rockaway Project 20-02 Mott Avenue Far Rockaway, NY BCP #C241224

- 1. An update of progress made during the reporting day including references to alphanumeric map for Site activities.
- -Utility, rebar, and formwork installation in A1- A4, B1- B5, C5-C8, D1- D7, E2- E4, and F2- F4.
- -Excavated clean fill in A4 and B4 for utility installation.
- 2. Locations of work and quantities of material imported and exported from the Site.
- -1 load of nonhazardous soil from grid C6 (0-7) was exported to the Posillico Facility in Farmingdale, NY.
- -No material was imported to the site today.
- 3. A summary of any and all complaints with relevant details (names, phone numbers).
- -No complaints.
- 4. A summary of CAMP findings (air and dust readings).
- -No elevated PID or dust readings were identified.
- 5. An explanation of notable Site conditions.
- -Today's work was overseen by David Klein of CA RICH. No conditions of note were observed.

- -Continue formwork and rebar installation for Building B.
- -Continue formwork and rebar installation for Building C.
- -Continue formwork and rebar installation for Building H.

Photo 1- View of loading out non-hazardous soil for export offsite. Photo 2- View of utility and formwork installation in A3, A4, B3, and B4.

Photo 3- View of utility and formwork installation in C6-C8.

