PERIODIC REVIEW REPORT FOR

PORTION OF THE NIAGARA FALLS MUNICIPAL COMPLEX 1925 MAIN STREET NIAGARA FALLS, NEW YORK 14305 BCP SITE NUMBER C932133



Prepared for:

Bellevue Local Development Corporation

745 Main Street PO Box 69 Niagara Falls, NY 14302



4950 Genesee St., Suite #100 Buffalo, N.Y. 14225 716-633-4844

PERIODIC REVIEW REPORT

PORTION OF THE NIAGARA FALLS MUNICIPAL COMPLEX 1925 MAIN STREET NIAGARA FALLS, NEW YORK 14305 BCP SITE NUMBER C932133

TABLE OF CONTENTS

2.0	PERIO 2.1	DIC REVIEW Institutional and Engineering Controls 2.1.1 Inspection of Engineering and Institutional Controls	
	2.2 2.3	Site Monitoring Plan Operation and Maintenance	4
3.0	CONC	LUSIONS AND RECOMMENDATIONS	!
4.0	LIMITA	ATIONS	:
	F FIGUR		
FIGUR FIGUR		PROPERTY LOCATION MAP SITE PLAN	
LIST O	F APPEN	IDICES	
	IDIX A	NYSDEC'S DECEMBER 18, 2013 EXTENSION LETTER PHOTOGRAPHS	
APPEN	IDIX C	NYSDEC SITE MANAGEMENT PERIODIC REVIEW NOTICE INSTITUTIONAL AND ENGINEERING CONTROLS CERTIFICATION FORM	
APPEN	IDIX D	NYSDEC'S JUNE 20, 2013 INSPECTION LETTER AND REVISED MONTHLY INSPECTION CHECKLIST	٧
APPEN	IDIX E	CORRECTIVE MEASURES WORK PLAN	
APPEN	IDIX F	SUB-SLAB DEPRESSURIZATION SYSTEM MONTHLY INSPECTION CHECKLIST JUNE 2013 THROUGH DECEMBER 2013	

1.0

INTRODUCTION

Site Overview

1

1.0 INTRODUCTION

The City of Niagara Falls retained Greenman-Pedersen Inc. (GPI) to evaluate current conditions at the Niagara Falls Municipal Complex (henceforth referred to as the "Site") in the City of Niagara Falls, New York and prepare this Periodic Review Report (PRR) for the Site. This Site is currently owned by the Bellevue Local Development Corporation (Owner). This PRR is being completed to meet the Site Management Periodic Review Report and Institutional Control / Engineering Control (IC/EC) Certification requirements under the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP). The NYSDEC BCP site number is C932133. This PRP documents the implementation of and compliance with the November 2010 Site Management Plan (SMP) prepared for this site.

1.1 Site Overview

The Site is a portion of the Niagara Falls Municipal Complex, measuring approximately 0.803 acres. Figures 1 and 2 from the SMP are included in this PRR and show the location of the Site and the boundaries of the 0.803 acre portion comprising the BCP site. The properties comprising the Site were historically used for multiple purposes including an automotive repair / service facility; a dry cleaner; various retail stores; a beauty shop; jewelry stores; a liquor store; a tailor; dentist and lawyers offices; unidentified commercial structures and residential properties. Historically, the Site was comprised of seven separate tax parcels, which along with several additional adjoining tax parcels not part of the BCP site, were combined in 2011 to form the single tax parcel 144.13-3.24. The Site is currently occupied by Niagara Falls Municipal Complex building which is approximately 130,000 square feet in size.

Remedial investigations were conducted at the Site between July and October 2007. These investigations identified the presence of petroleum and solvent based volatile organic compounds (VOCs); semi-volatile organic compounds (SVOCs), which consisted primarily of polycyclic aromatic hydrocarbons (PAHs) and heavy metals in overburden soils. The evaluation of detected concentrations revealed that one VOC and no SVOCs were recorded above NYSDEC's Part 375 Unrestricted Soil Cleanup Objectives (SCOs). Also, several metals were detected at concentrations above the Unrestricted SCOs. Additionally, analytical testing on staged soils excavated from beneath the former on-site structures during Interim Remedial Measures (IRMs) revealed the presence of tetrachloroethene, a common dry cleaning solvent at concentrations excess of Industrial SCOs. Also, total petroleum hydrocarbon analysis of the staged soils revealed the presence of petroleum impacts.

The investigation of groundwater identified the presence of chlorinated solvents at concentrations exceeding NYSDEC's water quality standards (WQS) in the overburden and bedrock groundwater. The highest concentrations were detected in the northern portion of the Site. Also, petroleum-related VOCs exceeding the WQS were detected in the overburden groundwater in the northern portion of the Site. No petroleum-related VOCs were detected in the bedrock groundwater. It

should be noted that groundwater is not used for potable or non-potable purposes at the Site or in the general vicinity of the Site.

An IRM was implemented at the Site and was conducted between late 2007 and early 2008. The IRM involved the excavation and off-site disposal of approximately 22,000 tons of impacted soils exceeding the Unrestricted SCOs. Also, four underground storage tanks identified during excavation along with 750-gallons of petroleum product were removed and disposed of off-site. The IRM addressed the impacted soil/fill from the Site; however, solvent contaminated groundwater within the bedrock aquifer remains on-site.

Based on the presence of solvent contaminated groundwater that remained on-site following IRM activities, a vapor barrier combined with a sub-slab depressurization system (SSDS) was installed during construction of the Niagara Falls Municipal Complex building. The system consists of a full-slab vapor barrier beneath the entire building footprint (including the portion outside the BCP portion of the Site) and an active venting system, involving the use of negative pressure blowers to evacuate air from below and around the building's basement floor slab.

2.0 PERIODIC REVIEW

GPI conducted the initial annual Periodic Review in December 2013 for the reporting period occurring between September 20, 2011 through February 3, 2013. It should be noted that the NYSDEC granted an extension of time to the Owner to file the PRR until December 31, 2013. A copy of the NYSDEC letter granting this extension is included in Appendix A. This Periodic Review is discussed in the sections below. Appendix B includes photographs taken during the Site Inspection and Appendix C includes the NYSDEC "Site Management Periodic Review Report Notice – Institutional and Engineering Controls Certification Form."

2.1 Institutional and Engineering Controls

Since remaining contaminated groundwater and soil vapor potentially exists beneath the Site, Engineering Controls and Institutional Controls were required to protect human health and the environment.

As described above the EC implemented at the Site includes a vapor mitigation system that is comprised of a vapor barrier beneath the entire footprint of the building combined with a SSDS. Because all contaminated soil was excavated from the Site, an Excavation Work Plan was not included in the SMP and no special procedures are required to be implemented for future excavations at the Site.

In addition to the ECs a series of ICs were also required for the Site. The ICs implemented at the Site include:

- Compliance with the Environmental Easement and the SMP;
- Operation and maintenance of all ECs in accordance with the SMP;
- Inspection of all ECs at the Site in accordance with the SMP;
- The ECs may not be discontinued without an amendment or extinguishment of the Environmental Easement;
- Reporting of all required monitoring data in accordance with the SMP;
- The Site may only be used for restricted-residential or more restrictive uses provided that the long-term EC/ICs listed in the SMP are employed and may not be used for a higher level of use without additional remediation and amendment of the Environmental Easement, as approved by the NYSDEC;
- The use of the groundwater underlying the Site is prohibited without treatment rendering it safe for intended use;
- The potential for vapor intrusion must be evaluated for any buildings developed within the boundaries of the Site;
- A qualified environmental professional shall submit to NYSDEC a written certified report on annual basis; and
- The NYSDEC shall retain the right to access the Site at any time in order to evaluate any and all controls.

2.1.1 Inspection of Engineering and Institutional Controls

On December 16, 2013, GPI's Project Manager, Mr. James C. Manzella, CHMM, conducted the site inspection. The inspection included observation of current conditions throughout and surrounding the building; the basement of the building; and the sub-slab depressurization system. GPI also held discussions with Mr. Thomas O'Donnell, Deputy Corporation Counsel for the City of Niagara Falls, NY, during the site inspection. The evaluation of the IC/ECs obtained from the site inspection is summarized in the paragraphs below.

The Site is currently occupied by the Niagara Falls Municipal Complex, which houses the City's police department headquarters and local court system; therefore, is in compliance with the Site use restriction requirements of the Environmental Easement. Also, the Site is serviced by the public water system and no groundwater use occurs on-site and as such meets the groundwater use restrictions.

While the SMP required a soil vapor intrusion evaluation prior to the construction of any enclosed structures on the Site, the SMP allowed for the installation of vapor mitigation system in lieu of this evaluation. As described above the vapor mitigation system is comprised of a vapor barrier beneath the entire footprint of the building combined with a SSDS. The site monitoring as well as the operation and maintenance components associated with the SSDS are summarized in Sections 2.2 and 2.3 below.

2.2 Site Monitoring Plan

The Site Monitoring Plan component of the SMP requires that the sub-slab depressurization system be inspected pursuant to a monthly inspection checklist to confirm each of the electric blowers is operating. Additionally, the monthly inspection is to include an examination of visible piping for any cracks and ensure the discharge stacks are free from obstructions. Also, in their June 20, 2013 correspondence the NYSDEC provided a modified checklist that includes a column to record the SSDS's pressure readings. The NYSDEC also recommended in this letter that a copy of the monthly checklist be posted on the wall adjacent to the SSDS's pressure gauges. A copy of this letter along with the revised monthly checklist is included in Appendix D.

A copy of the monthly checklist was not present on-site at the time of the December 16, 2013 site visit. Based on discussions with City personnel the monthly inspections required by the SMP were not performed during this reporting period; therefore the Owner is not in compliance with the SMP and a Corrective Measures Work Plan (CMWP) is required to address this deficiency. The CMWP is comprised of a letter prepared by Mr. Thomas O'Donnell to address the monthly inspection deficiency. This letter explains the cause for the deficiency, the measures to be taken to correct the deficiency and the schedule for implementing the corrective measures. A copy of the CMWP letter is included in Appendix E. It should also be noted that since NYSDEC's June 2013 visit the City has been conducting the required monthly inspections. A copy of the checklist documenting these monthly inspections is included in Appendix F.

2.3 Operation and Maintenance

In addition to the monthly inspections of the SSDS, annual inspections of the following additional components of the system are to be performed: all warning devices/alarm indicators, system labeling, vacuum pressure gauges, exhaust stack discharge, and integrity of the vapor barrier, as appropriate. Inspection of these features are confirmed by visual observation as well as noting air discharges from vents located on the roof of the building. As-built drawings as well as other pertinent information regarding the Sub-Slab Depressurization System are presented in Figure 6 and Appendices B and C of the SMP.

GPI evaluated the operation of the SSDS during the December 16, 2013 site inspection. GPI observed the discharge locations on the roof of the building, and the locations were free of ice and snow build-up. Additionally, while on the roof GPI confirmed that both blowers were operating and that air was flowing out of the vent pipes. No excessive noise, as identified in NYSDEC's June 20, 2013 letter was noted during the site inspection. Regardless, the City has contacted a qualified vendor to inspect the blowers, and will repair them if applicable. The City will prepare a Non-Routine Maintenance Report and submit to NYSDEC under separate cover a copy of this report.

GPI manually tripped the alarms on the SSDS to confirm system operation by disconnecting the pressure tubing from each of the two alarm units. Both units changed from green indicator lights to red indicator lights and an audible alarm sounded within a few seconds indicating the alarm system was functioning properly. System labeling was in place as identified in the SMP. Each of the pressure gauges displayed an operating pressure of 0.5 W.C. (inches of water), which is within the operating pressure range listed in the SMP. While the integrity of the vapor barrier could not be visually examined due to its subsurface location, the visual examination of the building's basement floor slab showed its integrity to be intact, which indicates impacts to the vapor barrier are unlikely.

3.0 CONCLUSIONS AND RECOMMENDATIONS

As stated above the Owner is not in compliance with the monthly inspection requirement listed in the Site Monitoring Plan component of the SMP for the reporting period. A CMWP to address this deficiency is included in Appendix E. While not in compliance with the SMP, this deficiency does not appear to have had any impact on the efficacy of the SSDS. This assertion is based on the recent visual inspection, the fact that the monthly inspection have been conducted since June 2013 and the Corrective Measures to be put in place in accordance with the CMWP included in Appendix E.

With the exception of the monthly inspection deficiency the Site in compliance with the SMP and Environmental Easement. Therefore with the exception of implementing the measures outlined in the CMWP, no changes to the periodic review reporting are recommended.

4.0 LIMITATIONS

The conclusions presented in this report are based on information gathered in accordance generally accepted professional consulting principles and practices. All conclusions reflect observable conditions existing at the time of the site inspection. Information provided by outside sources (individuals, agencies, laboratories, etc.), as cited herein, was used in the evaluation of the Site. The accuracy of the conclusions drawn from this Periodic Review is, therefore, dependent upon the accuracy of information provided by these sources. Furthermore, GPI is not responsible for the impacts of any changes in environmental standards, practices, or regulations subsequent to the performance of services.


This Periodic Review Report is based upon the application of scientific principles and professional judgment to certain facts with resultant subjective interpretations. Professional judgments expressed herein are based upon the facts currently available within the limits of the existing data, scope of services, budget, and schedule. To the extent that more definitive conclusions are desired by the Client than are warranted by the current available facts, it is specifically GPI's intent that the conclusions and recommendations stated herein will be intended as guidance and not necessarily a


firm course of action except where explicitly stated as such. GPI makes no warranties, expressed or implied including without limitation, warranties as to merchantability or fitness of a particular purpose. Furthermore, the information provided in this report is not to be construed as legal advice.

This Periodic Review Report has been completed and prepared on behalf of and for the exclusive use of the City of Niagara Falls. Any reliance on this report by a third party is at such party's sole risk. Furthermore, nothing contained in this report shall be construed as a warranty or affirmation by GPI that the Site described in this report is suitable collateral for any loan or that acquisition of such property by any lender through foreclosure proceedings or otherwise will pose no risk of potential environmental liability on the part of such lender.

FIGURES







APPENDIX A - NYSDEC'S DECEMBER 18, 2013 EXTENSION LETTER



New York State Department of Environmental Conservation Office of General Counsel, 14th Floor

625 Broadway, Albany, New York 12233-1500 Phone: (518) 402-9185 Fax: (518) 402-9018

Website: www.dec.ny.gov



December 18, 2013

SENT VIA Facsimile 716-286-4424

Department of Law
P.O. Box 69
Niagara Falls, NY 14302-0069

RE: Brownfield Site Cleanup Agreement Index No. B9-0758-07-11 915 Cleveland Avenue Site No. C932133

Dear Mr. O'Donnell:

In response to your letter of December 16, 2013, the NYS Department of Environmental Conservation (Department) will grant your request for an extension of time to file the Periodic Review Report.

The Department requests that the Report be filed by December 31, 2013. If you have any questions or concerns relating to the filing date, please feel free to contact our office directly at 518-402-9510.

Your timely response to comply is appreciated.

Sincerely,

Maria Mastroianni Legal Assistant

RCRA and Hazardous Waste

Enforcement Bureau

cc: Ben Conlon, DEC

APPENDIX B - PHOTOGRAPHS





Photograph No. 1 – Exterior of Niagara Falls Municipal Complex Building, west side.



Photograph No. 2 – Lobby of Niagara Falls Municipal Complex Building.



Photograph No. 3 – Basement level of Niagara Falls Municipal Complex Building depicting general conditions.



Photograph No. 4 – Sub-slab Depressurization System in basement, depicting alarms, pressure gauges and stack discharge piping.



Photograph No. 5 – Sub-slab Depressurization System discharge vents and blowers.



Photograph No. 6 – Sub-slab Depressurization System power control for discharge vents.

APPENDIX C - NYSDEC SITE MANAGEMENT PERIODIC REVIEW NOTICE INSTITUTIONAL & ENGINEERING CONTROLS CERTIFICATION FORM





Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



		Box 1				
Site	No.	C932133	Site Details			
Site	Name 915	Cleveland Avenue	ı			
City	Address: 1 /Town: Nia inty: Niagara Acreage: 0	a a	Zip Code: 14305-2637			
Rep	orting Perio	od: September 20, 2	011 to February 03, 2013			
				YES	NO ·	
1.	Is the inform	nation above correct	?	M		
•••			e or on a separate sheet.			
	Has some of		erty been sold, subdivided, merged, or undergone a		×	
3.		peen any change of t RR 375-1.11(d))?	use at the site during this Reporting Period		×	
4.	Have any for or at the	ederal, state, and/or property during this	local permits (e.g., building, discharge) been issued Reporting Period?		×	
	If you answ that docum	wered YES to quest nentation has been	tions 2 thru 4, include documentation or evidence previously submitted with this certification form	• •		
5.	Is the site of	currently undergoing	development?		X	
		6		Box 2		
				YES	NO .	
6.	Is the curre Restricted-	ent site use consister Residential, Comme	nt with the use(s) listed below? ercial, and Industrial	×	0	
7.	Are all ICs/	/ECs in place and fu	nctioning as designed?	×		
	IF TI	HE ANSWER TO EIT	HER QUESTION 6 OR 7 IS NO, sign and date below E THE REST OF THIS FORM. Otherwise continue.	and		
A C	Corrective M	leasures Work Plan	must be submitted along with this form to address	these is:	sues.	
Sig	nature of Ov	vner, Remedial Party	or Designated Representative Date			

Box 2A YES NO 8. Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid? If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. Box 3 **SITE NO. C932133**

Description of Institutional Controls

Parcel

Owner

Institutional Control

144.13-3-24

Bellevue Local Development Corporation

Building Use Restriction Ground Water Use Restriction

IC/EC Plan

Landuse Restriction Monitoring Plan O&M Plan

Site Management Plan

Soil Management Plan

Box 4

Description of Engineering Controls

Parcel Parcel

Engineering Control

144.13-3-24

Vapor Mitigation

Engineering Control Details for Site No. C932133

Parcel: 144.13-3-24

The Environmental Easement was filed as of 02-16-2011. The vapor mitigation system for the building includes a sub-slab depressurization system. A groundwater use restriction is in place along with a restriction for restricted residential use.

Periodic Review Report (PRR) Certification Statements

- 1. I certify by checking "YES" below that:
 - a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;
 - b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.

YES NO



- 2. If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:
 - (a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;
 - (b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment:
 - (c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;
 - (d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and
 - (e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.

YES NO

M

IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.

A Corrective Measures Work Plan must be submitted along with this form to address these issues.

Signature of Owner, Remedial Party or Designated Representative

Date

IC CERTIFICATIONS SITE NO. C932133

Box 6

SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

print name	at print business address	
am certifying as		_(Owner or Remedial Party
for the Site named in the Site Details	Section of this form.	
or the Site named in the Site Details	Section of this form.	
or the Site named in the Site Details	Section of this form.	

IC/EC CERTIFICATIONS

			Box 7
Qual	ified Environmental Pro	ofessional Signature	BOX /
		•	
certify that all information in Bo			
unishable as a Class "A" misde	meanor, pursuant to Sec	tion 210.45 of the Penal L	.aw.
		3	9
	at		
print name	prin	t business address	
m certifying as a Qualified Envi	ronmental Professional f		
		(Owner or Remed	lial Party)
*			
A STATE OF THE STA			
Signature of Qualified Environm		Stamp	Date
he Owner or Remedial Party, R	endering Certification	(Required for PE)	

APPENDIX D - NYSDEC'S JUNE 20, 2013 INSPECTION LETTER AND REVISED MONTHLY INSPECTION CHECKLIST



New York State Department of Environmental Conservation Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



June 20, 2013

Mr. Thomas Pryce Bellevue Local Development Corporation 745 Main Street P.O. Box 69 Niagara Falls, New York 14302

Dear Mr. Pryce:

915 Cleveland Avenue/1925 Main Street Niagara Falls, NY 14305 Site No.: C932133

On June 13, 2013, I met with Mr. James Anthony to inspect the sub-slab depressurization (SSD) system at the above-subject site. The SSD system was operating; however, one of the vent pipe blowers, located on the third floor roof, was making excessive noise and is in need of maintenance work. I also noted that there was no Monthly Sub-Slab Blower Inspection Check List on site as required by the Site Management Plan (SMP).

Enclosed is a Monthly Sub-Slab Blower Inspection Check List which should be used to record each SSD system inspection. It has been modified from the check list in Appendix D of the SMP to include SSD system pressure readings. It may be useful to mount it in a folder on the basement wall of Mechanical Room B05 where the SSD system valves and pressure gauges are located. A copy of the check list and records of any maintenance performed on the system must be included in the Site Management Periodic Review Report (PRR). Other requirements for the PRR are outlined in the SMP, a copy of which is included for your convenience on the enclosed CD along with a copy of the Vapor Barrier and Collection System Installation Report.

If you have any questions, please call me at (716) 851-7220.

Sincerely,

Tim Dieffenbach

Engineering Geologist II

Tim Diefferback

TD:sz Enclosures

ec: Teresa Mucha, Esq. - NYSDEC, Office of General Counsel

Mr. Gregory Sutton - NYSDEC, Division of Environmental Remediation

cc: Thomas O'Donnell, Esq. - Deputy Corporation Counsel

Mr. James Anthony - City of Niagara Falls (w/enclosures)

Monthly Sub-Slab Blower Inspection Check List

Date Initials Time		All Blowers Operational?	Are there any cracks in the visible piping?	Is the discharge stack clear?	Press. Readings	Comments	
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		
			Yes / No	Yes / No	Yes / No		

APPENDIX E - CORRECTIVE MEASURES WORK PLAN LETTER





City of Niagara Falls, New York

P.O. Box 69, Niagara Falls, NY 14302-0069

DEPARTMENT OF LAW Telephone: (716) 286-4409

December 23, 2013

Re:

Corrective Measures Work Plan

915 Cleveland Avenue Site No. C932133

Niagara Falls Municipal Complex

The monthly inspection of the sub-slab depressurization system and inspection check list were not maintained during this reporting period. The failure to perform this was due to the lack of communication to the building's maintenance staff.

Moving forward and on a continuous basis, the inspections will be conducted on a monthly basis in accordance with the November, 2010 Site Management Plan and the NYSDEC letter dated June 20, 2013.

Remedial Plan

To ensure future compliance with the required monthly monitoring, the following measures are being implemented:

- 1. The appropriate building staff is aware and will do the monitoring in accordance with the required check list and complete the check list on a monthly basis.
 - 2. The inspection will be conducted during the first week of each calendar month.
- 3. In order to ensure that the inspections take place on a timely basis, a copy of the inspection data will be forwarded to the Director of the Department of Public Works and to the City of Niagara Falls Engineering Department.
- 4. If either does not receive the report by the 15th day of the month, follow up will occur to ensure that the inspection was performed and the appropriate documentation was secured.

Very truly yours,

CRAIG H. JOHNSON
Corporation Counsel

By: THOMAS M. O'DONNELL Deputy Corporation Counsel

TMO/jt



APPENDIX F - SUB-SLAB DEPRESSURIZATION SYSTEM MONTHLY INSPECTION CHECKLIST JUNE 2013 THROUGH DECEMBER 2013



Monthly Sub-Slab Blower Inspection Check List

Comments	# 2 ,06		H 2 .05		# 2 ,56		750. CH		dd. 54		18. St.																			
Press. Readings	#1-,05		#1.05		#1.06		20.14		70. 1H		50° 1 #																			
Is the discharge stack clear?	(Yes)/ No	Yes / No	(Yes)/ No	Yes / No	√es)/ No	Yes / No	(Yes) No	oN / se /	(Yes) No	Yes / No	resy No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	Yes / No	
Are there any cracks in the visible piping?	Yes (A)	Yes / No	Yes (Mo)	Yes / No	YesyAMO	Yes / No	Yes (Mo	Yes / No	Yes (NO)	Yes/No	Yes (TND)	Yes / NV	Yes / No																	
All Blowers Operational?	(es)/ No	Yes / No	(Yes) No	Yes / No	(Yes) No	Yes / No	yes) No	Yes / No	(Yes)/No	Yes / No	(Yes)/ No	Yes / No																		
Time	G. B. Dum		1.30pm		10.00/4		N. 00 1/4.		gos Start	1	Mosdan																			
Initials	ジバ	200	210		W/E		10/12		2/1/1		21.0	4																		
Date	2/2/13		51/0/8		2/1/13		81/11/01		11/1/18	1	12/4/12																			