

VOLUNTARY
CLEAN-UP PROGRAM
INVESTIGATION
REPORT - VOLUME I



Former Ithaca Gun Factory Property
Falls Creek and Lake Street
Ithaca, Tompkins County, NY 14850

Job No. 01-021

Prepared for:

Dr. Wally Diehl, DVM
110 Banks Drive
Chapel Hill, North Carolina 27514

Prepared By:



PRESCOTT ENVIRONMENTAL ASSOCIATES, INC.
Post Office Box 2555, Chapel Hill, North Carolina 27515-2555 (919) 942-8006

CERTIFICATION

Re: VOLUNTARY CLEAN-UP PROGRAM INVESTIGATION REPORT
Former Ithaca Gun Factory Property, Falls Creek and Lake Street,
Ithaca, Tompkins County, NY 14850

I have reviewed the subject report prepared by Prescott Environmental Associates, Inc. (PEAI), Chapel Hill, North Carolina, and I am familiar with the site.

In my professional judgement, the site investigation conducted by PEA I was in conformance with good engineering practices and standard industry-accepted environmental assessment practices. Additionally, the remediation alternatives discussed in the report appear to be consistent with the findings of the investigation, and are consistent with the provisions of 6 NYCRR Part 375, Inactive Hazardous Waste Disposal Sites, §375-1.10(c), Remedy Selection.

C. Paul McWilliams

C. Paul McWilliams, P.E.
NYS License No. 043258



VOLUME I - TABLE OF CONTENTS

	Page
1.0 EXECUTIVE SUMMARY	1
2.0 INTRODUCTION	4
3.0 DESCRIPTION OF INVESTIGATION ACTIVITIES	5
3.1 Soil Borings	5
3.2 Groundwater Monitoring Well Installation	8
3.3 QA/QC	9
4.0 INVESTIGATION FINDINGS	10
4.1 Soil Sampling Analytical Results	10
4.2 Groundwater Sampling Analytical Results	14
4.3 Dye Tracer Study	15
5.0 QUALITATIVE HUMAN HEALTH EXPOSURE ASSESSMENT	18
5.1 Identified Contaminated Media	19
5.2 Exposure Pathways	19
6.0 DEVELOPMENT AND EVALUATION OF REMEDIAL ALTERNATIVES	22
6.1 Sources of Contamination	22
6.2 Extent of Contamination	23
6.3 Alternatives for Remediation	25
7.0 REMEDIAL COST ESTIMATES	27
8.0 HEALTH & SAFETY CONSIDERATIONS	28
9.0 DATA USABILITY SUMMARY REPORT	29
10.0 INTERIOR ISSUES/DATA GAPS	30

VOLUME I - TABLE OF CONTENTS (continued)

FIGURES AND TABLES

- Figure 1: Site Location Map
Figure 2: Site Plan - Soil Boring, Sampling, and Monitoring Well Locations
Figure 3: Dye Tracer Study Results
Figure 4: Site Plan - Contaminated Areas Summary
Figure 5: Westerly Parcel Soil Boring Locations, Showing Isoconcentrations of Total Lead - Partial/3D
Figure 6: Westerly Parcel Soil Boring Locations, Showing Isoconcentrations of Total Lead - Partial/2D
Figure 7: Groundwater Hydraulic Gradient Map
Figure 8: Site Plan - Responsibility for Clean-up - U.S. EPA and Volunteer
- Table 1: XRF Screening Results - Soil and Sediment Samples
Table 2: OVA Screening Results - Soil and Sediment Samples
Table 3: Laboratory Analytical Results Summary - Soil & Sediment
Table 4: Laboratory Analytical Results Summary - Groundwater
Table 5: Westerly Parcel Soil Lab Results Summary - Total Lead

APPENDICES

- Appendix A Test Boring/Monitoring Well Logs
Appendix B Site Worker Air Monitoring and Blood Lead Lab Reports
Appendix C Data Validation Report
Appendix D XRF Data Reports
Appendix E Follow-up Groundwater Laboratory Analytical Report