

INFORMATION STM STANDARDS



Dvirka and Bartilucci

Consulting Engineers

GRUMMAN AEROSPACE CORPORATION

SUPPLEMENTAL INFORMATION PURSUANT TO ASTM STANDARDS NEW YORK STATE SITE REGISTRY DELISTING PETITION 789 SOUTH BROADWAY (LINDEN TREE SITE) HICKSVILLE, NEW YORK

PREPARED BY

DVIRKA AND BARTILUCCI CONSULTING ENGINEERS SYOSSET, NEW YORK

APRIL 1994



6800 Jericho Turnpike, Syosset, New York 11791 516-364-9892 • Fax: 516-364-9045

April 28, 1994

John Ohlmann, P.E., Director
Corporate Environmental Protection
Grumman Aerospace Corporation
1111 Stewart Avenue
Mail Stop D08-GHQ
Bethpage, NY 11714-3582

New York State Site Registry Delisting Petition Supplemental Information Pursuant to ASTM Standards D&B No. 1110 789 South Broadway (Linden Tree Site)

Dear Mr. Ohlmann:

As you are aware, Dvirka and Bartilucci Consulting Engineers (D&B) completed a Phase I and Phase II Site Assessment in support of a New York State Site Registry Delisting Petition requirements of the ASTM standards. referenced site in an effort to supplement the prior site assessment to meet the applicable In accordance with your request, additional information has been obtained for the above Materials (ASTM) standards for Phase I Environmental Site Assessments (Designation E1527-93). was completed prior to the May 1993 publication of the American Society for Testing and for the above referenced site (Section 46, Block 503, Lots 7 and 14) in March 1992. That project

assessment has been supplemented with an evaluation of the following additional sources of information: In an effort to meet the applicable requirements of the ASTM standards, the prior

- data base search) State and Federal Standard Environmental Record Sources (computer environmental
- Standard Historical Source (fire insurance maps)
- utilizing site assessments completed more than 180 days prior) New Site Reconnaissance, Interviews and Updated Records Review (required when

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Two

The findings of the evaluation of these additional sources of information are as follows:

STATE AND FEDERAL STANDARD ENVIRONMENTAL RECORD SOURCES

environmental data base search are presented in Attachment 1. accordance with the ASTM minimum radius search criteria. computer environmental data base search of state and federal environmental record sources in with ASTM standards, VISTA Environmental Information, Inc. was requested to undertake a or immediately adjacent to the site. In order to supplement this effort and achieve consistency evaluation of local agency records was undertaken to identify any environmental concerns on-site New York State Department of Environmental Conservation (NYSDEC), an investigation and As part of the original New York State Site Registry Delisting Petition, as required by the The detailed findings of the

search is presented below by data base category A summary of the evaluation of each of the sites identified in the environmental data base

Large Quantity Generators

not identify any record of regulatory violations associated with this facility. of waste. In addition to these considerations, the Vista Environmental Information Report did administrative controls including the use of manifests for tracking the transportation and disposal containment structures for any designated storage areas along with stringent record keeping and as administered by the Nassau County Department of Health. Overall, these include secondary addressing the overall management and storage of hazardous waste over a sole source aquifer, Program but must also adhere to the very stringent management standards and design criteria Department of Environmental Conservation's (NYSDECs) Hazardous Waste Management County, NY, it is not only subject to the regulatory requirements of the New York State as a large quantity generator of hazardous waste. As a generator of hazardous waste in Nassau The Vista Environmental Information Report has identified the Texaco facility

unlikely to adversely impact the Linden Tree site. Assessment of the Linden Tree property supports the conclusion that the Texaco facility is The results of this information search along with the findings of the Phase I and II Site

waste in Nassau County, NY, it is not only subject to the regulatory requirements of the New York State Department of Environmental Conservation's (NYSDECs) Hazardous Waste design criteria addressing the overall management and storage of hazardous waste over a sole Management Program but must also adhere to the very stringent management standards and Typesetters facility as a large quantity generator of hazardous waste. As a generator of hazardous CD Typesetters: The Vista Environmental Information Report has identified the CD

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Three

include secondary containment structures for any designated storage areas along with stringent source aquifer, as administered by the Nassau County Department of Health. Overall, these transportation and disposal of waste. In addition to these considerations, the Vista Environmental Information Report did not identify any record of regulatory violations associated with this

Assessment of the Linden Tree property supports the conclusion that the CD Typesetters facility unlikely to adversely impact the Linden Tree site. The results of this information search and the findings of the Phase I and II Site

record keeping and administrative controls including the use of manifests for tracking the include secondary containment structures for any designated storage areas along with stringent source aquifer, as administered by the Nassau County Department of Health. Overall, these design criteria addressing the overall management and storage of hazardous waste over a sole Management Program but must also adhere to the very stringent management standards and waste in Nassau County, NY, it is not only subject to the regulatory requirements of the New Mobil facility as a large quantity generator of hazardous waste. As a generator of hazardous Information Report did not identify any record of regulatory violations associated with this transportation and disposal of waste. In addition to these considerations, the Vista Environmental State Department of Environmental Conservation's (NYSDECs) Hazardous John's South Bay Mobil: The Vista Environmental Information Report has identified this

unlikely to adversely impact the Linden Tree site Assessment of the Linden Tree property supports the conclusion that this Mobil facility is The results of this information search and the findings of the Phase I and II Site

source aquifer, as administered by the Nassau County Department of Health. Overall, these design criteria addressing the overall management and storage of hazardous waste over a sole include secondary containment structures for any designated storage areas along with stringent Management Program but must also adhere to the very stringent management standards and waste in Nassau County, NY, it is not only subject to the regulatory requirements of the New Oldsmobile facility as a large quantity generator of hazardous waste. As a generator of hazardous Information Report did not identify any record of regulatory violations associated with this transportation and disposal of waste. In addition to these considerations, the Vista Environmental record keeping and administrative controls including the use of manifests for tracking York State Merry Oldsmobile: The Vista Environmental Information Report has identified the Merry Department of Environmental Conservation's (NYSDECs) Hazardous Waste

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Four

facility is unlikely to adversely impact the Linden Tree site. Assessment of the Linden Tree property supports the conclusion that the Merry Oldsmobile The results of this information search and the findings of the Phase I and II Site

Small Quantity Generators

transportation and disposal of waste. In addition to these considerations, the Vista Environmental include secondary containment structures for any designated storage areas along with stringent source aquifer, as administered by the Nassau County Department of Health. Overall, these the New York State Department of Environmental Conservation's (NYSDECs) Hazardous Waste Cogen Partners facility as a small quantity generator of hazardous waste. As a generator of hazardous waste in Nassau County, NY, it is not only subject to the regulatory requirements of downgradient of the Linden Tree site. facility. Furthermore, it is important to note that the TBG Cogen Partners facility is located Information Report did not identify any record of regulatory violations associated with this record keeping and administrative controls including the use of manifests for tracking the design criteria addressing the overall management and storage of hazardous waste over a sole Management Program but must also adhere to the very stringent management standards and TBG Cogen Partners: The Vista Environmental Information Report has identified the TBG

facility is unlikely to adversely impact the Linden Tree site. Assessment of the Linden Tree property supports the conclusion that the TBG Cogen Partners The results of this information search and the findings of the Phase I and II Site

include secondary containment structures for any designated storage areas along with stringent source aquifer, as administered by the Nassau County Department of Health. Overall, these facility. Furthermore, it is important to note that the Alpian II facility is located downgradient Information Report did not identify any record of regulatory violations associated with this transportation and disposal of waste. In addition to these considerations, the Vista Environmental record keeping and administrative controls including the use of manifests for tracking the design criteria addressing the overall management and storage of hazardous waste over a sole Management Program but must also adhere to the very stringent management standards and of the Linden Tree site. York State Department of Environmental Conservation's (NYSDECs) Hazardous Waste waste in Nassau County, NY, it is not only subject to the regulatory requirements of the New II Cleaners facility as a small quantity generator of hazardous waste. As a generator of hazardous Alpian II Cleaners: The Vista Environmental Information Report has identified the Alpian

facility is unlikely to adversely impact the Linden Tree site. Assessment of the Linden Tree property supports the conclusion that the Alpian II Cleaners The results of this information search and the findings of the Phase I and II Site

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Five

Underground Storage Tanks (UST)

control and tank testing programs. secondary containment structures, leak detection, cathodic protection and rigorous inventory aquifer resources of the County. Department of Health. the stringent design, inventory control and reporting requirements of the Nassau County requirements for upgrading underground storage tank systems but are also required to adhere to documented releases will also be listed on the LUST data base (see following section). Furthermore, any USTs located in Nassau County, New York, are subject not only to the federal with registered underground storage tanks are listed on the UST data base and any facilities with Information Report does not include UST sites. However, it is important to note that all facilities the sale of this data base to commercial establishments and, as such, the VISTA Environmental not include information maintained within Nassau County. Furthermore, Nassau County prohibits It should be noted that the New York Underground Storage Tank (UST) data base does These additional requirements are in place to protect the sole source Overall, these include the design and implementation of

on the Linden Tree property Tree property supports the conclusion that UST sites are not likely to have had an adverse impact The above discussion and the findings of the Phase I and II Site Assessment of the Linden

Leaking Underground Storage Tanks (LUST)

place to protect the sole source aquifer resources of the County. Overall, these include the design rigorous inventory control and tank testing programs. and implementation of secondary containment structures, leak detection, cathodic protection and requirements of the Nassau County Department of Health. These additional requirements are in systems but is also required to adhere to the stringent design, inventory control and reporting facility is subject not only to the federal requirements for upgrading underground storage tank Rental facility on the LUST data base. Avis Car Rental: The Vista Environmental Information Report has identified the Avis Car As a LUST located in Nassau County, New York, the

property supports the conclusion that the Avis Car Rental facility is unlikely to adversely impact information search and the findings of the Phase I and II Site Assessment of the Linden Tree with vehicular fueling operations. The incident is reported as "case closed." The results of this the Linden Tree site. Car Rental facility apparently experienced a 15 gallon surface spill of gasoline likely associated Based on information contained in the Vista Environmental Information Report, the Avis

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Six

rigorous inventory control and tank testing programs. and implementation of secondary containment structures, leak detection, cathodic protection and place to protect the sole source aquifer resources of the County. requirements of the Nassau County Department of Health. These additional requirements are in systems but is also required to adhere to the stringent design, inventory control and reporting facility is subject not only to the federal requirements for upgrading underground storage tank Northeast facility on the LUST data base. As a LUST located in Nassau County, New York, the ERM Northeast: The Vista Environmental Information Report has identified the ERM Overall, these include the design

Northeast facility is unlikely to adversely impact the Linden Tree site Phase I and II Site Assessment of the Linden Tree property supports the conclusion that the ERM reported as "cleanup in progress." The results of this information search and the findings of the Northeast facility apparently experienced a fuel oil spill of undisclosed volume. Based on information contained in the Vista Environmental Information Report, the ERM The incident is

of the Nassau County Department of Health. These additional requirements are in place to control and tank testing programs secondary containment structures, leak detection, cathodic protection and rigorous inventory protect the sole source aquifer resources of the County. Overall, these include the design and but is also required to adhere to the stringent design, inventory control and reporting requirements is subject not only to the federal requirements for upgrading underground storage tank systems facility on the LUST data base. As a LUST located in Nassau County, New York, the facility Blue Flame: The Vista Environmental Information Report has identified the Blue Flame

facility is unlikely to adversely impact the Linden Tree site. I and II Site Assessment of the Linden Tree property supports the conclusion that the Blue Flame reported as "case closed." Flame facility apparently experienced a fuel oil spill of undisclosed volume. Based on information contained in the Vista Environmental Information Report, the Blue The results of this information search and the findings of the Phase The incident is

not only to the federal requirements for upgrading underground storage tank systems but is also on the LUST data base. As a LUST located in Nassau County, New York, the facility is subject rigorous inventory control and task testing programs implementation of secondary containment structures, leak detection, cathodic protection and Nassau County Department of Health. These additional requirements are in place to protect the required to adhere to the stringent design, inventory control and reporting requirements of the Bertane: The Vista Environmental Information Report has identified the Bertane facility aquifer resources of the County. Overall, these include the design

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Seven

facility is unlikely to adversely impact the Linden Tree site. I and II Site Assessment of the Linden Tree property supports the conclusion that the Bertane reported as "case closed." Bertane facility apparently experienced a fuel oil spill of undisclosed volume. The incident is Based on information contained in the Vista Environmental Information Report, the The results of this information search and the findings of the Phase

control and task testing programs. of secondary containment structures, leak detection, cathodic protection and rigorous inventory sole source aquifer resources of the County. Overall, these include the design and implementation Nassau County Department of Health. These additional requirements are in place to protect the required to adhere to the stringent design, inventory control and reporting requirements of the not only to the federal requirements for upgrading underground storage tank systems but is also on the LUST data base. As a LUST located in Nassau County, New York, the facility is subject Slomins: The Vista Environmental Information Report has identified the Slomins facility

Slomins facility is unlikely to adversely impact the Linden Tree site downgradient of the Linden Tree site. The results of this information search and the findings of the Phase I and II Site Assessment of the Linden Tree property supports the conclusion that the reported as "case closed." Furthermore, it is important to note that the Slomins facility is located Slomins facility apparently experienced a fuel oil spill of undisclosed volume. The incident is Based on information contained in the Vista Environmental Information Report, the

Comprehensive Environmental Response Compensation Liability Information System (CERCLIS)

to note that the Servo Corporation facility was removed from the State Priorities List by the New due to the fact that there currently exists no administrative mechanism to remove it), it is worthy to present a significant threat to the environment. System (CERCLIS) data base. While the Servo facility remains on the CERCLIS list (principally Corporation on the Comprehensive Emergency Response, Compensation and Liability Information York State Department of Environmental Conservation over 6 years ago as it was determined not Servo Corporation: The Vista Environmental Information Report has identified the Servo

the findings of the Phase I and II Site Assessment of the Linden Tree property, the Servo facility is unlikely to adversely impact the Linden Tree site. Based on information contained in the Vista Environmental Information Report along with

National Priorities List (NPL)

is under active investigation and/or remedial phases pursuant to a Consent Order with additional the Ruco Polymer facility as a National Priorities List (NPL) site. monitoring and remediation planned for the future. Ruco Polymer Corporation: The Vista Environmental Information Report has identified In addition, as an NPL site, the facility is As an NPL site, this facility

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Eight

supports the conclusion that the Ruco Polymer Corporation facility is unlikely to adversely impact search and the findings of the Phase I and II Site Assessment of the Linden Tree property under active review by appropriate federal regulatory authorities. The results of this information the Linden Tree site.

State Priorities List (SPL)

adversely impact the Linden Tree site. property supports the conclusion that the Ruco Polymer Corporation facility is unlikely to information search and the findings of the Phase I and II Site Assessment of the Linden Tree facility is under active review by appropriate state regulatory authorities. additional monitoring and remediation planned for the future. In addition, as an SPL site, the the Ruco Polymer Corporation facility as a State Priorities List (SPL) site. facility is under active investigation and/or remedial phases pursuant to a Consent Order with Ruco Polymer Corporation: The Vista Environmental Information Report has identified As an SPL site, this The results of this

of this information search and the findings of the Phase I and II Site Assessment of the Linden important to note that the Grumman facility is located lateral to the Linden Tree site. additional monitoring and remediation planned for the future. In addition, as an SPL site, the the Linden Tree site Tree property supports the conclusion that the Grumman facility is unlikely to adversely impact facility is under active review by appropriate state regulatory authorities. Furthermore, facility is under active investigation and/or remedial phases pursuant to a Consent Order with has identified the Grumman facility as a State Priorities List (SPL) site. Grumman Aerospace - Bethpage Facility: The Vista Environmental Information Report As an SPL site, this The results

none of the sites listed are likely to have had an adverse impact on the Linden Tree property Delisting Petition and our evaluation of the environmental data base search, as presented above, search criteria, based upon the Phase I and Phase II findings of the New York State Site Registry In conclusion, although several sites are identified within the ASTM minimum radius

STANDARD HISTORICAL SOURCE

this initial effort did not consult historical aerial sources prior to 1940 (earliest available aerial VISTA Environmental Information, Inc. was requested to undertake a full-search and reproduction photographs were dated 1950), the ASTM standards require that another "standard historical were evaluated to identify the historical use of the site and surrounding areas. As part of the original New York State Site Registry Delisting Petition, aerial photographs (as identified in Section 7.3.4 of Designation E1527-93) be consulted.

John Ohlmann, P.E., Director Corporate Environmental Protection Grumman Aerospace Corporation April 28, 1994

Page Nine

evaluation of historical sources of information meets or exceeds the applicable ASTM procedural building department records and property tax files) were consulted as part of the prior assessment. also be noted that several other standard historical sources identified in the ASTM standard (i.e. of all available Sanborn (fire insurance) Maps, which frequently date back to the mid to late requirements Although none of the consulted standard historical sources dated back to before 1940, the Sanborn Maps are not available for the property under evaluation (see Attachment 2). It should 1800's. Sanborn Mapping and Geographic Information Services, Inc., subsequently reported that

NEW SITE RECONNAISSANCE, INTERVIEWS AND UPDATED RECORDS REVIEW

performed a site inspection/windshield survey on April 18, 1994, and conducted interviews with site assessments completed more than 180 days prior, the ASTM standards require that a new site listed are likely to have had an adverse impact on the property under evaluation of the updated records review (state and federal environmental data base search), none of the sites based upon the findings of the New York State Site Registry Delisting Petition and our evaluation materially since the prior environmental site assessment was conducted. As previously discussed, the site conditions likely to affect recognized environmental conditions have not changed representatives of Grumman Aerospace Corporation. Based upon our evaluation of the preceding, reconnaissance, interviews and an update of the records review be performed. As a result, D&B reconnaissance, interviews and a records review were performed. However, in order to utilize As part of the original New York State Site Registry Delisting Petition,

Conclusions

of any adverse impacts from identified surrounding properties on the Linden Tree site Delisting Petition and the supplemental information provided in this report, there is no evidence Based upon the Phase I and Phase II findings of the New York State Site Registry

to contact me or Mr. Richard Russell at (516) 364-9892. If you have any questions and/or comments regarding this matter, please do not hesitate

Richard M. Walka

Project Manager

RMW/ss

c: Kelley Evens (GAC)
Richard P. Russell (D&B)

♦1110/RMW04114.GA3

ATTACHMENT 1

ENVIRONMENTAL DATA BASE SEARCH

SITE ASSESSMENT REPORT

	Ladiate Poligitude: (To. / T/ LTO, / J. JOSOST /
	1 attnide/1 onginide: (40 749148 73 503034)
SYOSSET, NY 11791	HICKSVILLE, NY 11802
6800 JERICHO TURNPIKE	789 S BROADWAY
DVIRKA BARTILUCCI	LINDEN TREE SITE
RICH RUSSELL	Project Name/Ref #: DVIRKA BARTIL
M CLIENT INFORMATION	MEGRAMATION

	6	•	2	Sites that Generate Small Quantities of Haz Waste	RCRIS	US EPA
1			+	Sites that Generate Large Quantities of Haz Waste	RCRIS	US EPA
	•		0	Sites With Previous Hazardous Materials Spills	ERNS	US EPA
				to 1/8 mile:	D) RISK SITES searched to 1/8 mile:	D) RISK S
		0		Sites with Registered Underground Storage Tanks	TSU	STATE
				to 1/4 mile:	C) RISK SITES searched to 1/4 mile:	C) RISK S
1	0	0	0	Sites permitted as Solid Waste Landfills, Incinerators, or Transfer stations	SWLF	STATE
	2	2	_	Sites with Leaking UnderGround Storage Tanks	LUST	STATE
	-	0	0	Sites under Review by US EPA	CERCLIS	US EPA
				to 1/2 mile:	B) RISK SITES searched to 1/2 mile:	B) RISK S
0	0	0	0	Facilities That Treat, Store and/or Dispose of Haz Waste	RCRIS	US EPA
N/A	N/A	N/A	A/N	Sites Under Review by State	SCL	STATE
2	0	0	0	Sites Prioritized by State for Cleanup	SPL	STATE
	0	0	0	Sites designated for Superfund Cleanup by the US EPA	NPL	US EPA
unha s Albara and austron s				to 1 mile:	A) RISK SITES searched to 1 mile:	A) RISK S
				of Records	Agency / Database - Type of Records	Agency / I
1/2/to	1/4 to	1316	Haller 1/8	Environmental Risk Distribution Summary	avironmen S	leş.

This geographic database search meets the American Society for Testing Materials (ASTM) standards for a government records review. A (-) indicates the search distance exceeds ASTM search parameters.

LIMITATION OF LIABILITY


Customer proceeds at its own risk in choosing to rely on VISTA services, in whole or in part, prior to proceeding with any transaction. VISTA cannot be an insurer of the accuracy of the information, errors occurring in conversion of data, or for customer's use of data. VISTA and its affiliated companies, officers, agents, employees and independent contractors cannot be held liable for accuracy, storage, delivery, loss or expense suffered by customer resulting directly or indirectly from any information provided by VISTA.






SITE ASSESSMENT REPORT

Map of Risks Within One Mile



For More Information Call VISTA Environmental Information at - 800 - 767 - 0403

Report ID: 039300-001




For More Information Call VISTA Environmental Information at Report ID: 039300-001 1 - 800 - 767 - 0403

Date of Report: March 18, 1994



SITE ASSESSMENT REPORT

Street Map



Date of Report: March 18, 1994

SITE ASSESSMENT REPORT

DESCRIPTION OF DATABASES SEARCHED

A) DATABASES SEARCHED TO 1 MILE

SRC#: 1622 VISTA conducts a database search to identify all sites within 1 mile of your property

The agency release date for NPL was January, 1994

sites identified for priority remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Dept of Health and Human Services and the US EPA in order to become an The National Priorities List (NPL) is the EPA's database of uncontrolled or abandoned hazardous waste

SPL SRC#: 1412 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Inactive Hazardous Waste Disposal Sites was May, 1993.

maintains an inventory of facilities subject to investigations concerning likely or threatened releases of The New York Department of Environmental Conservation, Bureau of Hazardous Site Control

hazardous substances from those facilities.

RCRA-TSD SRC#: 1372 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was July, 1993.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or

disposal of hazardous waste

B) DATABASES SEARCHED TO 1/2 MILE

SRC#: 1535 CERCLIS VISTA conducts a database search to identify all sites within 1/2 mile of your property. The agency release date for CERCLIS was November, 1993.

currently investigating for a release or threatened release of hazardous substances pursuant to the The CERCLIS List is a compilation by the EPA of the sites which the EPA has investigated or is

Comprehensive Environmental Response, Compensation and Liability Act of 1980 (Superfund Act).

LUST SRC#: 1515 VISTA conducts a database search to identify all sites within 1/2 mile of your property. The agency release date for LUST (Tank Test Failures) Database was October, 1993.

underground storage tanks. The New York Department of Environmental Conservation maintains an inventory of leaking

SWLF SRC#: 1248 VISTA conducts a database search to identify all sites within 1/2 mile of your property. The agency release date for Active Solid Waste Disposal Sites was April, 1993.

inventory of the solid waste facilities in the state The New York Department of Environmental Conservation, Division of Municipal Waste maintains an

SWLF VISTA conducts a database search to identify all sites within 1/2 mile of your property

SRC#: 1332 The agency release date for Recycler's Listing was April, 1993

inventory of the solid waste facilities in the state The New York Department of Environmental Conservation, Bureau of Municipal Waste maintains an



SWLF SRC#: 1333 The agency release date for Incinerators-Resource Recovery Projects was January, 1993 VISTA conducts a database search to identify all sites within 1/2 mile of your property.

inventory of the solid waste facilities in the state The New York Department of Environmental Conservation, Bureau of Waste Management maintains an

C) DATABASES SEARCHED TO 1/4 MILE

SRC#: 1514 The agency release date for Aboveground Storage Tanks was October, 1993. VISTA conducts a database search to identify all sites within 1/4 mile of your property

on thus list). an inventory of registered underground storage tanks (aboveground tanks are reported when included The New York Department of Environmental Conservation, Petroleum Bulk Storage Program maintains

SRC#: 1514 VISTA conducts a database search to identify all sites within 1/4 mile of your property. The agency release date for Underground Storage Tank Database was October, 1993.

on this list). an inventory of registered underground storage tanks (aboveground tanks are reported when included The New York Department of Environmental Conservation, Petroleum Bulk Storage Program maintains

D) DATABASES SEARCHED TO 1/8 MILE

ERNS SRC#: 1428 VISTA conducts a database search to identify all sites within 1/8 mile of your property. The agency release date for ERNS was September, 1993.

on reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the US Coast Guard, the National Response hazardous substances in the stated area. 1986 through September 1993 revealed the following information regarding reported spills of oil or Center and the Department of transportation. The Emergency Response Notification System (ERNS) is a national database used to collect information A search of the database records for the period October

SRC#: 1372 RCRA-LgGen VISTA conducts a database search to identify all sites within 1/8 mile of your property. The agency release date for HWDMS/RCRIS was July, 1993.

disposal of hazardous waste. compilation by the EPA of facilities which report generation, storage, transportation, treatment or waste from the point of generation to the point of disposal. The RCRA Facilities database is a The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous

SRC#: 1372 RCRA-SmGen VISTA conducts a database search to identify all sites within 1/8 mile of your property. The agency release date for HWDMS/RCRIS was July, 1993.

disposal of hazardous waste. waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous



SITE ASSESSMENT REPORT

RISK INVENTORY

2	2	2	-		poort	-	BA	
MERRY OLDS INC 777 SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714	JOHNS SOUTH BAY MOBIL 755 S OYSTER BAY RD BETHPAGE, NY 11714	ALPIAN II CLEANERS 339 S OYSTER BAY RD PLAINVIEW, NY 11803	TBG COGEN PARTNERS 939 SOUTH BROADWAY HICKSVILLE, NY 11801	C D TYPE SETTERS INC 960 SOUTH BROADWAY HICKSVILLE, NY 11801	AVIS CAR RENTAL 980 SOUTH BROADWAY BETHPAGE, NY 11714	TEXACO U.S.AA DIV. OF TEXACO INC. 1000 SOUTH BROADWAY HICKSVILLE, NY 11801	AND THE ADJACENT AREA (within 1/8 mile)	
			1				NPL SPL SCL TSD CERCLIS LUST SWLF UST ERNS LG GEN SM GEN	I
							SCL	- 12
							TSD	1
							CERCLIS	
ļ		ļ			×		LUST	. 5
				ļ			SWLF	
			×				UST	ſ
			ļ				EKNS	4
×	×		 	×	<u> </u>	×	LG GEN	•
	ļ	×	×		ļ		SM GEN	J.,
268888	127057	262775	1275656	7448	1118893	421625	NOTES MATA	

3 T 3 H	3 T 3 M	BAN
BLUE FLAME 3 WASHINGTON PARKWAY HICKSVILLE, NY 11801	ERM NORTHEAST 335 NEW SOUTH ROAD HICKSVILLE, NY 11801	RISK AT SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)
***************************************		NPL SPL SCL TSD CERCLIS LUST SWLF UST ERNS LG GEN SM GEN
		SCL
**************************************		CERCIIS
×	×	CERCLIS LUST SWLF UST ERNS LG GEN SM GEN
		SWLF
	·	UST C
		EKNS -
		SM GEN
_		NOTES
2739921	3506484	VISYA ID



4	ß	w	BAN
SLOMINS OIL 125 LAUMAN LANE HICKSVILLE, NY 11801	SERVO CORP 111 NEW S RD HICKSVILLE, NY 11801	BERTANE INC 121 NEW SOUTH ROAD HICKSVILLE, NY 11801	RISK AT SITES IN THE SURROUNDING AREA (within 14-17 mile)
NUMBER OF STREET			NPL SPL SPL TSD CERCLIS LUST SWLF UST CERNS LG GEN SM GEN
			SCL >
			TSD
×	×	<u> </u>	CERCLIS
		<u>×</u>	LUST 📼
			usi o
			ERNS
			LG GEN 🗢
			SM GEN
383950	374610	45505	NOTES .

6	V	e X
GRUMMAN AEROSPACE-BETHPAGE FACILITY STEWART AVENUE BETHPAGE, NY 11714	RUCO POL YMER CORPORATION NEW SOUTH ROAD HICKSVILLE, NY 11802	RISK AT SITES IN THE SURROUNDING AREA (within 1/2-1 mile)
	×	NPL
×	×	SPL
		SCL
		SCL TSD CERCLIS LUST #
		CERCLIS
		CERCLIS LUST #
		The state of the s
		UST O ERNS LG GEN S
		ERNS
****		LG GEN 🖾
		SM GEN
		3
		NOTES
		G
Ņ		2
2495698	362950	MSTA I

GRUMMAN GRUMMAN PLANT #17 BETHPAGE, NY 11714	GRUMMAN AEROSPACE GRUMMAN AEROSPACE PL #20 BETHPAGE, NY 11714	NAVAL WEAPONS INDUSTRIAL RESERVE PLA SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714 X	GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY RD BETHPAGE, NY 11714	NAVAL WEAPONS IND. RESERVE PLANT STEWART AVENUE BETHPAGE, NY 11714	NPL SPL SCL TSD CERCLIS LUST SWLF UST ERNS LG GEN SM GEN
					UST C ERNS LG GEN
					SM GEN
2720226	1337762	3624601	3624600	1123188	NOTES PISTA D



			>				, NY
3502316			¢				GLEN COVE T.S.
			>				, NY
3502289			<				ENERGY TACTICS OCEANSIDE
			>				, NY
2489228			ζ				SYOSSET LEAF COMPOST
			>				NY
2489061		-	₹				LAWRENCE (V)
3693147			X				UNK CUSTOMER 502 SO BROADWAY HICKSVILLE, NY 11801
1522341			×				JERICHO JEWISH CENTER NORTH BROADWAY HICKSVILLE, NY 11801
4111075			×				GRUMMAN BLDG #15 BETHPAGE, NY 11714
4111074			×				GRUMMAN AEROSPACE BUILDING 04-01-1 BETHPAGE, NY 11714
4111072			X				GRUMMAN AEROSPACE BLDG 115 BETHPAGE, NY 11714
4111071			X				GRUMMAN AEROSPACE BUILDING #1 BETHPAGE, NY 11714
4111070			×				GRUMMAN AEROSPACE BUILDING #2 GRUMMAN BETHPAGE, NY 11714
4111065			×				GRUMMAN AEROSPACE BUILDING 116-01-1 BETHPAGE, NY 11714
4701114			X				GRUMMAN AEROSPACE BLDG 111 BETHPAGE, NY 11714
NOTES:	ERNS LG GEN SM GEN	UST C	LUST =	TSD CERCLIS LUST SWLF UST	OPT T	NPL SPL	UNIMAPPED SITES
		3	7	1	1		



	×		2	5	"	
TSD CERCLIS	LUST	SWLF	TONG	LOCEN	SMCEN	NOTES PATA D
GARDEN CITY COMPOST		Χ				3502320
, NY	<u> </u>	<u> </u>				
HEMPSTEAD (OCEANSIDE) (T)		<				3502 34 7
, NY		,				
OLD BETHPAGE	4	<	~			3502496
,NY	L.				 	
ROCKVILLE CENTER T.S.		Κ	····		•	3502530
, NY	<u> </u>	<u> </u>		 	 	
NORTH HEMPSTEAD T.S.		×				3954909
,NY				 	 	



SITE ASSESSMENT REPORT

	RISK AT SITE AND WITHIN THE ADJACENT 1/8 MILE AREA	NT 1/8 MILE AREA	
Property Address with	TEXACO U.S.AA DIV. OF TEXACO IN Map ID#:	Map ID#:	1
VISTA Verified\Enhanced	VISTA Verified\Enhanced 1000 SOUTH BROADWAY	VISTA ID#:	421625
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	N/A
DETAILS REGARDING:	RCRA-LgGen / SOURCE# 1372	EPA ID	NYD000694448
Agency Address:	SAME AS ABOVE		THE PARTY PROPERTY AND ADDRESS OF THE PARTY PROPERTY.
Generator Class:	GENERATORS WHO GENERATE AT LEAST 1000 KG. MONTH OF NON-ACUTELY	ST 1000 KG.MONTH OF N	ON-ACUTELY
	HAZARDOUS WASTE OR I KG. MONTH OF ACUTELY HAZARDOUS WASTE	OF ACUTELY HAZARDOU	S WASTE.
Generator Req Violation:	NO		The state of the s
C.A.S. Violation:	NO		
Land Req Violation:	NO		

Remedial Status 2:	Remedial Status 1:	Remedial Action:	Leak Source:	Leak Cause:	Quantity:	Substance:	Media Affected:	Leak Date:	Tank Status:			Agency Address:	DETAILS REGARDING:	City and Zip:	VISTA Verified\Enhanced 980 SOUTH BROADWAY	Property Address with
NOT AVAILABLE FROM AGENCY	CASE CLOSED	NOT AVAILABLE FROM AGENCY	CAR	UNDERGROUND TANK LEAK	15.000000 GALLONS	GASOLINE (UNSPECIFIED)	NOT AVAILABLE FROM AGENCY	FEBRUARY 19, 1989	NOT AVAILABLE FROM AGENCY	BETHPAGE, NY	980 SOUTH BROADWAY	AVIS CAR RENTAL	LUST / SOURCE# 1515	BETHPAGE, NY 11714	980 SOUTH BROADWAY	AVIS CAR RENTAL
													Agency iD	Distance/Direction:	VISTA ID#:	Map ID#:
													8809010	N/A	1118893	

Property Address with	C D TYPE SETTERS INC	Map ID#:	
8	VISTA Verified/Enhanced 960 SOUTH BROADWAY	VISTA ID#:	74448
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.11MI/NW
DETAILS REGARDING:	DETAILS REGARDING: RCRA-LegGen / SOURCE# 1372	EPA ID	NYD982186983
Agency Address:	SAME AS ABOVE		
Generator Class:	GENERATORS WHO GENERATE AT LEAST 1000 KG./MONTH OF NON-ACUTELY	T 1000 KG./MONTH OF NO	ON-ACUTELY
	HAZARDOUS WASTE OR I KG. MONTH OF ACUTELY HAZARDOUS WASTE.	F ACUTELY HAZARDOUS	WASTE.
Generator Req Violation:	NO		
C.A.S. Violation:	NO		
Land Req Violation:	NO		



RISK	RISK AT SITE AND WITHIN THE ADJACENT 1/8 MILE AREA CONT	LNOO VANY THIN SAL	7.5
Property Address with	TBG COGEN PARTNERS	Map ID#:	1275656
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.12MI/NW
DETAILS REGARDING:	RCRA-SmGen / SOURCE# 1372	EPA ID	NYD987029691
Agency Address:	T B G COGEN PARTNERS 939 S BROADWAY HICKSVILLE, NY 11801		
Generator Class:	NERATE	LESS THAN 100 KG./MONTH OF NON-ACUTELY	NON-ACUTELY
Generator Req Violation:	NO		
C.A.S. Violation:	NO	The state of the s	
Land Req Violation:	NO		
DETAILS REGARDING:	UST / SOURCE# 1514	Agency ID	1-3280
Agency Address:	TBG COGEN PARTNERS 939 S BROADWAY HIGH NY 11801		
Underground Tanks:	0		
Aboveground Tanks:			
Tanks Removed:	0		
DETAILS REGARDING:	UST / SOURCE# 1514	Agency ID	1-3280
Agency Address:	939 S BROADWAY		
Tank ID:	7AG		
Contents:	FUEL OIL		
Age:	SOOOO (CALLONS)		
Status:	ACTIVE/IN SERVICE		
Leak Monitor:	MONITOR PRESENT		
Piping:	BARE STEEL		
Tank Material:	BARE STEEL		
DETAILS REGARDING:	UST / SOURCE# 1514	Agency ID	1-000129
Agency Address:	SAME AS ABOVE		
	0		
Aboveground lanks:	0		
DETAILS BEGARDING:	TIST / SOURCE# 1414	Agency ID	1-000129
Agency Address:	SAME AS ABOVE		
Tank ID:			
Contents:	NOT AVAILABLE FROM AGENCY		
Age:			
Statis:	ACTIVE IN SERVICE		
Leak Monitor:	MONITOR PRESENT		
Piping:	BARE STEEL		
Tank Material:	BARE STEEL		



For More Information Call VISTA Environmental Information at 1 - 800 - 767 - 0403

Report ID: 039300-001

Page #12

RISK	RISK AT SHE AND WITHIN THE ADUACENT 1/8 MILE AREA CONT	NT 1/8 MILE AREA CONT	
Property Address with	TBG COGEN PARTNERS	Map ID#:	-
VISTA Verified\Enhanced	VISTA Verified\Enhanced 939 SOUTH BROADWAY	VISTA ID#:	1275656
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.12MI/NW
DETAILS REGARDING:	UST/SOURCE# 1514	Agency ID	1-000129
Agency Address:	SAME AS ABOVE		
Tank ID:	12		
Contents:	ACID		
Age:	0		
Size (Units):	2100 (GALLONS)		
Status:	ACTIVE/IN SERVICE		
Leak Monitor:	MONITOR PRESENT		
Piping:	BARE STEEL		
Tank Material:	BARE STEEL		

Property Address with	ALPIAN II CLEANERS	Man ID#:	2
VISTA Verified\Enhanced 339 S OYSTER BAY RD	339 S OYSTER BAY RD	VISTA ID#:	262775
City and Zip:	PLAINVIEW, NY 11803	Distance/Direction:	N/A
DETAILS REGARDING:	RCRA-SmGen / SOURCE# 1372	EPA ID	NYD981081953
Agency Address:	SAME AS ABOVE		
Generator Class:	GENERATORS WHO GENERATE 100 KG. MONTH BUT LESS THAN 1000	MONTH BUT LESS THAN	1000
	KG./MONTH OF NON-ACUTELY HAZARDOUS WASTE	OUS WASTE	
Generator Req Violation: NO	NO		
C.A.S. Violation:	NO		
Land Req Violation:	NO		

Land Req Violation: NO	C.A.S. Violation: NO	Generator Req Violation: NO	HAZAI	Generator Class: GENEI	Agency Address: SAME	DETAILS REGARDING: RCRA	City and Zip: BETHI	VISTA Verified\Enhanced 755 S OYSTER BAY RD	Property Address with JOHN
			HAZARDOUS WASTE OR I KG, MONTH OF ACUTELY HAZARDOUS WASTE.	GENERATORS WHO GENERATE AT LEAST 1000 KG./MONTH OF NON-ACUTELY	SAME AS ABOVE	RCRA-LgGen / SOURCE# 1372	BETHPAGE, NY 11714	DYSTER BAY RD	JOHNS SOUTH BAY MOBIL
			OF ACUTELY HAZARDO	ST 1000 KG./MONTH OF		EPA ID	Distance/Direction:	VISTA ID#:	Map LU#:
			US WASTE.	NON-ACUTELY		NYD981555360	0.10MI / SE	127057	2

Land Req Violation:	C.A.S. Violation:	Generator Req Violation: NO	H	Generator Class: G	Agency Address: S	DETAILS REGARDING: R	City and Zip:	VISTA Verified\Enhanced 7	Property Address with
NO	O	O	HAZARDOUS WASTE OR I KG.MONTH OF ACUTELY HAZARDOUS WASTE	GENERATORS WHO GENERATE AT LEAST 1000 KG. MONTH OF NON-ACUTELY	SAME AS ABOVE	RCRA-LgGen / SOURCE# 1372	BETHPAGE, NY 11714	VISTA Verified\Enhanced 777 SOUTH OYSTER BAY ROAD	MERRY OLDS INC
			F ACUTELY HAZARDOUS	IT 1000 KG./MONTH OF NO		EPA ID	Distance/Direction:	VISTA ID#:	Map ID#:
			S WASTE.	ON-ACUTELY		NYD065956922	0.10MI / SE	268888	2



11	HESK SITES WITHEN THE SURROUNDING 1/0 - 1/4 MILE AREA	3 1/9 - 1/4 MILE AR EA	
Property Address with	ERM NORTHEAST	Map ID#:	3
8	335 NEW SOUTH ROAD	VISTA ID#:	3506484
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.22MI/NW
DETAILS REGARDING:	LUST/SOURCE#1515	Agency ID	9206957
Agency Address:	ERM NORTHEAST		***************************************
	335 NEW SOUTH ROAD		alla la constitución de la const
	HICKSVILLE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	SEPTEMBER 16, 1992		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CLEANUP IN PROGRESS		The state of the s
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Remedial Status 2:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Leak Source:	COMMERCIAL INDUSTRY		
Leak Cause:	UNDERGROUND TANK LEAK		
Quantity:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Leak Date:	AUGUST 28, 1987		
Tank Status:	NOT AVAILABLE FROM AGENCY		
	HICKSVILLE, NY		
,	3 WASHINGTON PARKWAY		
Agency Address:	BLUE FLAME		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction	tion:
VISTA Verified\Enhanced	VISTA Verified\Enhanced 3 WASHINGTON PARKWAY	VISTA ID#:	
Property Address with	BLUE FLAME	Map ID#:	



For More Information Call VISTA Environmental Information at 1 - 800 - 767 - 0403

Report ID: 039300-001

Date of Report: March 18, 1994

11	HENK SITES WITHIN THE SURROUNDING 1/4 - 1/2 MILE AREA	> 1/4 - 1/2 MILB ARBA	
Property Address with	BERTANE INC	Map ID#:	3
VISTA Verified\Enhanced	121 NEW SOUTH ROAD	VISTA ID#:	45505
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.25MI/NW
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9004626
Agency Address:	BERTANE INC		
,	121 NEW SOUTH ROAD		
	HICKSVILLE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	SEPTEMBER 11, 1987		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	NON-COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Start Date: Completion Date:	Event Status:	Lead Agency:	EventType:	Agency Address:	DETAILS REGARDING:	Completion Date:	Start Date:	Event Status:	Lead Agency:	EventType:	Agency Address:	DETAILS REGARDING:	Completion Date:	Start Date:	Event Status:	Lead Agency:	EventType:	Agency Address:	DETAILS REGARDING:	Site Description:	Lead Agency:	Facility Class:	NPL Status:	Agency Address:	DETAILS REGARDING:	City and Zip:	VISTA Verified\Enhanced	Property Address with
NOT AVAILABLE FROM AGENCY APRIL 10, 1980	NOT REPORTED	FUND LEAD	DISCOVERY	SAME AS ABOVE	CERCLIS / SOURCE# 1535	JANUARY 15, 1987	JANUARY 06, 1987	NOT REPORTED	FUND LEAD	PRELIMINARY ASSESSMENT	SAME AS ABOVE	CERCLIS / SOURCE# 1535	JUNE 26, 1991	APRIL 01, 1991	NOT REPORTED	FUND LEAD	SCREENING SITE INSPECTION	SAME AS ABOVE	CERCLIS / SOURCE# 1535	NOT AVAILABLE FROM AGENCY	NO DETERMINATION	AGENCY REPORTS THE UNDEFINED TERM "OTHER"	NOT PROP/CURR/DELE NPL	SAME AS ABOVE	CERCLIS / SOURCE# 1535	HICKSVILLE, NY 11801	111 NEW S RD	SERVO CORP
					EPA ID							EPA ID			Andreas - Landerstein - Lander				EPA ID			RM "OTHER"			EPAID I	Distance/Direction:	12	Map ID#:
					NYD002418911							NYD002418911				in the state of th			NYD002418911						NYD002418911	0.25MI/NW	374610	3



\$1518	RIBK STIES WITHIN THE SURROUNDING 1/4-1/2 MILE AREA CONT	- 1/2 MILE AREA CON	
Property Address with	SIOMINS OIL	Map ID#:	4
VISTA Verified\Enhanced	125 LAUMAN LANE	VISTA ID#:	383950
City and Zip:	HICKSVILLE, NY 11801	Distance/Direction:	0.42MI / SE
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	8910541
Agency Address:	SLOMINS OIL		
	125 LAUMAN LANE		
	HICKSVILLE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	APRIL 17, 1991		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

	RISK SITES IN THE SURROUNDING 1/2 - 1 MILE AREA	- I MILE AREA	
Property Address with	RUCO POLYMER CORPORATION	Map ID#:	5
E C	NEW SOUTH ROAD	VISTA ID#:	362950
City and Zip:	HICKSVILLE, NY 11802	Distance/Direction:	0.66MI/N
DETAILS REGARDING:	SPL/SOURCE# 1412	Agency ID	130004
Agency Address:	RUCO POLYMER CORP. (HOOKER CHEM))	
	NEW SOUTH ROAD		
NPL Status:	NOT AVAILABLE FROM AGENCY		
Facility Type:	PURE LAGOONS		
Lead Agency:	NOT AVAILABLE FROM AGENCY		
State Status:	NOT AVAILABLE FROM AGENCY		
Pollutant:	METHYL/ETHYL		
Description:	NOT AVAILABLE FROM AGENCY		TOTAL DESIGNATION OF THE PROPERTY OF THE PROPE
DETAILS REGARDING:	SPE/SOURCE#1412	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
NPL Status:	NOT AVAILABLE FROM AGENCY		
Facility Type:	PURE LAGOONS		
Lead Agency:	NOT AVAILABLE FROM AGENCY		
State Status:	NOT AVAILABLE FROM AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Pollutant:	PCB'S		
Description:	NOT AVAILABLE FROM AGENCY		



2	RISK SITES IN THE SURROUNDING 1/2 - 1 MILE AREA CONT	I MILE AREA CONT.	
Property Address with	RUCO POLYMER CORPORATION	Map ID#:	5
City and Zip:	HICKSVILLE, NY 11802	Distance/Direction:	0.66MI/N
DETAILS REGARDING:	SPL/SOURCE# 1412	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
NPL Status:	NOT AVAILABLE FROM AGENCY	in the second of	Martine Committee of the Committee of th
Facility Type:	PURE LAGOONS		
Lead Agency:	NOT AVAILABLE FROM AGENCY		
Pollutant:	ORGANICS		
Pollutant:	WEIHYL/EIHYL		
Pollutant:	METHYL/ETHYL		
Description:	NOT AVAILABLE FROM AGENCY		A STATE OF THE PROPERTY OF THE
DETAILS REGARDING:	NPL / SOURCE# 1622	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
NPL Status:	CURRENTLY ON FINAL NPL		
Lead Agency:	FEDERAL ENFORCEMENT		
Site Description:	NOT AVAILABLE FROM AGENCY		
DETAILS REGARDING:	NPL / SOURCE# 1622	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
EventType:	SCREENING SITE INSPECTION		
Event Status:	NOT REPORTED		Y-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
Start Date:	SEPTEMBER 01, 1984		The state of the s
Completion Date:	OCTOBER 01, 1984		
DETAILS REGARDING:	NPL / SOURCE# 1622	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
Lead Agency:	NOT AVAILABLE FROM AGENCY		MATERIAL PROPERTY OF THE PROPE
Event Status:	NOT REPORTED		
Start Date:	NOT AVAILABLE FROM AGENCY		
Completion Date:	SEPTEMBER 01, 1984		
DETAILS REGARDING:	NPL / SOURCE# 1622	EPA/Agency ID	N/A
Agency Address: EventType:	PROPOSED FOR NPI		
Lead Agency:	FUND LEAD		
Event Status:	NOT REPORTED		
Start Date: Completion Date:	NOT AVAILABLE FROM AGENCY OCTOBER 15, 1984		
RDING:	NPT. / SOURCE# 1622	EPA/Agency ID	N/A
Ш	SAME AS ABOVE		
	NO FURTHER ACTION		
Lead Agency:	FUND LEAD		
Start Date:	NOT AVAILABLE FROM AGENCY	il .	
Completion Date:	JUNE 10, 1986		



R	RISK SITES IN THE SURROUNDING 1/2 - 1 MILE AREA CONT	MILE AREA CONT.	
Property Address with	RUCO POLYMER CORPORATION	Map ID#:	5
VISTA Verified\Enhanced NEW SOUTH ROAD	NEW SOUTH ROAD	VISTA ID#:	362950
City and Zip:	HICKSVILLE, NY 11802	Distance/Direction:	0.66MI/N
DETAILS REGARDING:	NPL / SOURCE# 1622	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
EventType:	DISCOVERY		
Lead Agency:	FUND LEAD		
Event Status:	NOT REPORTED		
Start Date:	NOT AVAILABLE FROM AGENCY		The state of the s
Completion Date:	NOVEMBER 01, 1979		

		NOT AVAILABLE FROM AGENCY	Description:
		METALS	Pollutant:
		PAINT/PAINT THINNER	Pollutant:
		ALUMINUM	Pollutant:
		NOT AVAILABLE FROM AGENCY	State Status:
		STATE	Lead Agency:
		LANDFILL	Facility Type:
		NOT AVAILABLE FROM AGENCY	NPL Status:
		SAME AS ABOVE	Agency Address:
N/A	EPA/Agency ID	SPL/SOURCE#1412	DETAILS REGARDING:
		NOT AVAILABLE FROM AGENCY	Description:
		SOLVENTS	Pollutant:
		NOT AVAILABLE FROM AGENCY	State Status:
		STATE	Lead Agency:
		LANDFILL	Facility Type:
		NOT AVAILABLE FROM AGENCY	NPL Status:
		SAME AS ABOVE	Agency Address:
130003A	Agency ID	SPE/SOURCE#1412	DETAILS REGARDING:
0.97MI/NE	Distance/Direction:	BETHPAGE, NY 11714	City and Zip:
2495698	VISTA ID#:	STEWART AVENUE	VISTA Verified\Enhanced
6	Map ID#:	GRUMMAN AEROSPACE-BETHPAGE	Property Address with

	UNMAPPED SITES		
Property Address with	NAVAL WEAPONS IND. RESERVE PLA VISTA ID#	VISTA ID#:	4123188
VISTA Verified\Enhanced STEWART AVENUE City and Zip: BETHPAGE, NY 1171	STEWART AVENUE BETHPAGE, NY 11714		
DETAILS REGARDING:	SPL/SOURCE# 1412	Agency ID	130003В
Agency Address:	SAME AS ABOVE		
NPL Status:	NOT AVAILABLE FROM AGENCY		
Facility Type:	LANDFILL		
Lead Agency:	FUND LEAD		
State Status:	NOT AVAILABLE FROM AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Pollutant:	LEAD		
Description:	NOT AVAILABLE FROM AGENCY		



	UNMAPPED SITES CONT		
Property Address with	NAVAL WEAPONS IND. RESERVE PLA VISTA ID#:	VISTA ID#:	4123188
VISTA Verified/Enhanced STEWART AVENUE	STEWART AVENUE		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	SPL/SOURCE#1412	EPA/Agency ID	N/A
Agency Address:	SAME AS ABOVE		
NPL Status:	NOT AVAILABLE FROM AGENCY		
Facility Type:	LANDFILL		
Lead Agency:	FUND LEAD	AND AND THE PROPERTY OF THE PR	
State Status:	NOT AVAILABLE FROM AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Pollutant:	REPORTED AS "UNKNOWN" BY AGENCY		
Description:	NOT AVAILABLE FROM AGENCY		

Property Address with GRUMMAN ALEROSPACE CORP VISTA Verified/Enhanced SOUTH OYSTER BAY RD				
BETHPAGE, NY 11714	Property Address with VISTA Verified/Enhanced	GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY RD	VISTA ID#:	3624600
DING: RCRA-TSD / SOURCE# 1372 EPA ID	City and Zip:	BETHPAGE, NY 11714		
GRUMMAN AEROSPACE SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714 NOT AVAILABLE FROM AGENCY NO YES YES YES YES YES YES YES YES YES YOUT AVAILABLE FROM AGENCY 0 DING: LUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY DILSEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	DETAILS REGARDING:	RCRA-TSD / SOURCE# 1372	EPA ID	NYD002047967
SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714 NOT AVAILABLE FROM AGENCY NO YES YES YES YES YES YES YES YE	Agency Address:	GRUMMAN AEROSPACE		
NOT AVAILABLE FROM AGENCY NO YES YES		SOUTH OYSTER BAY ROAD RETTEPAGE NY 11714		
NO	Permit Status:	NOT AVAILABLE FROM AGENCY		
MO	Offsite Waste Rec:	NO		
NO YES YES	Land Disposal:	NO		
YES lation: YES YES YES YES YES YES NOT A VAILABLE FROM AGENCY O	Incinerator:	NO		
Iation: YES	Storage Treatment:	YES		
YES YES YES YES NOT AVAILABLE FROM AGENCY O LUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.000000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Ground Water Violation:	YES		
YES YES YES NOT AVAILABLE FROM AGENCY O LUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Closure Violation:	YES		
YES YES NOT AVAILABLE FROM AGENCY ILUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Fin Req Vio:	YES		
YES VES NOT AVAILABLE FROM AGENCY ILUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Corr Act Vio:	YES		
YES NOT AVAILABLE FROM AGENCY IUST / SOURCE# 1515 GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Land Ban Vio:	YES		
NOT AVAILABLE FROM AGENCY DING: LUST / SOURCE# 1515 Agency ID GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY OT AT	Other Req Vio:	YES		
DING: LUST / SOURCE# 1515 Agency ID GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY JULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.00000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Process Codes:	NOT AVAILABLE FROM AGENCY		
DING: LUST / SOURCE# 1515 Agency ID GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY IULY 12, 1993 NOT AVAILABLE FROM AGENCY DIESEL 5.000000 GALLONS UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY CASE CLOSED NOT AVAILABLE FROM AGENCY	Waste Codes:	0		
	DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9306867
	Agency Address:	GRUMMAN PLANT #25		
		SO OYSTER BAY ROAD BETHPAGE, NY		
	Tank Status:	NOT AVAILABLE FROM AGENCY		
	Leak Date:	JULY 12, 1993		
	Media Affected:	NOT AVAILABLE FROM AGENCY		
	Substance:	DIESEL	The same and a same and a same and a same and a same a same and a same a same a same a same a same a same a sa	
	Quantity:	5.000000 GALLONS		
	Leak Cause:	UNDERGROUND TANK LEAK		
	Leak Source:	COMMERCIAL INDUSTRY		
	Remedial Action:	NOT AVAILABLE FROM AGENCY		
	Remedial Status 1:	CASE CLOSED		
	Remedial Status 2:	NOT AVAILABLE FROM AGENCY		



	UNMAPPED SITES CONT		
Property Address with: VISTA Verified\Enhanced City and Zip:	GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY RD BETHPAGE, NY 11714	VISTA ID#:	3624600
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9304538
Agency Address:	GRUMMAN AERO SOUTH OYSTER BAY ROAD BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY MAY 25 1989		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	DIESEL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		
DETAILS REGARDING: Agency Address:	LUST / SOURCE# 1515 GRUMMAN SO OVETER BAY BOAD	Agency ID	9303257
Tank Status:	SO OYSTER BAY ROAD BETHPAGE, NY NOT AVAILABLE FROM AGENCY		
Leak Date:	APRIL 16, 1991		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CLEANUP IN PROGRESS		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NYD002047967
Agency Address: NPL Status:	NOT PROP/CURR/DELE NPL		
Facility Class:	AGENCY REPORTS THE UNDEFINED TERM "OTHER"	M "OTHER"	
Lead Agency: Site Description:	NO DETERMINATION NOT AVAILABLE FROM AGENCY		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NYD002047967
Agency Address: EventType:	PRELIMINARY ASSESSMENT		
	FUND LEAD		
Event Status: Start Date:	NOT AVAILABLE FROM AGENCY	ED	
Completion Date:	JANUARY 01, 1980		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NYD002047967
EventType:	DISCOVERY		
Lead Agency:	FUND LEAD		
Event Status:	NOT AVAIT ABLE FROM AGENICY		
Completion Date:	DECEMBER 01, 1979		



	THOS CONT		
Property Address with	NAVAL WEAPONS INDUSTRIAL RESE	VISTA ID#:	3624601
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NY2170022162
Agency Address:	SAME AS ABOVE		
NPL Status:	NOT PROP/CURR/DELE NPL	The state of the s	
Facility Class:	FEDERALLY OWNED		
Lead Agency:	NO DETERMINATION		
Site Description:	NOT AVAILABLE FROM AGENCY		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NY2170022162
Agency Address:	SAME AS ABOVE		
EventType:	SCREENING SITE INSPECTION		
Lead Agency:	NOT AVAILABLE FROM AGENCY		A Make and the Straight of the Contract
Event Status:	NOT REPORTED		
Start Date:	NOT AVAILABLE FROM AGENCY		
Completion Date:	SEPTEMBER 30, 1992		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NY2170022162
Agency Address:	SAME AS ABOVE		
EventType:	PRELIMINARY ASSESSMENT		
Lead Agency:	NOT AVAILABLE FROM AGENCY		
Event Status:	NOT REPORTED		
Start Date:	DECEMBER 21, 1988		
Completion Date:	DECEMBER 29, 1988		
DETAILS REGARDING:	CERCLIS / SOURCE# 1535	EPA ID	NY2170022162
Agency Address:	SAME AS ABOVE		
EventType:	DISCOVERY	And the second s	
Lead Agency:	FUND LEAD		
Event Status:	NOT REPORTED		
Start Date:	NOT AVAILABLE FROM AGENCY		
Completion Date:	FEBRUARY 17, 1987		

Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	1337762
VISTA Verified\Enhanced	VISTA Verified\Enhanced GRUMMAN AEROSPACE PL #20		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9304043
Agency Address:	GRUMMAN AEROSPACE		
	GRUMMAN AEROSPACE PL #20		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	JUNE 29, 1993		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	DIESEL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CLEANUP IN PROGRESS		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		



	URMAPPED SITES CONT	3	
Property Address with	GRUMMAN	VISTA ID#:	2720226
8	GRUMMAN PLANT #17		-
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9105709
Agency Address:	GRUMMAN		
	GRUMMAN PLANT #17		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	AUGUST 26, 1991		
Media Affected:	NOT AVAILABLE FROM AGENCY		With the second
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CLEANUP IN PROGRESS		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	4111064
8	BLDG 111		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9001711
Agency Address:	GRUMMAN AEROSPACE		
	BLDG 111		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	MAY 14, 1990		
Media Affected:	NOT AVAILABLE FROM AGENCY	A THE REAL PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE	
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY	A CALL TO THE PARTY OF THE PART	
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CLEANUP IN PROGRESS		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		



	UNMAPPED SITES CONT		
Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	4111065
8	BUILDING 116-01-1		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	8901526
Agency Address:	GRUMMAN AEROSPACE		
	BUILDING 116-01-1		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	MAY 16, 1989	According to the control of the cont	
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL	The state of the s	
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	FIXED FACILITY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Remedial Status 2: NO	Remedial Status 1: CA	Remedial Action: NO	Leak Source: CO	Leak Cause: UN	Quantity: NO	Substance: FUI	Media Affected: NO	Leak Date: AU	Tank Status: NO	BE		Agency Address: GRI	DETAILS REGARDING: LUI	City and Zip: BE'	VISTA Verified\Enhanced BUILDING #2 GRUMMAN	Property Address with GR	
NOT AVAILABLE FROM AGENCY	CASE CLOSED	NOT AVAILABLE FROM AGENCY	COMMERCIAL INDUSTRY	UNDERGROUND TANK LEAK	NOT AVAILABLE FROM AGENCY	FUEL OIL	NOT AVAILABLE FROM AGENCY	AUGUST 19, 1987	NOT AVAILABLE FROM AGENCY	BETHPAGE, NY	BUILDING #2 GRUMMAN	GRUMMAN AEROSPACE	LUST / SOURCE# 1515	BETHPAGE, NY 11714	ILDING #2 GRUMMAN	GRUMMAN AEROSPACE	
													Agency ID			VISTA ID#:	
													8704145			4111070	



	UNMAPPED SITES CONT	6	
Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	4111071
VISTA Venified/Enhanced	BUILDING #1		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	8705197
Agency Address:	GRUMMAN AEROSPACE		
	BUILDING #1		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	SEPTEMBER 21, 1987	The state of the s	TOTAL
Media Affected:	NOT AVAILABLE FROM AGENCY	And the second s	
Substance:	JET FUEL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK	Add the second s	
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	4111072
VISTA Verified\Enhanced	BLDG 115		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	8807239
Agency Address:	GRUMMAN AEROSPACE		
	BLDG 115		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	DECEMBER 01, 1988		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		



	UNMAPPED SITES CONT		
Property Address with	GRUMMAN AEROSPACE	VISTA ID#:	4111074
8.	BUILDING 04-01-1		
City and Zip:	BETHPAGE, NY 11714		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	8901527
Agency Address:	GRUMMAN AEROSPACE		
,	BUILDING 04-01-1		
	BETHPAGE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		The state of the s
Leak Date:	MAY 12, 1989		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	FIXED FACILITY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED	The state of the s	
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Demonial Action: NO AVAILABLE TROM ACTING
UNDERGROUND TANK LEAK COMMERCIAL INDUSTRY NOT AVAILABLE FROM AGENCY
NOT AVAILABLE FROM AGENCY
Media Affected: NOT AVAILABLE FROM AGENCY
MAY 19 1989
Agency Address: GRUMMAN BLDG #15 BETHPAGE, NY
DETAILS REGARDING: LUST / SOURCE# 1515
City and Zip: BETHPAGE, NY 11714



For More Information Call VISTA Environmental Information at 1 - 800 - 767 - 0403

Report ID: 039300-001

Page #25

	LINMAPPED SITES CONT	7	
Property Address with	JERICHO JEWISH CENTER	VISTA ID#:	1522341
VISTA Verified\Enhanced. City and Zip:	NORTH BROADWAY HICKSVILLE, NY 11801		
DETAILS REGARDING:	LUST/SOURCE#1515	Agency ID	9009442
Agency Address:	JERICHO JEWISH CENTER		
,	NORTH BROADWAY		
	HICKSVILLE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		The state of the s
Leak Date:	NOT AVAILABLE		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY		
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	NON-COMMERCIAL INDUSTRY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

		¥	
Property Address with	UNK CUSTOMER	VISTA ID#:	3693147
VISTA Verified/Enhanced 502 SO BROADWAY	502 SO BROADWAY		
City and Zip:	HICKSVILLE, NY 11801		
DETAILS REGARDING:	LUST / SOURCE# 1515	Agency ID	9205657
Agency Address:	UNK CUSTOMER		
,	502 SO BROADWAY		
	HICKSVILLE, NY		
Tank Status:	NOT AVAILABLE FROM AGENCY		
Leak Date:	MARCH 24, 1992		
Media Affected:	NOT AVAILABLE FROM AGENCY		
Substance:	FUEL OIL		
Quantity:	NOT AVAILABLE FROM AGENCY	and have been served to the served of the se	
Leak Cause:	UNDERGROUND TANK LEAK		
Leak Source:	FIXED FACILITY		
Remedial Action:	NOT AVAILABLE FROM AGENCY		
Remedial Status 1:	CASE CLOSED		
Remedial Status 2:	NOT AVAILABLE FROM AGENCY		

Property Address with	LAWRENCE (V)	VISTA ID#:	2489061
8			
City and Zip:	, NY		
DETAILS REGARDING:	SWLF / SOURCE# 1248	Agency ID	30C14
Agency Address:	SAME AS ABOVE		
Facility Type:	AGENCY REPORTS THE UNDEFINED TERM "OTHER"	M "OTHER"	
Facility Status:	ACTIVE		
Facility Life:	0		
Permit Status	PERMITTED/LICENSED		
Waste:	SLUDGE/SEPTAGE		



			֡
Property Address with	SYOSSET LEAF COMPOST	VISTA ID#:	2489228
VISTA Venified\Enhanced			
City and Zip:	, NY		
DETAILS REGARDING:	DETAILS REGARDING: SWLF / SOURCE# 1248	Agency ID	30Y15
Agency Address:	SAME AS ABOVE		
Facility Type:	RUBBLE FILL (DEMO,ETC)	Management of the second of th	
Facility Status:	ACTIVE		
Facility Life:	0		
Permit Status	PERMITTED/LICENSED		
Waste:	LEAVES/CLIPPINGS		

Waste:	Permit Status	Facility Life:	Facility Status:	Facility Type:	Agency Address:	DETAILS REGARDING: SWLF / SOURCE# 1248	City and Zip:	VISTA Verified\Enhanced	Property Address with
NOT AVAILABLE FROM AGENCY	PERMITTED/LICENSED	0	ACTIVE	AGENCY REPORTS THE UNDEFINED TERM "OTHER"	SAME AS ABOVE	SWLF / SOURCE# 1248	, NY		ENERGY TACTICS OCEANSIDE
		The state of the s		M "OTHER"	The second secon	Agency ID			VISTA ID#:
						30F13			3502289

		NOT AVAILABLE FROM AGENCY	Waste:
		UPGRADE ORDER	Permit Status
		0	Facility Life:
		ACTIVE	Facility Status:
		TRANSFER STATION	Facility Type:
		SAME AS ABOVE	Agency Address:
30T29	Agency ID	SWLF/SOURCE# 1248	DETAILS REGARDING:
		, NY	City and Zip:
			VISTA Verified\Enhanced
3502316	VISTA ID#:	GLEN COVE T.S.	

		NOT AVAILABLE FROM AGENCY	Waste:
		UNPERMITTED/UNLICENSED	Permit Status
		0	Facility Life:
		ACTIVE	Facility Status:
		RUBBLE FILL (DEMO,ETC)	Facility Type:
		SAME AS ABOVE	Agency Address:
30Y16	Agency ID	SWLF / SOURCE# 1248	DETAILS REGARDING:
		, NY	City and Zip:
			VISTA Verified\Enhanced
3502320	VISTA ID#:	GARDEN CITY COMPOST	Property Address with



	UNDARPRES STIES CONT.	7	
Property Address with	HEMPSTEAD (OCEANSIDE) (T)	VISTA ID#:	3502347
VISTA Venified\Enhanced			
City and Zip:	, NY		
DETAILS REGARDING:	SWLF / SOURCE# 1248	Agency ID	30T19
Agency Address:	SAME AS ABOVE		- interface in the second of t
Facility Type:	TRANSFER STATION		
Facility Status:	ACTIVE		
Facility Life:	0		
Permit Status	PERMITTED/LICENSED		
Waste:	HOUSEHOLD		William Control of the Control of th

Property Address with VISTA Verified\Enhanced	OLD BETHPAGE	VISTA ID#:	3502496
City and Zip:	, NY		
DETAILS REGARDING: SWLF / SOURCE# 1248	SWLF / SOURCE# 1248	Agency ID	30F07
Agency Address:	SAME AS ABOVE		
Facility Type:	AGENCY REPORTS THE UNDEFINED TERM "OTHER"	M "OTHER"	
Facility Status:	ACTIVE	The state of the s	- Company of the Comp
Facility Life:	0	A STATE OF THE STA	
Permit Status	PERMITTED/LICENSED		
Waste:	NOT AVAILABLE FROM AGENCY		

		110000110000	17 GOLG.
		HOLISEHOLD	Waste
		PERMITTED/LICENSED	Permit Status
		0	Facility Life:
		ACTIVE	Facility Status:
		TRANSFER STATION	Facility Type:
		SAME AS ABOVE	Agency Address:
30T08	Agency ID	SWLF / SOURCE# 1248	DETAILS REGARDING:
		, NY	City and Zip:
			VISTA Verified\Enhanced
3502530	VISTA ID#:	ROCKVILLE CENTER T.S.	Property Address with

			7054000
Property Address with	ZOXIH HEMPUTEAU I.U.	VISIA D#:	3734707
VISTA Verified\Enhanced			
City and Zip:	, NY		
DETAILS REGARDING:	DETAILS REGARDING: SWLF / SOURCE# 1248	Agency ID	30T28
Agency Address:	SAME AS ABOVE		
Facility Type:	TRANSFER STATION		
Facility Status:	ACTIVE		
Facility Life:	0		
Permit Status	UPGRADE ORDER		
Waste:	HOUSEHOLD		



For More Information Call VISTA Environmental Information at 1 - 800 - 767 - 0403

Report ID: 039300-001

Date of Report: March 18, 1994

ATTACHMENT 2

SANBORN MAPS

(



March 31, 1994

DVIRKA & BARTILUCCI-SYOSSET 6800 JERICHO TPKE SYOSSET, NY 11791

address: SANBORN MAP-SITE SEARCH was conducted on the following

Name/Ref#: LINDEN TRUE SITE

Address: 789 S BROWDWAY , City/St/Zip: HICKSVILL, NY 11802

Vista Order#: 266002

SANBORN certifies that a and no SANBORN MAPS are a certification on file. The on a separate invoice. Y greatly appreciated. The charge for the group track of VISTA I Ω. of their holdings
has this letter of
search will be sent
for this service is ₽. **U**

Document Retrieval Service VISTA ENVIRONMENTAL INFORMATION, INC.

<u>:</u>

;

;