



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION

Original-BHSC
Copy-REGION
Copy-DEE
Copy-DOH
Copy-PRÉPARER

REGISTRY SITE CLASSIFICATION DECISION

1. SITE NAME FORMER HOPEWELL PRECISION		2. SITE NUMBER 314052	3. TOWN/CITY/VILLAGE EAST FISHKILL	4. COUNTY DUTCHESS
5. REGION 3	6. CLASSIFICATION CURRENT 2A PROPOSED D1 MODIFY			
7. LOCATION OF SITE (Attach U.S.G.S. Topographic Map showing site location)				
a. Quadrangle: Hopewell Junction b. Site Latitude 36° 39' 55" ^{41° 51' 39.8"} c. Tax Map Number: SECTION 655 - 801 BLOCK 0727 LOT 710				
8. BRIEFLY DESCRIBE THE SITE (Attach site plan showing disposal/sampling locations)				
The site is approximately a 1 acre lot that is presently used by the owner, Nicholas Brothers Moving Co., for storage. Hopewell Precision operated a machine shop at the site until 1981, when they moved next door to a new facility. See Attachment II for a site sketch. Attachment III is a copy of the USGS Quad for Hopewell Junction. DEC performed both a Phase I and II at the site during the 1980's. During the Phase II, three monitoring wells were installed. At the time only one was found to contain TCE. In 1993 the PRP and the DEC took samples at the site of the wells and the tap water. Nothing was detected.				
a. Area 1 acres b. EPA ID Number NYD066813064 c. Completed (X)Phase I (X)Phase II () PSA ()RI/FS ()PA/SI (X)Other-				

9. Hazardous Waste Disposed (Include EPA Hazardous Waste Numbers)
None

10. ANALYTICAL DATA AVAILABLE

a. ()Air (X)Groundwater ()Surface Water ()Sediment ()Soil ()Waste ()Leachate ()EPTox
()TCLP

b. Contravention of Standards or Guidance Values
Three onsite wells, two drinking water wells, and a storm drain were sampled in April 1993. DEC split samples - Non Detect PRP Results 2ppb TCE in a monitoring well

See Attachment IV for DEC results and Attachment V for PRP results.

11. JUSTIFICATION FOR CLASSIFICATION DECISION

Although low levels were detected in the well during the mid 80's, the latest round of sampling revealed levels less than 2 ppb of TCE. The site has not been used as a machine shop for over twelve years. The hazardous waste allegedly disposed has never been located nor any evidence of it found, therefore the site should be delisted from a 2A to D1.

12. SITE IMPACT DATA

a. Nearest Surface Water: Distance:100ft	Direction:South West	Classification : NA
b. Nearest Groundwater:Depth:10ft	Flow Direction: SW	()Sole Source ()Primary ()Principal
c. Nearest Water Supply: Distance 0	Direction On site	Active (X)Yes ()No
d. Nearest Building: Distance 0 ft.	Direction On site	Use: Storage, Commercial
e. In State Economic Development Zone?	()Y (X)N	i. Controlled Site Access? (X)Y ()N
f. Crops or livestock on site?	()Y (X)N	j. Exposed hazardous waste? ()Y (X)N
g. Documented fish or wildlife mortality?	()Y (X)N	k. HRS Score N/A
h. Impact on special status fish or wildlife resource?	()Y (X)N	l. For Class 2: Priority Category N/A

13. SITE OWNER'S NAME John DeNicholas, Sr.	14. ADDRESS Ryan Road, Hopewell Junction	15. 914/ 221 - 0430
--	--	-------------------------------

16. PREPARER <i>[Signature]</i> Signature Daniel Bendell, DHWR - Region 3 Name Title Organization	October 7, 1993 Date	17. APPROVED <i>[Signature]</i> Signature Ass't Dir. Name Title Organization	Date
--	-------------------------	---	------