

## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

## Inactive Hazardous Waste Site Operations and Maintenance Review Report

			Form Date 6/13/02
Site Name: Camden Wire		Class: 4	Number: 633002
O&M Funding Source: ☐ State Sup	erfund   Federal Super	fund 🔲 Municipa	Responsible Party
O&M Information: O&M Start: ?	End:	Annual Cos	t: \$
Interim Remedial Measures/Operable Un  Drum Removal Cap/Cover Groundwater Recovery/Treatment Air Sparging/Stripper System Other: Institutional Controls: Deed Restrict Other: O&M Review Information: Reports:	nits in O&M Phase:  Soil Removal Containment Structure Leachate Collection/Treat Treatment/Filtration Plant tion Discharge Pe	☐ Tank F☐ Fence tment ☐ Vapor /System ☐ Potabl ermit ☐ Dep	Removal
Conclusions:			
Remedy Effective?   Yes   No: _?			
ROD Compliance?			
Consent Order Compliance? ☐ Yes	□ No: ?		
Other:			***************************************
Recommendations: According to Peter Ouderkirk, the seepage into Fish Creek should be sampled. In order to de-list this site, a petition must be made by Camden Wire. The first thing we need to do is meet with the RP to discuss the status of the site, and inform them that OM&M needs to be conducted in order to de-list the site from the Registry. We will need to determine the number of wells needed, number of sampling rounds needed, and analysis requirements for samples. We need to determine which 2 lagoons were remediated and their location relative to monitoring wells so that a monitoring and closure sampling plan can be developed. We need to determine if the 2 new monitoring wells were installed and if not, decide whether or not we need to put some in, so we can conduct monitoring to determine if the site needs OM&M, or if they were installed, were they drilled to 15 feet and why? If drinking water wells are in use, then DOH should be contacted for possible sampling. We need to determine how to prevent damage to wells that could be a result from car racing on the site, i.e. we might want to install a fence around the monitoring wells. Finally, we need to get a copy of the deed restriction for our files.			
ROD/Consent Order Modifications?	Yes (per above) Recl	assify the Site?	No ☐ Yes → Class:
Comments: A thorough file review was conducted in Spring 2002 and a conference call was held with Peter Ouderkirk of the discuss the status of the site. It seems OM&M has never been done. A memo summarizing the status and identifying actions which should be taken was written from Bill Peters to Peter in June 2002. The actions are summarized in the recommendations above.  Next Mexico 3/03			
Signature Sue Lasdin BHSC		ignature  J. Rider Jr. BHSC Name Region or Bu	