



Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Columbia Mills		Class: 4	Number: 7-38-012
O&M Funding Source: <input checked="" type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input type="checkbox"/> Responsible Party			
O&M Information: O&M Start: 96/07 End: Annual Cost: \$3100 <input checked="" type="checkbox"/> Estimated			
Interim Remedial Measures/Operable Units in O&M Phase:			
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal (follow up inspection)	<input type="checkbox"/> Tank Removal	
<input checked="" type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input checked="" type="checkbox"/> Other: GW / leachate / sediment sampling			
Institutional Controls: <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input type="checkbox"/> Other:			
O&M Review Information:			
Reports: Analytical results and sampling notes			
Inspection: 3/14/00 & 9/21-22/00 by DER CO sampling teams, Region 7 Operations for mowing			
Sampling: 3/14 leachate/sediment; 9/21-22 leachate/sediment/GW			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: effluent continues to meet discharge limits			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No:			
Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No:			
Other: landfill cover continues to be in good condition. Trespass activity by ATV users has compromised the integrity of the fence. Operations will be asked to make repairs.			
Remedial Activities: Leachate / sediment sampling frequency has not yet been reduced, but is still recommended.			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: Access to the site can no longer be obtained from Barrett Dr.; A Mr. Robert Pekarek, 203 Craw Road, Mexico, (315-963-8609), is purchasing the former worker housing from Oswego County. Mr. Pekarek asserts the Town of Minetto has given him permission to block access. At the time of the 9/21/00 sampling access could not be gained by Chase Drive due to a fallen tree. A County Sheriff called by Mr. Pekarek said he would inform the Town of the need to remove the tree. DER will follow up with letters to the Town and Mr. Pekarek confirming the need for access to the site. According to Mr. Pekarek, plans to convert the former factory building to senior housing are proceeding. This project will require the construction of additional points of ingress and egress to the building. It is not clear at this time if this will affect the landfill or amphibian breeding pond area.			
Project Manager:		Reviewer:	
			
October 26, 2000		10/27/00	
Signature		Signature	
Date		Date	
Cynthia A. Whitfield,	CO	Thomas Reamon	BHSC
Name	Region or Bureau	Name	Region or Bureau
457-0639	Telephone	7-9538	Telephone