

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 96.10.01

Site Name: Tioga Casting Facilities **Class:** 2 **Number:** 7-54-012

O&M Funding Source: State Superfund Federal Superfund Municipal Responsible Party

O&M Information: O&M Start: 9707 End: Annual Cost: \$ 1,500 Estimated

Interim Remedial Measures/Operable Units in O&M Phase:

- | | | |
|---|--|--|
| <input type="checkbox"/> Drum Removal | <input type="checkbox"/> Soil Removal | <input type="checkbox"/> Tank Removal |
| <input checked="" type="checkbox"/> Cap/Cover | <input type="checkbox"/> Containment Structure | <input checked="" type="checkbox"/> Fence/Security |
| <input type="checkbox"/> Groundwater Recovery/Treatment | <input type="checkbox"/> Leachate Collection/Treatment | <input type="checkbox"/> Vapor Extraction/rrreatment |
| <input type="checkbox"/> Air Sparging/Stripper System | <input type="checkbox"/> Treatment/Filtration Plant/System | <input type="checkbox"/> Potable Water Supply/System |
| <input checked="" type="checkbox"/> Other: Groundwater Monitoring | | |

Institutional Controls: Deed Restriction Discharge Permit Department of Health Sampling
 Other: None

O&M Review Information:

Reports: Awaiting the Final Remediation Report for an additional IRM work done in Summer 2000. The work was the removal of some contaminated soil and more non-contaminated soil around and under a building foundation that is located east of the fenced landfill.

Inspection: August 2000 by Region

Sampling: No Annual monitoring done in 2000.

Other:

Conclusions:

Remedy Effective? Yes No: One of the five monitoring wells has shown exceedance of Cadmium and Lead. We will compare results after next annual sampling in Summer 2001.

ROD Compliance? Yes No: The existing landfill on-site shows no erosion and has a good grass cover. Site fence has been cleared of all vegetation and is in good condition.

Consent Order Compliance? Yes No: N/A



Other:

Recommendations: Next Review Report: 0912001

ROD/Consent Order Modifications? No Yes (per above) Reclassify the Site? No Yes → Class:

Comments: Do annual groundwater monitoring in 2001. Metals of concern are Cadmium, Chromium and Lead.

There is an asbestos issue to be resolved. The IRM contractor has been asked to sample to determine the level of contamination. Due to the closeness of an elementary school to the site, the USEPA may look into the asbestos issue. The site can be resized to just include the landfill, and reclassified to a 4 once the final remediation report is complete.

Project Manager:  Signature			Reviewer:  Signature		
10/16/00 Date			10/18/00 Date		
John R. Strang	Haz. Site Control	(518) 457-0927	Gerald J. Rider, Jr.	Haz. Site Control	(518) 457-0927
Name	Region or Bureau	Telephone	Name	Region or Bureau	Telephone