

Performance Materials and Technologies

Honeywell
Buffalo Research Laboratory
20 Peabody Street
Buffalo, NY 14210
716-827-6200

KE
915002

RECEIVED
MAY 20 2014
FEB 24 2014

REL

February 21, 2014

Kathleen Horrigan Emery, PE
> Environmental Engineer II
> New York State Department of Environmental Conservation
> 270 Michigan Avenue
> Buffalo, New York 14203


RE: 2013 Annual Soil Management Report

Dear: Ms. Emery:

Attached you will find the 2013 Annual Soil Management Report for Honeywell's Buffalo Research Laboratory.

If you have any questions or if you need additional information please call me at (716) 827-6318 or (716) 491-4977 (cell).

Sincerely,



Lana L. Dole
Health, Safety, and Environmental Leader
Honeywell International Inc., Buffalo Research Laboratory

ENCL
Cc: File



**Honeywell Buffalo Research Laboratory
2013 Annual Soil Management Report**

There was one event that occurred in 2013 for which we contacted DEC . It was related to a sewer issue West of 514 that required a repair/excavation. This soil was returned back to the hole with DEC approval.

As per our policy, contractors were trained in Arsenic Awareness, prior to starting this project.