

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
Division of Environmental Remediation

**Inactive Hazardous Waste Site Operations and Maintenance Review Report**

Form Date 96.10.01

<b>Site Name:</b> Love Canal	<b>Class:</b> 4	<b>Number:</b> 932020
<b>O&amp;M Funding Source:</b> <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party		
<b>O&amp;M Information:</b> December 1979    End: Continuing    Annual Cost: Unknown <input type="checkbox"/> Estimated		
<b>Interim Remedial Measures/Operable Units in O&amp;M Phase:</b>		
<input type="checkbox"/> Drum Removal	<input type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal
<input checked="" type="checkbox"/> Cap/Cover	<input checked="" type="checkbox"/> Containment Structure	<input checked="" type="checkbox"/> Fence/Security
<input type="checkbox"/> Groundwater Recovery/Treatment	<input checked="" type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System
<input type="checkbox"/> Other:		
<b>Institutional Controls:</b> <input type="checkbox"/> Deed Restriction <input checked="" type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling		
<input type="checkbox"/> Other: Consent Decree. Niagara Falls Dep't of Water Facilities. Niagara County Dep't of Health.		
<b>O&amp;M Review Information:</b>		
Reports: <u>Quarterly RP Discharge Monitoring. 11/30/97, 2/28/98, 5/30/98, and 8/31/98. Effluent in compliance.</u>		
Inspection: <u>June 10 and June 11, 1998 of the Leachate Treatment Facility.</u>		
Sampling: <u>June 10 and June 11, 1998 split sampling of five monitoring wells with the RP.</u>		
Other:		
<b>Conclusions:</b>		
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: _____		
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: _____		
Other: _____		
<b>Recommendations:</b>		
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:		
<b>Comments:</b> <u>Corrective actions as determined by the M2P2 inspection on 7/23/98 have been implemented.</u>		
<u>Leachate continues to be collected, pumped and treated to maintain inward gradients. Analytical results from the Department's groundwater splits grabbed on 6/10 and 6/11 were non-detect. Miller Springs formerly Glenn Springs Holdings Inc. operates and maintains the site effectively. The double diaphragm air driven pumps in the leachate treatment room have been replaced with variable speed centrifugal pumps.</u>		
<b>Project Manager:</b> <u>Brian P. Sadowski</u>		<b>Reviewer:</b> <u>ABUL BARKAT</u>
Signature: <u>Brian P. Sadowski</u>	Date: <u>10/16/98</u>	Signature: <u>Daniel King</u>
Name: <u>Brian P. Sadowski</u>	Region or Bureau: <u>9</u>	Telephone: <u>716-851-7220</u>
		Signature: <u>Daniel K. King</u>
		Date: <u>10/16/98</u>
		Name: <u>Daniel K. King</u>
		Region or Bureau: <u>9</u>
		Telephone: <u>716-851-7220</u>