

Proactive by Design



## **2018 PERIODIC REVIEW REPORT**

NORTHTOWN INC. SITE 3097 SHERIDAN DRIVE AMHERST, NEW YORK BCP Site Number C915292

May 14, 2018 File No. 21.0056687.30



## **PREPARED FOR:**

Northtown Property Owner L.L.C. 33 Boylston Street Chestnut Hill, MA 02467

## **GZA GeoEnvironmental of New York**

300 Pearl Street, Suite 700 | Buffalo, New York 14202 716-685-2300

32 Offices Nationwide www.gza.com

Copyright© 2018 GZA GeoEnvironmental of New York



Proactive by Design

GEOTECHNICAL

**ENVIRONMENTA** 

ECOLOGICAL

WATER

CONSTRUCTION MANAGEMENT

GZA GeoEnvironmental of NY 300 Pearl Street Suite 700 Buffalo, NY 14202 T: 716-685-2300 F: 716-248-1472

www.gza.com



#### **VIA EMAIL**

May 14, 2018 File No. 21.0056687.30

Mr. Brian Sadowski
New York State Department of Environmental Conservation
Division of Environmental Remediation
270 Michigan Avenue
Buffalo, New York 14203
email: brian.sadowski@dec.ny.gov

Re: 2018 Periodic Review Report

Northtown Inc.

3097 Sheridan Drive, Amherst, New York

Brownfield Cleanup Program Site (Number C915292)

Dear Mr. Sadowski:

GZA GeoEnvironmental of New York (GZA) submits this Periodic Review Report (PRR) on behalf of Northtown Property Owner LLC (Northtown). Northtown is the owner and operator of the Northtown Inc. Brownfield Cleanup Program (BCP) Site (No. 915292). GZA prepared this PRR in general conformance with Section 6.3(b) of DER-10 *Technical Guidance for Site Investigation and Remediation* as well as the guidelines provided to Northtown in the 45-day reminder notice letter dated March 6, 2018.

If you have any questions or need additional information, please call Jim Richert at (716) 844-7048.

Sincerely,

GZA GEOENVIRONMENTAL OF NEW YORK

im Richert

James J. Richert, P.G.

Senior Project Manager

Bart A. Klettke, P.E.

Sat a. Klauk

Principal

Cc: Marco Borbo (Northtown)
Andrew Manning (Northtown)





#### **TABLE OF CONTENTS**

			<u>Page</u>
1.0	EXEC	UTIVE SUMMARY	1
	1.1	BACKGROUND	1
	1.2	EFFECTIVENESS OF THE REMEDIAL PROGRAM	1
	1.3	RECOMMENDATIONS	1
2.0	SITE (	OVERVIEW	2
	2.1	SITE LOCATION BOUNDARIES AND FEATURES	2
	2.2	INVESTIGATION AND REMEDIAL HISTORY	
3.0	EVAL	UATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS	3
4.0	INSTI	TUTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT	4
	4.1	IC/EC REQUIREMENTS AND COMPLIANCE	4
5.0	PRR (	CONCLUSIONS AND RECOMMENDATIONS	4
	5.1	PRR CONCLUSIONS	4
	5.2	PRR RECOMMENDATIONS	

## **FIGURES**

FIGURE 1 SITE LOCATION MAP

FIGURE 2 PHOTO LOCATIONS MAP

#### **APPENDICES**

APPENDIX A SITE MANAGEMENT FORM

APPENDIX B PHOTOGRAPH LOG

APPENDIX C ZONING VARIANCES AND SITE PLAN MAP

APPENDIX D IC/EC CERTIFICATION FORM



#### 1.0 EXECUTIVE SUMMARY

#### 1.1 BACKGROUND

The Northtown Inc. Brownfield Cleanup Program (BCP) Site (Site) is comprised of three Areas of Interest (AOIs) the combined total area of which is approximately 1.4 acres within the approximately 25-acre Northtown Plaza. The plaza is located at 3097 Sheridan Drive in the Town of Amherst, Erie County, New York and is undergoing a major modernization transformation which includes demolition of existing buildings and construction of new buildings and related amenities. The AOIs of the BCP Site were remediated of fuel oil and chlorinated organic constituents in soil. However, the presence of buildings at the AOIs limited the areal extents of site remediation. This resulted in placement of Institutional and Engineering Controls (IC/EC), required by the New York State Department of Environmental Conservation (NYSDEC). The IC/ECs are intended to protect current and future Site users from exposure to contaminants that remain in the subsurface. The ICs and ECs are summarized below:

#### **Institutional Controls Include:**

- Property use may include restricted commercial and restricted industrial use only;
- Groundwater may not be used without prior treatment and approval of the regulator;
- Compliance with the Site Management Plan is required; and
- Periodic certification of institutional and engineering controls is required.

#### The Engineering Control is:

• Operation of sub-slab depressurization (SSD) systems in Building 2 (when occupied) and tenant space No. 14 of Building 3, (when occupied).

The Environmental Easement (EE), which includes greater specificity of the above ICs and EC, was signed by NYSDEC on September 15, 2016.

#### 1.2 <u>EFFECTIVENESS OF THE REMEDIAL PROGRAM</u>

Based upon our PRR inspection conducted on April 13, 2018, the Site use continues as commercial, the tenant units in which SSD systems have been installed are now vacant and unused, and subsurface excavation activities were not observed. Therefore, the Site remedy continues to be effective at meeting Site RAOs and the Institutional Controls and Engineering Control (ICs/EC) remain in place. GZA identified the Site to be in compliance with the SMP.

#### 1.3 RECOMMENDATIONS

GZA and Northtown recommend no changes to the SMP nor to the frequency of Site inspections and PRR submittals. Implementation of the SMP will continue as the Site progresses to building demolition and construction as part of the overall Site redevelopment. This will include:

- Written notice to NYSDEC prior to ground disturbance;
- Implementation of the Excavation Work Plan during excavation and earth moving activities; and
- Evaluation of soil vapor intrusion within and west of AOI 3.



#### 2.0 SITE OVERVIEW

#### 2.1 SITE LOCATION BOUNDARIES AND FEATURES

The Northtown Plaza is located in the Town of Amherst, Erie County (see Figure 1) and is bounded as follows:

- Sheridan Drive to the north;
- Eggert Road to the south;
- commercial and residential properties to the east; and
- commercial properties to the west.

The BCP Site consists of three Areas of Interest (AOIs) within the greater Northtown Plaza, collectively comprising 1.424 acres of the approximately 25-acre Northtown Plaza (see Figure 2).

#### 2.2 INVESTIGATION AND REMEDIAL HISTORY

In 2013, a Phase I Environmental Site Assessment (ESA) of the Northtown Plaza identified Recognized Environmental Concerns (RECs) including heating oil underground storage tanks (USTs) and hazardous waste generation related to the historic use of chlorinated solvents by an on-site dry-cleaning operation.

In 2014, a Phase II ESA was completed of the plaza to investigate the above RECs. The Phase II included sampling of subsurface soil, groundwater, indoor air, and sub-slab soil vapor. Environmental impacts were identified, including:

- impacted soil associated with the two abandoned heating oil USTs;
- soil impacted by tetrachloroethene (PCE) associated with the former dry-cleaning operations;
- Indoor air impacted by PCE above its respective air guidance value (AGV) in and adjacent to the dry cleaner.

### **Brownfield Cleanup Program:**

In 2014, Northtown Associates LLC (predecessors of Northtown Property Owner LLC), applied to NYSDEC for admittance into the voluntary BCP. In the BCP application, three areas of interest (AOIs) were identified based on findings from the Phase II. AOIs 1 and 2 are associated with former fuel oil tanks, one at the southern exterior of Building #4 (AOI 1) and other at the western exterior of Building 3 (AOI 2). AOI 3 is associated with the former dry cleaner that occupied the southernmost tenant unit of Building 3. (See Figure 2)

Once admitted into the BCP, Northtown completed two additional investigations in 2015 to delineate the vertical and lateral extent of chlorinated volatile organic compounds (CVOCs) at concentrations above the commercial use soil cleanup objectives (SCOs) at AOI3. After completion of the additional investigations and assessment of potential environmental risks, Remedial Action Objectives (RAOs) for each environmental media were defined.



The RAOs identified for the Site were:

#### Groundwater:

- Prevent ingestion of groundwater containing contaminant levels exceeding drinking water standards.
- Prevent contact with, or inhalation of, volatiles emanating from contaminated groundwater.
- Remove the source of ground or surface water contamination.

#### Soil:

- Prevent ingestion/direct contact with contaminated soil;
- Prevent inhalation of, or exposure to, contaminants volatilizing from contaminated soil;
- Prevent migration of contaminants that would result in groundwater or surface water contamination.

#### Soil Vapor:

 Mitigate impacts to public health resulting from existing, or the potential for, soil vapor intrusion into buildings at a site.

In 2015 and 2016, three Interim Remedial Measures (IRMs) were completed at the Site under the BCP, these IRMs included the following:

- Removal of the two USTs and associated petroleum-impacted soils within AOI 1 and AOI 2;
- Removal of solvent-impacted subsurface soil in areas exterior of the building at AOI 3; and
- Installation of sub-slab depressurization systems within tenant space No. 14 of Building 3 (former dry-cleaner) and within off-site tenant space No. 1 of Building 2 (former Total Automotive service facility).

The IRMs were successful in meeting the Remedial Action Objectives (RAOs) for the Site and NYSDEC accepted the Final Engineering Report by issuing a Certificate of Completion (COC) on December 15, 2016.

#### 3.0 EVALUATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS

GZA performed a Site Inspection during the reporting period (December 15, 2016 to April 15, 2018) on April 13, 2018. This was the first Site inspection since NYSDEC issued the COC. The completed Site Management Form shows the results of the site inspection (See Appendix A). Conditions of the Site were also photo documented (See Appendix B). The locations and orientations of the Site photos are illustrated on Figure 2.

Since the issuance of the COC, nearly all the tenants within the BCP Site boundaries have vacated in anticipation of building demolition and subsequent Site redevelopment.

Remaining impacted soils have not been disturbed since issuance of the COC, and the original Site buildings remain in place and unoccupied. The Site remedy, therefore, continues to be effective at meeting the Site RAOs for protection of current and intended future site users.



## 4.0 INSTITUTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT

#### 4.1 IC/EC REQUIREMENTS AND COMPLIANCE

IC/ECs for the Site were determined by NYSDEC and specified in the EE issued by NYSDEC on September 15, 2016. A summary list of the ICs and ECs for the BCP Site is provided as follows:

#### **Institutional Controls:**

- Property use may include restricted commercial and industrial uses only;
- Groundwater may not be used without prior treatment and approval of the regulators;
- Compliance with the Site Management Plan is required;
- Periodic certification of institutional and engineering controls is required.

#### **Engineering Control:**

Operation of sub-slab depressurization systems in Building 2 (when occupied) and tenant space
 No. 14 of Building 3, (when occupied).

Since receipt of COC, the two tenant spaces at which the SSD systems are in place have remained vacant and therefore, with concurrence of NYSDEC, the SSD systems are present but currently not active. Nine of the 10 tenant spaces within the BCP Site as well as Building 2 (which has a SSD system) have been vacated in anticipation of eventual building demolition and Site redevelopment. Asbestos mitigation is currently in progress and demolition of both buildings within the BCP Site (Buildings 3 and 4) and Building 2 directly to the west of the BCP Site (the former Total Automotive building) are scheduled for demolition during the summer of 2018. Several variances to the Town zoning ordinance were granted, documentation of which is provided in **Appendix C**. Also included in **Appendix C** is a Site plan map that shows the planned locations of new building and paved surfaces overlaid onto the existing plaza layout.

The Site-specific IC/EC Certification Form, for reporting period of December 15, 2016 to April 15, 2018, was provided to Northtown as an attachment to the March 6, 2018 45-Day Reminder Notice letter sent by NYSDEC. This form has been completed by Northtown and Certified by GZA as QEP. The completed and certified IC/EC Certification Form for this reporting period is included in **Appendix D** of this PRR.

#### 5.0 PRR CONCLUSIONS AND RECOMMENDATIONS

#### 5.1 PRR CONCLUSIONS

The IC/ECs remain in place and are performing as intended. The Site use remains commercial and the two SSD systems are in place but inactive because their respective tenant spaces are vacant and unused. The overall Site conditions and current Site use were observed by GZA to be in compliance with the SMP.





Northtown Inc. Site, BCP Site No. C915292 – 2018 Periodic Review Report

File No. 21.0056687.30

Page | 5


#### 5.2 PRR RECOMMENDATIONS

GZA and Northtown recommend no changes to the SMP nor to the annual frequency of site inspections and PRR submittals. Implementation of the SMP will continue as the redevelopment of the Site progresses to the building demolition phase, including:

- 15-day written notification to NYSDEC as specified in Section D-1 of the Excavation Work Plan (Appendix D of the SMP), prior to ground intrusive activities;
- Implementation of the Excavation Work Plan (soil and air monitoring and management) during excavation operations; and
- Evaluation of soil vapor intrusion in the building within AOI 3 and west of AOI 3 to the western boundary of parcel 67.10-1-10. Sample types, number, and locations will be determined based on the specifics of the proposed new building(s). Prior to SVI sampling, a SVI Sampling and Analysis Work Plan will be prepared and approved by the NYSDEC.



**FIGURES** 







## **APPENDIX A**

**SITE INPECTION FORM** 

Northtown Inc. BCP Site No.: C915292 Site Management Form

SITE DETAILS			
Site No.: C915292   Site Name: Northtown Inc.			
Site Address: 3097 Sheridan Drive, Amherst, New York			
PERSON PERFORMING INSPECTION			
Name: Jim Richert Email: james.richert@gza.com  Company: GZA GeoEnvironmental of New York Phone Number: 716/844-7048			
Company: GZA GeoEnvironmental of New York Phone Number: 716/844-7048  Others Present: N/A			
INSPECTION DATE AND SITE CONDITIONS			
Insepction Date: April 13, 2018 Inspection Time: 8:15 AM			
Weather Conditions: Overcast, calm, 42 degrees F.			
REASON FOR SITE INSPECTION			
Type of Inspection: ☐ Annual ☐ Routine Maintenance Inspection ☐ Non-Routine Inspection			
Inspection after a Severe Condition that could effect Site contro  □ No  □ No			
Describe severe condition triggering inspection:			
N/A			
VERIFICATION OF SITE DETAILS			
Current Site Owner: Northtown Property Owner LLC			
Current Site Operator: Northtown Property Owner LLC			
Describe Current Site Use (check all that apply)			
□ Industrial □ Commercial □ Residential □ Other			
Briefly describe observed site uses:			
Commercial Shopping Plaza. All but one tenant space on the BCP Site (Treats Unleashed)			
was vacant on the day of inspection. See Photo Log.			
Note any additional pertinent information to Verification of Site Details (use additional pages if necessary.			
DESCRIPTION OF ENGINEERING CONTROLS			
Are the Engineering Controls still in place:   ✓ Yes   No			
If No, explain: SSD systems in place but turned off because the respective tenant spaces are vacant.			
Is the Site Management Plan still in place: ☐ Yes ☐ No			
If No, explain:			
AREAS IN NEED OF REPAIR OR MAINTENANCE			
Area discussed in this section must be shown on a figure and have photographic documentation.			
N/A			
N/A			
INTRUSIVE ACTIVITIES PERFORMED AT SITE DURING INSPECTION PERIOD			
Location: Date:			
Description of activities being performed:			
And Cite records hairs are neglected and resintained (City			
Are Site records being properly generated and maintained: ☑ Yes □ No			
Provide a summary of recordkeeping review and adeuacy:			
ADDITIONAL NOTES & COMMENTS			
The state of the s			
Site owner plans to demolish existing buildings and build new buildings. Where these activities take place on			
the BCP Site, implementation of the Excavation Work Plan and other provisions of the Site Management Plan			
shall be followed.			
INSPECTION CERTIFICATION			
I hereby certify that the information included in this report is complete and accurate to the best of my knowledge			
Inspector Signature: Aim Richart Date: April 13, 2018			



**APPENDIX B** 

**PHOTO LOG** 



## **Photographic Log**

Client Name: Northtown Property Owner

LLC

Site Location: 3097 Sheridan Drive, Amherst, NY

Project No. 21.0056687.30

Photo No. Date: 4-13-18 Direction Photo Taken:

Northeast

Description:

AOI 1 with Asbestos abatement contractor trailer.



Photo No.

Date: 4-13-18

**Direction Photo Taken:** 

Northwest

Description:

AOI 1 with asbestos abatement contractor trailer.







Photo No.

**Date:** 4-13-18

**Direction Photo Taken:** 

North

## Description:

AOI 2 and 3 Building 1 (former Total Automotive) to the left.



Photo No.

**Date:** 4-13-18

**Direction Photo Taken:** 

North

## Description:

Building 1 (Vacant) total Automotive







Photo No.

**Date:** 4-13-18

**Direction Photo Taken:** 

North

## Description:

Rear of AOI 3, SW corner of former Building 3 (former GiRo Cleaners to the right).



Photo No.

Date: 6 4-13-18

**Direction Photo Taken:** 

Northwest

## **Description:**

SE corner of Building 3. Former GiRo Cleaners in foreground.







Photo No. 7

**Date:** 4-13-18

**Direction Photo Taken:** 

Northeast

## Description:

SW corner of Building 3. Rear of former GiRo Cleaners.



Photo No.

**Date:** 4-13-18

**Direction Photo Taken:** 

North

## Description:

West side of Building 1. Former Total Automotive.





## **APPENDIX C**

APPROVED ZONING VARIANCES AND SITE PLAN MAP



## TOWN OF AMHERST

#### **TOWN CLERK'S OFFICE**

5583 MAIN STREET
WILLIAMSVILLE, NEW YORK 14221
(716) 631-7021
FAX (716) 631-7152
www.amherst.ny.us

Marjory Jaeger Town Clerk

Kathleen Cooper Deputy Town Clerk

Timothy Koller Asst. Deputy Town Clerk

December 21, 2017

Northtown Property Owner LLC c/o Sean Hopkins, Esq. 5500 Main Street, Suite 343 Williamsville, NY 14221

Re: 3045 Sheridan Drive

Dear Mr. Hopkins:

This letter is to advise you that a decision has been made and filed on your petition. Your request for area variances to the Town of Amherst Zoning Ordinance for 1) vehicle use area – front yard setback (Sheridan Dr), 2) vehicle use area – front yard setback (Eggert Rd), 3) building "F" front yard setback (Eggert Rd), 4) building separation (Building B & existing Key Bank), 5) required number of parking spaces, 6) maximum number of parking spaces between landscaped islands (11 locations), 7) required interior landscaping percentage (site), 8) minimum percentage of landscaping adjacent to a building (Building A), and 9) minimum required covered pedestrian walkway (Buildings A, B, C, E & F) at 3045 Sheridan Drive was decided as follows by the Zoning Board of Appeals on December 19:

1. The Board issued a negative declaration for area variance 5.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

2. The Board granted area variance 1.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

3. The Board granted area variance 2.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, no and Mr. Cimasi, aye. The motion was declared carried by a vote of ayes 3, noes 1.

4. The Board granted area variance 3.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, no and Mr. Cimasi, aye. The motion was declared carried by a vote of ayes 3, noes 1.

5. The Board granted area variance 4.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

6. The Board granted area variance 5.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

7. The Board granted area variance 6.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

8. The Board granted area variance 7.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

9. The Board granted area variance 8.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

10. The Board granted area variance 9.

Upon roll call the vote was: Mr. Radens, aye; Mr. Pollack; Mr. Palumbo, aye and Mr. Cimasi, aye. The motion was declared unanimously carried by a vote of ayes 4, noes 0.

Please contact the Building Department at 631-7080, if you have further questions and to secure all necessary permits.

Thank you for your cooperation.

Sincerely yours,

Marjory Jaeger

Amherst Town Clerk

M/J //nm

MJ/tk

C: Assessor, Building, Planning



## **APPENDIX D**

IC/EC CERTIFICATION FORM



# Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Site	Site Details No. C915292	Box 1			
Site	Name Northtown Inc.				
City Cou	Site Address: 3097 Sheridan Drive Zip Code: 14226 City/Town: Amherst County: Erie Site Acreage: 1.4				
Rep	porting Period: December 15, 2016 to April 15, 2018				
		YES	NO		
1.	Is the information above correct?	Z			
	If NO, include handwritten above or on a separate sheet.				
2.	Has some or all of the site property been sold, subdivided, merged, or undergone a tax map amendment during this Reporting Period?		×		
3.	Has there been any change of use at the site during this Reporting Period (see 6NYCRR 375-1.11(d))?		×		
4.	Have any federal, state, and/or local permits (e.g., building, discharge) been issued for or at the property during this Reporting Period?	Z			
	If you answered YES to questions 2 thru 4, include documentation or evidence that documentation has been previously submitted with this certification form.				
5.	Is the site currently undergoing development?				
		Box 2			
		YES	NO		
6.	Is the current site use consistent with the use(s) listed below?  Commercial and Industrial	<b>S</b>			
7.	Are all ICs/ECs in place and functioning as designed?	<b>₽</b>			
	IF THE ANSWER TO EITHER QUESTION 6 OR 7 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.				
A Corrective Measures Work Plan must be submitted along with this form to address these issues.					
Sig	nature of Owner, Remedial Party or Designated Representative Date				

	,		Box 2	A	
8 Has any new informati	on revealed that assumptions made i	n the Ouglitative Evnesure	YES	NO	
Assessment regarding	Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid?			Ø	
	to question 8, include documentat nas been previously submitted with				
	n the Qualitative Exposure Assessme sure Assessment must be certified ev		8		
	to question 9, the Periodic Review I Exposure Assessment based on the				
SITE NO. C915292			Вох	3	
Description of Institut	ional Controls				
<u>Parcel</u>	Owner	Institutional Contro	<u>I</u>		
Portion of 67.10-1-10  Northtown Property Owner LLC  Monitoring Plan O&M Plan Ground Water Use Restriction Landuse Restriction Site Management Plan IC/EC Plan			ion		
An Environmental Easement, filed with the Erie County Clerk's Office on October 12, 2016, imposes the following controls on the property:  1. The property may be used for Commercial and Industrial use and shall not be used for Residential or Resticted Residential purposes as described in 6NYCRR 375-1.8(g)(2).  2. The use of groundwater underlying the property is prohibited without necessary water quality treatment as determined by the New York State Department of Health or the Erie County Department of Health.  3. Compliance with the Department approved November 28, 2016 Site Management plan is required.  4. The remedial party or site owner must complete and submit to the Department a periodic certification of institutional and engineering controls in accordance with Part 375-1.8(h)(3).					
			Вох	<b>4</b>	
Description of Engine	ering Controls				
Parcel	Engineering Control				
Portion of 67.10-1-10					
Vapor Mitigation  1. Continued operation of the sub-slab depressurization systems installed in 2 tenant spaces.					

н	ΛY	

	Periodic Review Report (PRR) Certification Statements		
1.	I certify by checking "YES" below that:		
	<ul> <li>a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;</li> </ul>		
	<ul> <li>b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.</li> </ul>		
	YES NO		
2.	If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:		
	(a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;		
	(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;		
	<ul> <li>(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;</li> </ul>		
	(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and		
(e) if a financial assurance mechanism is required by the oversight document for the site, mechanism remains valid and sufficient for its intended purpose established in the document			
	YES NO		
	<b>X</b> □		
	IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.		
A Corrective Measures Work Plan must be submitted along with this form to address these issues.			
	Signature of Owner, Remedial Party or Designated Representative Date		

#### IC CERTIFICATIONS SITE NO. C915292

Box 6

## SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

Penal Law.	
Derave A. Geogram 33 Boylston Sprint/business add	St Chestrut Hill MA dress
am certifying asOWnev	(Owner or Remedial Party)
for the Site named in the Site Details Section of this form.	
Signature of Owner, Remedial Party, or Designated Representative Rendering Certification	6-7-18 Date

## IC/EC CERTIFICATIONS

Box 7

## **Professional Engineer Signature**

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

are at 300 PEARL STREET SUITE TOO BUFFALO, NY 14207

am certifying as a Professional Engineer for the \_\_\_\_\_

Remedial Party)

(Required for PE)

Signature of Professional Engineer, for the Owner or

Remedial Party, Rendering Certification



GZA GeoEnvironmental, Inc.