

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 3-03**

**East Park Auto
Town of Hyde Park**

Region 3, Dutchess County

Site Setup:

**Tires are accessible via a dirt road,
They are on a small hill, on a little slope.**



Number of tires: 1,500 estimated

Condition of tires:

**Mostly passenger tires,
less than half with rims
Some dirt and shrubbery mixed in with pile**



Access to site:

**Fence with a gate
Dirt road, up a hill
Tires are accessible**

Additional:

**Facility is operational,
Owner indicates he is cleaning as he takes the tires in**