

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 3-08**

**Mor Ton Recycling
Town of Fallsburgh**

Region 3, Sullivan County

Site Setup:

Tires are stockpiled in two large piles.



Number of tire piles: 2

**Number of Tires: 4,000 total estimated,
comprised of estimated 3,000
in one pile and 1,000 in the
other**



Condition of Tires: Good

Access: Good

Additional:

**Owner claims to be in process of removing
the tires. Site has a huge scrap metal pile.**

