

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 4-08**

**Jim Cooper Auto Parts
Town of Sand Lake**

Region 4, Rensselaer County

Site Setup:

This site is located behind two houses on a main road. There are several piles around the site including a pile of oversize tractor tires. Sparse vegetation.

Number of tires: 9,000 estimated

Condition of tires:

Mixed. There are comingled clean and dirty tires. Many of the tires are on rims.

Access to Site:

There is a dirt road from the main road down into the site providing good access.

