

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 5-06**

Northern Scrap Metal Village of Keeseville

Region 5, Essex County

Site Setup:

**Three tire piles at a back of the scrap yard.
Piles are in an open area. The facility is
an operating scrap metal yard.**



Number of tire piles:

**There are 3 tire piles located at the
southeast corner of the site.**

Dimensions of tire piles:

pile 1 = 18' X 24' X 8' high

pile 2 = 29' X 110' X 10' high

pile 3 = 10' X 51' X 8' high

Number of Tires: 6,000 estimated

Condition of Tires: Clean whole tires.

Access:

Dirt and gravel road. No gate.

Road is through a scrap metal junk yard

Concerns: Fire, vectors