

**New York State Department of Environmental Conservation  
Waste Tire Stockpile Assessment Summary Sheet - Site 5-08**

## **Fletcher's Dump Village of Tupper Lake**

**Region 5, Franklin County**

**Site Setup:** Tires were found along a dirt and gravel road on both sides several tires deep.  
Large tire pile at end of road.  
Trees surround the site.



**Number of piles:**  
Two linear piles along each side of the road.  
One large tire pile at end of road.  
Scattered tires near the large tire pile.



**Number of Tires. 10,000 estimated**

**Condition of Tires:**  
Clean whole tires. Some have rims.



**Access:**  
Dirt & gravel road to site.  
Site is gated, locked and posted.

**Additional Information:**  
Site is Posted and has locked gate.

