

**New York State Department of Environmental Conservation  
Waste Tire Stockpile Assessment Summary Sheet - Site 5-12**

## **Canfield's Auto Parts Village of Schuylerville**

**Region 5, Saratoga County**

**Site Setup:**

**Site of an operating automobile junkyard and owner's residence. Tire piles are located along the back side of the property. Site is in rural area. About 500 tires scattered around site in addition to distinct piles.**

**Number of tire piles: 2 piles. Insufficient space around tire piles. Piles are surrounded by junk vehicles and scrap metal.**

**Dimensions of tire piles:**

**Large pile 40'W X 75'L X 4'H**

**Number of Tires: 6,000 estimated**

**Condition of Tires: Most are on rims.**

**Access:**

**Dirt driveway. Some waste tire are surrounded with junk vehicles and scrap metal.**

**Concerns: Vectors, Fire**

