

New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 5-15

U Save Tire Town of Plattsburgh

Region 5, Clinton County

This is a permitted facility which is non-compliant.

Site Setup: Site consists of one tire pile at the rear of the property. Tire pile is accessible via dirt road. House trailers located nearby with some junk cars in a clearing near the tire pile.

Number of tire piles: 1 Dimension: 600' x 200'

Separation of tire piles: Single tire pile with a separation of 12 feet through the middle. The separation is not sufficient to prevent fire spread nor provide apparatus access.

Number of Tires: 200,000 estimated

Condition of Tires: Majority off rims. Approx. 70% passenger/light truck- 30% large tractor/OTR. Dirty on outside.

Access: The tire pile is located approximately 1/4 mile from the main road with access through a 15' wide dirt road. Road has potholes.

Concerns: Fire, vectors.
Property located 1/4 mile from school.

Additional Information:
Permit allows up to 52,000 tires. Regional Office met with the facility's attorney to discuss removal of tires.

