

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 5-21**

**West Side Auto
Town of Queensbury**

Region 5, Warren County

Site Setup:

Site of an operating automobile junkyard. Tire piles located in the northwest corner of the property. Site is located adjacent to residential areas.



Number of tire piles: 6

Separation of tire piles: 5' to 10'

Dimensions of tire piles:

**Smallest pile 4'W X 18'L X 3'H
Largest pile 37'W X 46'L X 5'H**



Number of Tires: 3,500 estimated

Condition of Tires:

Tires are not well segregated from other debris and scrap. Tire piles located in an overgrown area among some scrap vehicles and parts.

Access:

Fence with closed gate, dirt road through junkyard to waste tire area.

Concerns: Vectors, Fire

Additional Information:

Site owner has contracted with a hauler to start removing tires.