

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 6-08**

**Doc's Trucking & Auto Parts
Town of Verona**

Region 6, Oneida County

Site Setup:

Rural junk yard bordered by the Oneida Creek on the west and a road on the south. There is vegetation that has over grown large portions of the site and the piles.

**Number of tires: 10,000 estimated
Tires are in piles around the site
and in one building.
The largest pile is 3,000 tires.**

Condition of tires:

Mixed. There are some good tires mixed in with old, dirty tires. Approximately half appear to have rims. Most are surrounded or covered with vegetation and blue tarps.

Access to Site:

Most tires are in close proximity to a road through existing active junkyard.

