

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 6-12**

**White's Lisbon Iron & Metal
Town of Lisbon**

Region 6, St. Lawrence County

Site Setup:

Formerly Whites Iron & Metal.

The site was an active junkyard until recently.



Number of tires: 60,000 estimated

Condition of tires:

Poor condition. Most of the tires remain on the rims and are dirty. Several of the piles are contaminated with other scrap and debris.



Access to Site:

There is good access to the site via roads and a county highway

Concerns: Fires and vectors.