

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 7-01**

**Fortino Site
Town of West Monroe**

Region 7, Oswego County

**Site Setup: Access to site limited by
wetland, tires in many large piles**

**Number of tires: 10,000,000 estimated
(access to site limited)**

**Condition of tires:
Passenger, very few with rims
Most appeared to be clean, old**

**Access to site:
Dirt road
Road has become a wetland as the stream has
backed up**

**Concerns:
Stream that runs through site
Close to a trailer park**

