

**New York State Department of Environmental Conservation  
Waste Tire Stockpile Assessment Summary Sheet - Site 7-07**

## **H O Tires Extension Town of Brookfield**

**Region 7, Madison County**

**Site Setup:**

**Tires are located at the end of a dirt driveway. Most tires are located in two piles with additional tires scattered throughout the woods.**



**Number of tires: 10,000 estimated**

**Condition of tires:**

**Tires are old and weathered. Tires are overgrown with vegetation and located in wooded area. One pile of tires is covered with a plastic tarp**



**Access to site:**

**Difficult access to most of tires.  
Tires are located on a wooded hillside with one old logging trail present**

**Concerns:**

**Two trailer homes are located on the same parcel of land as the tires.  
No municipal water source available.  
A protected stream is located 500 feet down gradient of site.**

