

**New York State Department of Environmental Conservation
Waste Tire Stockpile Assessment Summary Sheet - Site 8-03**

**Tire Solutions, Inc.
Town of Seneca Falls**

Region 8, Seneca County

This is a registered facility which is non-compliant.



Site Setup:

Facility is 200 feet from road on edge of village. Residences across the road.

Tire pile is outside the processing building.

Number of tires: 10,000 estimated



Condition of tires:

All tires to be processed are off rims and on the ground on the south side of the processing building. There are at most 3,000 saleable tires on site.

Access to Site:

Gravel drive. Fencing still needed.

Concerns:

Vectors and fire