

**New York State Department of Environmental Conservation  
Waste Tire Stockpile Assessment Summary Sheet - Site 9-03**

**Ben Maglio Property  
Village of Perry**

**Region 9, Wyoming County**

**Site Setup: Grass road/trail leads to loop  
with piles along road on loop**



**Number of piles: 3**

**Number of tires: 150,000 estimated**

**Condition of tires:**

**Mostly passenger, very few with rims  
Some overgrown with weeds and bushes  
Some in the woods**



**Access to site:**

**Driveable grass road  
Some tires in woods, most accessible**



**Concerns:**

**Power lines running over tire piles**

