




**Flexo Transparent, Inc.**  
REMEDIAL INVESTIGATION REPORT

---

# Appendix B

## Photo Log



<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 1	<b>Date:</b> 8/4/09		
<b>Direction Photo Taken:</b> North			
<b>Description:</b> BCP Sign on south fence of 1146 Seneca Street Property			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 2	<b>Date:</b> 10/19/09		
<b>Direction Photo Taken:</b> West			
<b>Description:</b> North yard of 1132 Seneca St. property			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 3	<b>Date:</b> 10/19/09		
<b>Direction Photo Taken:</b> North			
<b>Description:</b> Grubbing operations on 1132 Seneca St. property			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 4	<b>Date:</b> 10/19/09		
<b>Direction Photo Taken:</b> South			
<b>Description:</b> RI Drilling operations at B/MW-5			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 5	<b>Date:</b> 10/22/09		
<b>Direction Photo Taken:</b>  NW			
<b>Description:</b>  RI well development operations at B/MW-2			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 6	<b>Date:</b> 3/18/10		
<b>Direction Photo Taken:</b>  North			
<b>Description:</b>  Phase 2 of pre-characterization drilling and sampling (on 1146 Seneca St. property)			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 7	<b>Date:</b> 12/14/09		
<b>Direction Photo Taken:</b> west			
<b>Description:</b> Phase 1 of pre-characterization drilling/sampling. Note traffic cone covering boring at suspected UST.			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 8	<b>Date:</b> 3/18/10		
<b>Direction Photo Taken:</b> NA			
<b>Description:</b> Split spoon sample. Typical black colored soil/fill over native clay.			

**Project:**  
1132-1146 Seneca Street BCP Site

**Location:**  
Buffalo, NY

**Project No.**  
6105-002

**Photo No.**  
9

**Date:**  
3/18/10

**Direction Photo Taken:**  
NA

**Description:**  
Native clay



**Project:**  
1132-1146 Seneca Street BCP Site

**Location:**  
Buffalo, NY

**Project No.**  
6105-002

**Photo No.**  
10

**Date:**  
3/18/10

**Direction Photo Taken:**  
North

**Description:**  
Phase 2 of pre-characterization sampling, at boring Q2.



<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 11	<b>Date:</b> 3/18/10		
<b>Direction Photo Taken:</b>  NNE			
<b>Description:</b>  View of elevation difference between 1132 and 1146 Seneca Street lots in the vicinity of the 1132 loading dock.			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 12	<b>Date:</b> 10/21/09		
<b>Direction Photo Taken:</b>  NA			
<b>Description:</b>  Typical sub-slab soil vapor sampling- tracer test equipment and configuration.			

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**

13

**Date:**

10/21/09

**Direction Photo Taken:**

NA

**Description:**

Typical sub-slab soil vapor sampling setup.

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**

14

**Date:**

10/21/09

**Direction Photo Taken:**

South

**Description:**

View into loading dock from outside before IRM excavation activities.



**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
15**Date:**  
10/28/09**Direction Photo Taken:**

Northeast

**Description:**

IRM excavation activities at 1132 loading dock. Note native clay at bottom of excavation.

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**


6105-002

**Photo No.**  
16**Date:**  
10/28/09**Direction Photo Taken:**

NA

**Description:**

Template used for collection of PCB wipe sample of removed RR ties.



**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
17**Date:**  
10/28/09**Direction Photo Taken:**

North

**Description:**

View of completed excavation at the 1132 loading dock IRM.

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
18**Date:**  
10/28/09**Direction Photo Taken:**

East/Southeast

**Description:**

Collection of sample (East wall North) from east wall of excavation at 1132 loading dock IRM site.



**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
19**Date:**  
10/28/09**Direction Photo Taken:**

Northeast

**Description:**

Collection of sample from north wall of completed excavation at 1132 loading dock IRM.

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
20**Date:**  
10/28/09**Direction Photo Taken:**

West

**Description:**

South end of loading dock.



**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
21**Date:**  
10/29/09**Direction Photo Taken:**

Southwest

**Description:**Completed excavation of  
1132 North area IRM.**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
22**Date:**  
10/29/09**Direction Photo Taken:**

Southwest

**Description:**Excavation and  
stockpiling operations at  
the 1132 North area IRM.

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 23	<b>Date:</b> 10/29/09		
<b>Direction Photo Taken:</b>  West			
<b>Description:</b>  Preparing to collect composite sample from south wall of completed excavation at 1132 north area IRM.			

<b>Project:</b> 1132-1146 Seneca Street BCP Site		<b>Location:</b> Buffalo, NY	<b>Project No.</b> 6105-002
<b>Photo No.</b> 24	<b>Date:</b> 10/29/09		
<b>Direction Photo Taken:</b>  West/Northwest			
<b>Description:</b>  Flags marking locations of composite sample points sampled from north wall of the 1132 North area IRM.			

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**

25

**Date:**

3/18/10

**Direction Photo Taken:**

Southwest

**Description:**Location of floor  
drain/pipe chase  
sediment sample FD-1**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**

26

**Date:**

3/18/10

**Direction Photo Taken:**

Southeast

**Description:**Location of floor  
drain/pipe chase  
sediment sample FD-2

**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
27

**Date:**  
3/18/10

**Direction Photo Taken:**

East and down

**Description:**

FD-2 sample collected of dirt/sediment beneath pipes



**Project:**

1132-1146 Seneca Street BCP Site

**Location:**

Buffalo, NY

**Project No.**

6105-002

**Photo No.**  
28

**Date:**  
3/18/10

**Direction Photo Taken:**

South and down

**Description:**

Location of FD-1, collected from beneath and west of all pipes.

