

LEGEND

- 2014 RI Monitoring Well
- 2012 Monitoring Well
- Pre-remediation Sanitary Sewer Utility
- Pre-remediation Water Utility
- Pre-remediation Gas Utility
- Property Boundary

SOURCES

-Aerial photograph is an 0.3 meter resolution image dated March 2013, downloaded from Google Maps.
-Property boundaries are derived from Cattaraugus County Online GIS Services.
-Sanitary sewer and gas utility locations from Figure C-3, Utilities Plan, Benchmark Environmental Engineering and Science, PLLC, November 8, 2013.
-Approximate location of water utility line provided by Mike John, personal communication, January 16, 2014.
-Approximate locations of monitoring well locations were measured using a handheld GPS by Roux Associates on June 4, 2014.

NOTES

-All features shown are approximate.
-RI = Remedial Investigation

0 30 60 120 180 Feet

Title:

Remedial Investigation Monitoring Well Locations

291 and 299 Homer Street, Olean, New York

Prepared For:

MJ Painting Contractor Corp.

ROUX
ROUX ASSOCIATES, INC.
Environmental Consulting & Management

Compiled By:	AH	Date:	1/22/2015	FIGURE
Prepared By:	AH	Scale:	AS SHOWN	3b.
Project Mgr.:	IR	Office:	MA	
File No.:	109.3b	Project:	2317.0001M002	

T:\GIS\MJ PAINTING CONTRACTOR CORP\2317.0001M002\109 - RIR 2014\F3b_2317.0001M002.109.mxd



T:\GIS\MJ PAINTING CONTRACTOR CORP\2317.0001M002\109 - RIR 2014\F3c_2317.0001M002.109.mxd

LEGEND

- 2015 Sub Slab Vapor Point
- 2014 RI Soil Vapor Point
- 2011 Soil Vapor Point
- Pre-remediation Sanitary Sewer Utility
- Pre-remediation Water Utility
- Pre-remediation Gas Utility
- Property Boundary

SOURCES

-Aerial photograph is an 0.3 meter resolution image dated March 2013, downloaded from Google Maps.
-Property boundaries are derived from Cattaraugus County Online GIS Services.
-Sanitary sewer and gas utility locations from Figure C-3, Utilities Plan, Benchmark Environmental Engineering and Science, PLLC, November 8, 2013.
-Approximate location of water utility line provided by Mike John, personal communication, January 16, 2014.
-Approximate locations of soil vapor points were measured using a handheld GPS by Roux Associates on June 4, 2014.

NOTES

-All features shown are approximate.
-RI = Remedial Investigation

0 30 60 120 180 Feet

Title:

Remedial Investigation Soil Vapor Point Locations

291 and 299 Homer Street, Olean, New York

Prepared For:

MJ Painting Contractor Corp.

ROUX

ROUX ASSOCIATES, INC. Environmental Consulting & Management

Compiled By:	AH	Date:	3/30/2015	FIGURE
Prepared By:	AH	Scale:	AS SHOWN	3c.
Project Mgr.:	IR	Office:	MA	
File No.:	109.3c	Project:	2317.0001M002	



LEGEND

- 2014 RI Surface Soil Sample Location
- 2014 RI Surface Soil Sample Location (collected during test pit activities)
- Pre-remediation Sanitary Sewer Utility
- Pre-remediation Water Utility
- Pre-remediation Gas Utility
- Property Boundary

SOURCES

-Aerial photograph is an 0.3 meter resolution image dated March 2013, downloaded from Google Maps.
-Property boundaries are derived from Cattaraugus County Online GIS Services.
-Sanitary sewer and gas utility locations from Figure C-3, Utilities Plan, Benchmark Environmental Engineering and Science, PLLC, November 8, 2013.
-Approximate location of water utility line provided by Mike John, personal communication, January 16, 2014.
-Approximate locations of surface sample locations were measured using a handheld GPS by Roux Associates on June 4, 2014.

NOTES

-All features shown are approximate.
-RI = Remedial Investigation

0 30 60 120 180 Feet

Title:
Remedial Investigation Surface Soil Sample Locations

291 and 299 Homer Street, Olean, New York

Prepared For:
MJ Painting Contractor Corp.

ROUX
ROUX ASSOCIATES, INC. Environmental Consulting & Management

Compiled By:	AH	Date:	1/22/2015	FIGURE
Prepared By:	AH	Scale:	AS SHOWN	3d.
Project Mgr.:	IR	Office:	MA	
File No.:	109.3d	Project:	2317.0001M002	

T:\GIS\MJ PAINTING CONTRACTOR CORP\2317.0001M002\109 - RIR 2014\F3d_2317.0001M002.109.mxd