

**NOTES**

- 1) HORIZONTAL CONTROL BASED UPON NEW YORK STATE PLANE COORDINATE SYSTEM WEST ZONE (NAD 83/2011)
- 2) VERTICAL CONTROL BASED UPON NAVD 88
- 3) NO SOIL SAMPLES WERE COLLECTED FROM LOCATIONS B-39, B-43, B-42, AND B-37 AS PER DIRECTION FROM NYSDEC PROJECT MANAGER
- 4) NO SOIL SAMPLE WAS COLLECTED FROM B-36 LOCATION, GROUNDWATER ONLY
- 5) SAMPLE COLLECTED FROM SUBSURFACE DRAINAGE STRUCTURE, NOT TEMPORARY MONITORING WELL GROUNDWATER SAMPLE.



- Legend**
- Permanent Monitoring Well Locations
  - Temporary Monitoring Well Locations
  - Soil Boring and Temporary Monitoring Well Locations
  - ⊠ Sump and Catch Basin Locations

\*All results are in µg/L.

Site boundary


## Groundwater, Sump, and Stormwater Exceedances for Volatile Organic Compounds



**FIGURE 2**  
Former Doro Dry Cleaners  
Cheektowaga, NY



Excerpt from:  
Remedial Investigation/Feasibility Study Report - Former Doro Dry Cleaners



**NOTES**

- 1) HORIZONTAL CONTROL BASED UPON NEW YORK STATE PLANE COORDINATE SYSTEM WEST ZONE (NAD 83/2011)
- 2) VERTICAL CONTROL BASED UPON NAVD 88
- 3) NO SOIL SAMPLES WERE COLLECTED FROM LOCATIONS B-39, B-43, B-42, AND B-37 AS PER DIRECTION FROM NYSDEC PROJECT MANAGER
- 4) NO SOIL SAMPLE WAS COLLECTED FROM B-36 LOCATION, GROUNDWATER ONLY
- 5) SUMP SAMPLE COLLECTED FROM DRAINAGE STRUCTURE, NOT A SUBSURFACE SAMPLE.




**Legend**

- Soil Boring Sampling Locations
- ⊗ Soil Boring and Temporary Monitoring Well Locations
- ⊠ Sump and Catch Basin Sampling Locations

\*All results are in mg/kg.

## Soil and Sludge Exceedances for Volatile Organic Compounds



**FIGURE 3**  
Former Doro Dry Cleaners  
Cheektowaga, NY  
**CDM Smith**

Site boundary

Excerpt from:  
Remedial Investigation/Feasibility Study Report - Former Doro Dry Cleaners