

NYSDEC - Region 9 - Division of Environmental Remediation Stratigraphic and Instrumentation Log



Project Name: BR
 Site No.:
 Location: 6-748-00-L35
 -L910
 NYSDEC Staff: BVH

Hole Designation:
 Date Completed: 8/24/05 1645
 Drilling Method: Vibracore

Depth (ft.)BGS	Stratigraphic Description & Remarks	Elevation (ft.)AMSL	Monitor Installation	Sample			
				C O U N T	N U M B E R	N V A L U E	P I D
	Surface Reference						
0 - 8'	Gray, medium stiff SILT, some clay, little sand (ML) Thin organic layer at 4'						
8 - 10'	Dark gray/black GRAVEL and silt, some sand, little clay, slag fragments, petroleum odor and sheen (GM) Lab sample at 3 - 5' Lab sample at 9 - 10' Recovery = 10'						

Notes: Measuring Point Elevations May Change: Refer to Current Elevation Table

Grain Size

Water Found

Static Level

