

Recommendations for Future Work.

Site Name and Number: RCA Rocky Point Site # 1-52-011

Date: 12/20/04

Project Management:

The project manager for the site is Matt Dunham. He can be contacted at 518-402-9812. Currently there is no work assignment for this site. Any samples will be sent to NYSDEC lab for analysis.

Site Conditions:

Mowing and plowing needs to be scheduled on a regular basis to ensure that the wells are accessible.

Well Conditions (labeling, etc):

All of the wells at the site look good. We need to monitor them to ensure that they are holding up.

Monitoring Frequency, Detection Limit, Contaminants Monitored:

According to the monitoring data, the monitoring frequency is good. So is the detection limit.