Project: Sp	ectrum Finishing - Remedial /	Action		_			CDM
Contractor: En	viroTrac Environmental Servi	ces		-			Park Wes
CDM Job No: D-0	006956 Site No. 1-52-029			-			, NY 11797
CDM Project Manager: Joh	nn Blaum			_	Telep	hone: 51	6.496.8400
				-"		Fax: 51	6.496.8864
	DAILY RE	<u>PORT</u>					
Day: S	M T W TH F S	WEATHER	Clear	Partly Cloudy	Overcast	Rain	Snow
Date:	4-Mar-09	TEMP L/H		13/31			
REPORT No.	92	HUMIDITY	Dry	Moderate	High		
PAGE No.	1	WIND	Calm	Light	Moderate	High	
		WIND DID	N	Ĕ	S	W	
PREPARED BY: F.R	obinsor TITLE: Inspector	WIND DIR	NE	SE	SW	NW	
		-				-	
AVERAGE FIELD FOR	CE						
Name of Contractor	Title	Hours Wor	ked	Remarks			
EnviroTrac	Construction manager	2x8 hrs			J. Szymanski, N		
EnviroTrac	Operator	1x4 hrs			J. Byrne:	3	
EQUIPMENT AT THE S Daewoo 450 skidder - W	ITE I = Idle W	/ = Working					
Saewoo 450 Skidder - W							
HEALTH AND SAFETY							
Name	Time (From - To)			Task/Le	vel of PPE		
			All	workers onsite	were in level D-PF	PE	
CONSTRUCTION ACTI							
Site Representative: Frank							
Health and Safety Site Office	cer: N/A						
	DESCRIPTION OF W	ODK DEDEOF	DATED A	ND ODGED	WED		
	DESCRIPTION OF W	OKK PEKFOR	KINIED A	IND OBSEK	VED		
- Progress Meeting #11 held in th	e site field trailer.						
2-EnviroTrac using skidder to clea	r snow off of site.						
	х	- Designates r	eport is	continued o	n additional pag	jes	
		-	•				

Project Manager: John Blaum

CDM Site Representative: F. Robinson

PHOTOGRAPHIC LOG

Date: 03/4/09

CDM Job No. D-006956

Spectrum Finishing Remedial Action

SITE No. 1-52-029

РНОТО	DATE	TIME	DESCRIPTION
100_0013.jpg	3/4/2009	PM	Snow cleared off of site, looking SW.
100_0014.jpg	3/4/2009	PM	Snow cleared off of site, looking NE.

PHOTOS 3/04/09



100_0013.jpg-Snow cleared off of site, looking SW.



100_0014.jpg-Snow cleared off of site, looking NE.