

From: "Robinson, Frank" <RobinsonF@cdm.com>
To: "Blaum, John" <BlaumJP@cdm.com>, "David Chiusano" <djchiusa@gw.dec.state...>
Date: 8/20/2009 8:09 AM
Subject: Spectrum Daily Report #185
Attachments: report.hw152029.2009-08-19.SpectrumContractD006356_CDMDailyNo185.pdf; 100_1162.jpg

John/Dave,

I went to the site yesterday and it was I thought easier to send as a daily report. As you can see nothing has been done since I was there last week. There are no pictures of the fronts of 60 Dale St. and 51 Cabot St. because I could not get them to transfer from my camera. I'm glad I went yesterday as I got to see a B-17 at the airport, see picture.

Frank

<<report.hw152029.2009-08-19.SpectrumContractD006356_CDMDailyNo185.pdf>>
<<100_1162.jpg>>

CDM
Frank Robinson
100 Crossways Park West
Woodbury, NY 11797
Phone: 516-496-8400
FAX: 516-496-8864
robinsonf@cdm.com

Project: Spectrum Finishing - Remedial Action
 Contractor: EnviroTrac Environmental Services
 CDM Job No: D-006956 Site No. 1-52-029
 CDM Project Manager: John Blaum

CDM
 100 Crossways Park West
 Woodbury, NY 11797
 Telephone: 516.496.8400
 Fax: 516.496.8864

DAILY REPORT

Day:

S	M	T	W	TH	F	S
---	---	---	---	----	---	---

 Date: 19-Aug-09
 REPORT No. 185
 PAGE No. 1

WEATHER	Clear	Partly Cloudy	Overcast	Rain	Snow
TEMP L/H		74/89			
HUMIDITY	Dry	Moderate	High		
WIND	Calm	Light	Moderate	High	
WIND DIR	N	E	S	W	
	NE	SE	SW	NW	

PREPARED BY: F.Robinson TITLE: Inspector

AVERAGE FIELD FORCE

Name of Contractor	Title	Hours Worked	Remarks

EQUIPMENT AT THE SITE I = Idle W = Working

HEALTH AND SAFETY

Name	Time (From - To)	Task/Level of PPE
All workers onsite were in level D-PPE		

CONSTRUCTION ACTIVITIES

Site Representative: Frank Robinson - CDM
Health and Safety Site Officer: N/A
DESCRIPTION OF WORK PERFORMED AND OBSERVED
1-No site work was performed today by EnviroTrac or any of their subcontractors.
2-Site inspection by F.Robinson: 1-- Field trailer and port-a-john still on site. 2- Area in front of 50 Dale St. still to be cleaned up, top soil added and seeded after trailer removed. 3- Front gates still have to adjusted by 51 and 61 Cabot St. 4- Grass seed to be added to the fronts of 60 Dale St. and 51 and 61 Cabot St. 5- 2 drums to be removed/disposed of from 50 Dale St.

x - Designates report is continued on additional pages

CDM Site Representative: F. Robinson

Project Manager: John Blaum

PHOTOGRAPHIC LOG

Date: 07/14/09

CDM Job No. D-006956

Spectrum Finishing Remedial Action

SITE No. 1-52-029

PHOTO	DATE	TIME	DESCRIPTION
100_1192.jpg	8/19/2009	PM	Missing water meter covers in front of 50/60 Dale St.
100_1193.jpg	8/19/2009	PM	Field trailer and port-a-john still on site.
100_1194.jpg	8/19/2009	PM	View of site looking east.
100_1195.jpg	8/19/2009	PM	2 drums to be removed/disposed of.
100_1196.jpg	8/19/2009	PM	Front of 61 Cabot St., grass to be re-seeded.

PHOTOS 8-19-09



100_1192.jpg - Missing water meter covers in front of 50/60 Dale St.



100_1193.jpg - Field trailer and port-a-john still on-site.



100_1194.jpg - View of site looking east.



100_1195.jpg - 2 drums still to be removed/disposed of.



100_1196.jpg - Front of 61 Cabot St., grass to be re-seeded.