



LEGEND

- DESTROYED MONITORING WELLS
- INTERIOR MONITORING WELL (INSIDE THE BUILDING)
- DEEP/SHALLOW MONITORING WELL CLUSTER
- SHALLOW MONITORING WELL
- INTERIOR SUMP
- FENCE LINE
- APPROXIMATE LOCATION OF DRAIN SPOUT
- APPROXIMATE VICINITY OF PREVIOUS EXCAVATED & STOCKPILED SOILS
- RIGHT OF WAY
- SEWER MANHOLE (APPROX 12' DEEP)
- UNDERGROUND STORM SEWER
- AMTRAK SHALLOW MONITORING WELL
- 1,2-DCE 1,2-DICHLOROETHENE
- TCE TRICHLOROETHENE
- PCE TETRACHLOROETHENE
- NS NOT SAMPLED
- J DETECTED BELOW DETECTION LIMIT
- U UNDETECTED

| | | | |
|---------------------------------|--|---|--------|
| DRAFTED BY: W.G.S. (N.J.) | | OFF-SITE GROUNDWATER MAP AMTRAK SUNNYSIDE YARD | |
| CHECKED BY: | | REMEDIAL INVESTIGATION REPORT | |
| REVIEWED BY: | | REMEDIAL INVESTIGATION/FEASIBILITY STUDY STANDARD MOTOR PRODUCTS LONG ISLAND CITY, NEW YORK | |
| NORTH | | Groundwater & Environmental Services, Inc. 1340 CAMPUS PARKWAY, NEPTUNE, NJ 07753 | |
| SCALE IN FEET 0 80 | | DATE | FIGURE |
| | | 1-21-04 | D-1 |





LOCATION OF SITE

Title:

1890 TOPOGRAPHIC MAP

Prepared For:
SUNNYSIDE YARD, QUEENS, NEW YORK



Copyrighted by
JULIUS BIEN & Co. 1890

| | | | |
|--|---------------------|-------------------|--------------|
| ROUX ROUX ASSOCIATES INC <i>Environmental Consulting & Management</i> | Compiled by: H.G. | Date: 12/94 | FIGURE 17 |
| | Prepared by: R.R. | Scale: 1" = 2000' | |
| | Project Mgr: J.D.D. | Revision: | |
| | Project: 05526/45 | | |